

2-21-2008

Structures in the Municipality of Denmark, 2008

Maine Department of Transportation

Follow this and additional works at: https://digitalmaine.com/mdot_docs

Recommended Citation

Maine Department of Transportation, "Structures in the Municipality of Denmark, 2008" (2008).
Transportation Documents. 2587.
https://digitalmaine.com/mdot_docs/2587

This Text is brought to you for free and open access by the Transportation at Digital Maine. It has been accepted for inclusion in Transportation Documents by an authorized administrator of Digital Maine. For more information, please contact statedocs@maine.gov.

Structures in the Municipality of Denmark

CONDITION RATINGS

TOWN1: Denmark	TOWN2: No town 2	SUBSTRUCTURE CONDITION: N Not Applicable
BRIDGE NO.: 5411	BRIDGE REGION: Southern	SUPERSTRUCTURE CONDITION: N Not Applicable
LOCATION: .2 MI E TOWNLINE	YEAR BUILT: 1941	DECK CONDITION: N Not Applicable
BRDGNAME: BUCK MEADOW	SPAN MATERIAL: 2 Concrete	CHANNEL CONDITION: 6 Satisfactory
OWNER: 1 State DOT	SPAN TYPE: 4 Culvert	CULVERT CONDITION: 7 Good
MAINTAINER: 1 State DOT	NUMBER OF MAIN SPANS: 1	APPROACH CONDITION: 7 Good
FEATURE ON: 160	STRUCTURE LENGTH IN FEET: 13	DATE OF INSPECTION: 9/19/2012
FEATURE UNDER: BUCK MEADOW	POSTING STATUS: 1 Open	FEDERAL SUFFICIENCY RATING: 90.4
ROAD INV NO: 000000160X	POSTING TYPE: 0 None needed	
ROUTE NO: 00160		
ROAD WIDTH: 0 FEET	FEDERAL BRIDGE INDICATOR: N	
CLASS: MINOR SPAN ON STATE AID ROAD		

Structures in the Municipality of Denmark

CONDITION RATINGS

TOWN1: Denmark	TOWN2: No town 2	SUBSTRUCTURE CONDITION: 8 Very Good
BRIDGE NO.: 5410	BRIDGE REGION: Southern	SUPERSTRUCTURE CONDITION: 6 Satisfactory
LOCATION: 0.3 MI W OF JCT RTE 117	YEAR BUILT: 1912	DECK CONDITION: 6 Satisfactory
BRDGNAME: BRACKETT MILL	SPAN MATERIAL: 2 Concrete	CHANNEL CONDITION: 6 Satisfactory
OWNER: 1 State DOT	SPAN TYPE: 6 Arch	CULVERT CONDITION: N Not Applicable
MAINTAINER: 1 State DOT	NUMBER OF MAIN SPANS: 1	APPROACH CONDITION: 6 Satisfactory
FEATURE ON: ROUTE 160	STRUCTURE LENGTH IN FEET: 36	DATE OF INSPECTION: 5/14/2012
FEATURE UNDER: MOOSE POND OUTLET	POSTING STATUS: 1 Open	FEDERAL SUFFICIENCY RATING: 79
ROAD INV NO: 000000160X	POSTING TYPE: 0 None needed	
ROUTE NO: 00160		
ROAD WIDTH: 23 FEET	FEDERAL BRIDGE INDICATOR: Y	
CLASS: BRIDGE ON TOWN WAY OR STATE AID ROAD		

Structures in the Municipality of Denmark

CONDITION RATINGS

TOWN1: Denmark	TOWN2: No town 2	SUBSTRUCTURE CONDITION: 7 Good
BRIDGE NO.: 0736	BRIDGE REGION: Southern	SUPERSTRUCTURE CONDITION: 8 Very Good
LOCATION: 3.6 MI S JCT RTE US 302	YEAR BUILT: 2002	DECK CONDITION: 8 Very Good
BRDGNAME: WALKER	SPAN MATERIAL: 7 Precast Concrete	CHANNEL CONDITION: 7 Good
OWNER: 1 State DOT	SPAN TYPE: 6 Arch	CULVERT CONDITION: N Not Applicable
MAINTAINER: 1 State DOT	NUMBER OF MAIN SPANS: 1	APPROACH CONDITION: 8 Very Good
FEATURE ON: MOUNTAIN ROAD	STRUCTURE LENGTH IN FEET: 28	DATE OF INSPECTION: 5/14/2012
FEATURE UNDER: MOOSE POND	POSTING STATUS: 1 Open	FEDERAL SUFFICIENCY RATING: 82.6
ROAD INV NO: 0001700805	POSTING TYPE: 0 None needed	
ROUTE NO: 00000		
ROAD WIDTH: 22 FEET	FEDERAL BRIDGE INDICATOR: Y	
CLASS: BRIDGE ON TOWN WAY OR STATE AID ROAD		

Structures in the Municipality of Denmark

CONDITION RATINGS

TOWN1: Denmark	TOWN2: No town 2	SUBSTRUCTURE CONDITION: N Not Applicable
BRIDGE NO.: 0716	BRIDGE REGION: Southern	SUPERSTRUCTURE CONDITION: N Not Applicable
LOCATION: 0.8 MI S RT 302	YEAR BUILT: 2008	DECK CONDITION: N Not Applicable
BRDGNAME: WARREN BROOK	SPAN MATERIAL: 5 Aluminum	CHANNEL CONDITION: 8 Very Good
OWNER: 4 Municipal	SPAN TYPE: 4 Culvert	CULVERT CONDITION: 9 Excellent
MAINTAINER: 4 Municipal	NUMBER OF MAIN SPANS: 1	APPROACH CONDITION: 5 Fair
FEATURE ON: WILTON-WARREN RD	STRUCTURE LENGTH IN FEET: 9	DATE OF INSPECTION: 6/14/2011
FEATURE UNDER: WARREN BROOK	POSTING STATUS: 1 Open	FEDERAL SUFFICIENCY RATING: 99
ROAD INV NO: 0001700693	POSTING TYPE: 0 None needed	
ROUTE NO: 00000		
ROAD WIDTH: 0 FEET	FEDERAL BRIDGE INDICATOR: N	
CLASS: MINOR SPAN ON TOWN WAY		