Maine State Library

Digital Maine

Transportation Documents

Transportation

2-21-2008

Structures in the Municipality of Dixfield, 2008

Maine Department of Transportation

Follow this and additional works at: https://digitalmaine.com/mdot_docs

Recommended Citation

Maine Department of Transportation, "Structures in the Municipality of Dixfield, 2008" (2008). *Transportation Documents*. 2594.

https://digitalmaine.com/mdot_docs/2594

This Text is brought to you for free and open access by the Transportation at Digital Maine. It has been accepted for inclusion in Transportation Documents by an authorized administrator of Digital Maine. For more information, please contact statedocs@maine.gov.

				CONDITION RATINGS				
TOWN1:	Dixfield	TOWN2	No town 2	SUBSTRUCTURE CONDITION	7	Good		
BRIDGE NO.	: 5255	BRIDGE REGION:	Western	SUPERSTRUCTURE CONDITION	6	Satisfactory		
LOCATION:	0.1 MI S OF JCT RTE 17	YEAR BUILT	1949	DECK CONDITION	3	Serious		
BRDGNAME	: WHEEL WRIGHT	SPAN MATERIAL	1 Steel	CHANNEL CONDITION:	6	Satisfactory		
OWNER:	1 State DOT	SPAN TYPE:	2 Girder - floor beam	CULVERT CONDITION:	N	Not Applicable		
MAINTAINE	R 1 State DOT	NUMBER OF MAIN	SPANS: 1	APPROACH CONDITION:	5	Fair		
FEATURE O	N: SEVERY HILL ROAD	STRUCTURE LENGT	TH IN FEET 74	DATE OF INSPECTION:	10/1	6/2012		
FEATURE U	NDER SEVEN MILE STREAM	POSTING STATUS:	1 Open	FEDERAL SUFFICIENCY RATING	72.7			
ROAD INV N	IO: 0001700385	POSTING TYPE:	0 None needed					
ROUTE NO:	00000 14 FEET	FEDERAL BRIDGE INDICATOR:	Y					
CLASS:	BRIDGE ON TOWN WAY OR STATE AID ROAD							

				CONDITION RATINGS				
TOWN1: Dixfield	TOWN2	No town 2	SUBSTRUCTURE CONDITION	7	Good			
BRIDGE NO.: 5181	BRIDGE REGION:	Western	SUPERSTRUCTURE CONDITION	6	Satisfactory			
LOCATION: 2 MI N US 2	YEAR BUILT	1951	DECK CONDITION	6	Satisfactory			
BRDGNAME: AUNT HANNAH	SPAN MATERIAL	2 Concrete	CHANNEL CONDITION:	6	Satisfactory			
OWNER: 1 State DOT	SPAN TYPE:	3 Slab	CULVERT CONDITION:	N	Not Applicable			
MAINTAINER 1 State DOT	NUMBER OF MAIN	SPANS: 1	APPROACH CONDITION:	5	Fair			
FEATURE ON: #142	STRUCTURE LENGT	TH IN FEET 22	DATE OF INSPECTION:	9/1	12/2012			
FEATURE UNDER AUNT HANNAH BRK	POSTING STATUS:	1 Open	FEDERAL SUFFICIENCY RATING	71.8				
ROAD INV NO: 000000142X	POSTING TYPE:	0 None needed						
ROUTE NO: 00142	FEDERAL BRIDGE							
ROAD WIDTH 26 FEET	INDICATOR:	N						
CLASS: MINOR SPAN ON STATE AID ROAD								

			CONDITION RATINGS				
TOWN1: Dixfield	TOWN2	No town 2	SUBSTRUCTURE CONDITION	6	Satisfactory		
BRIDGE NO.: 3732	BRIDGE REGION:	Western	SUPERSTRUCTURE CONDITION	7	Good		
LOCATION: 0.1 MI S RTE 2	YEAR BUILT	1940	DECK CONDITION	7	Good		
BRDGNAME: EAST DIXFIELD	SPAN MATERIAL	3 Wood	CHANNEL CONDITION:	7	Good		
OWNER: 4 Municipal	SPAN TYPE:	1 Girder	CULVERT CONDITION:	N	Not Applicable		
MAINTAINER 4 Municipal	NUMBER OF MAIN	SPANS: 1	APPROACH CONDITION:	6	Satisfactory		
FEATURE ON: CHURCH STREET	STRUCTURE LENGT	TH IN FEET 50	DATE OF INSPECTION:	9/	14/2011		
FEATURE UNDER SEVEN MILE STREAM	POSTING STATUS:	1 Open	FEDERAL SUFFICIENCY RATING	77.6			
ROAD INV NO: 0001700383	POSTING TYPE:	0 None needed					
ROUTE NO: 000000	FEDERAL BRIDGE						
ROAD WIDTH 13 FEET	INDICATOR:	Y					
CLASS: LOW USE/REDUNDANT BRIDGE							

				CONDITION RATI	NGS	
TOWN1: Dixfield	TOW	N2	No town 2	SUBSTRUCTURE CONDITION	N	Not Applicable
BRIDGE NO.: 3386	BRID	GE REGION:	Vestern	SUPERSTRUCTURE CONDITION	N	Not Applicable
LOCATION: 0.2 MI E RT2	YEAI	R BUILT	973	DECK CONDITION	N	Not Applicable
BRDGNAME: NEWTON E	SPAN	MATERIAL 1	Steel	CHANNEL CONDITION:	4	Poor
OWNER: 4 Municipal	SPAN	TYPE: 4	Culvert	CULVERT CONDITION:	4	Poor
MAINTAINER 4 Municipal	NUM	BER OF MAIN SPA	ANS: 1	APPROACH CONDITION:	4	Poor
FEATURE ON: PORTER R	STRU	CTURE LENGTH	IN FEET 16	DATE OF INSPECTION:	9/14	4/2011
FEATURE UNDER NEW!	POST:	ING STATUS:	1 Open	FEDERAL SUFFICIENCY RATING	64.3	
ROAD INV NO: 000170105	5 POST	ING TYPE:	0 None needed			
ROUTE NO: 000000	EDDE	RAL BRIDGE				
ROAD WIDTH	0 FEET INDIC		N			
CLASS: MINOR SPAN O	DN					

				CONDITION RATINGS				
TOWN1: Dixfie	eld	TOWN2	No town 2	SUBSTRUCTURE CONDITION	7	Good		
BRIDGE NO.: 3	3243	BRIDGE REGION:	Western	SUPERSTRUCTURE CONDITION	6	Satisfactory		
LOCATION: 0.6	6 MI E OF JCT RTE 2	YEAR BUILT	1935	DECK CONDITION	6	Satisfactory		
BRDGNAME: N	EWTON BROOK	SPAN MATERIAL	2 Concrete	CHANNEL CONDITION:	7	Good		
OWNER: 1 Stat	te DOT	SPAN TYPE:	3 Slab	CULVERT CONDITION:	N	Not Applicable		
MAINTAINER 1	1 State DOT	NUMBER OF MAIN S	SPANS: 1	APPROACH CONDITION:	6	Satisfactory		
FEATURE ON:	CANTON POINT ROAD	STRUCTURE LENGT	H IN FEET 23	DATE OF INSPECTION:	4/	3/2012		
FEATURE UNDE	R NEWTON BROOK	POSTING STATUS:	1 Open	FEDERAL SUFFICIENCY RATING	74.8			
ROAD INV NO:	0001700396	POSTING TYPE:	0 None needed					
ROUTE NO: 000	0000	EEDEDAL BRIDGE						
ROAD WIDTH		FEDERAL BRIDGE INDICATOR:	Y					
CLILDO.	OGE ON TOWN Y OR STATE AID D							

				CONDITION RATI	NGS	
TOWN1:	Dixfield	TOWN2	No town 2	SUBSTRUCTURE CONDITION	N	Not Applicable
BRIDGE NO.	: 3242	BRIDGE REGION:	Western	SUPERSTRUCTURE CONDITION	N	Not Applicable
LOCATION:	2.3 MI WEST TOWN LINE	YEAR BUILT	1997	DECK CONDITION	N	Not Applicable
BRDGNAME	: REED	SPAN MATERIAL	1 Steel	CHANNEL CONDITION:	4	Poor
OWNER:	1 State DOT	SPAN TYPE:	4 Culvert	CULVERT CONDITION:	7	Good
MAINTAINE	CR 1 State DOT	NUMBER OF MAIN	SPANS: 1	APPROACH CONDITION:	7	Good
FEATURE O	N: SA4 CANTON POINT R	STRUCTURE LENGT	TH IN FEET 17	DATE OF INSPECTION:	10/	(6/2011
FEATURE U	NDER HARVEY BROOK	POSTING STATUS:	1 Open	FEDERAL SUFFICIENCY RATING	100	
ROAD INV N	IO: 0001700396	POSTING TYPE:	0 None needed			
ROUTE NO:	00000	FEDERAL BRIDGE				
ROAD WIDT	TH 0 FEET	INDICATOR:	N			
CLILDO.	MINOR SPAN ON STATE AID ROAD					

			CONDITION RATI	NGS	
TOWN1: Dixfield	TOWN2	No town 2	SUBSTRUCTURE CONDITION	N	Not Applicable
BRIDGE NO.: 2870	BRIDGE REGION:	Western	SUPERSTRUCTURE CONDITION	N	Not Applicable
LOCATION: 1.3 MI W OF JCT US2 & 17	YEAR BUILT	1991	DECK CONDITION	N	Not Applicable
BRDGNAME: TOM STONE	SPAN MATERIAL	2 Concrete	CHANNEL CONDITION:	7	Good
OWNER: 1 State DOT	SPAN TYPE:	4 Culvert	CULVERT CONDITION:	7	Good
MAINTAINER 1 State DOT	NUMBER OF MAIN	SPANS: 1	APPROACH CONDITION:	7	Good
FEATURE ON: ROUTE US 2 & 17	STRUCTURE LENGT	TH IN FEET 40	DATE OF INSPECTION:	9/2	1/2011
FEATURE UNDER SEVEN MILE STREAM	POSTING STATUS:	1 Open	FEDERAL SUFFICIENCY RATING	96.7	
ROAD INV NO: 000000002X	POSTING TYPE:	0 None needed			
ROUTE NO: 00002	FEDERAL BRIDGE				
ROAD WIDTH 0 FEET	INDICATOR:	Y			
CLASS: BRIDGE ON STATE HIGHWAY					

			CONDITION RATI	NGS	
TOWN1: Dixfield	TOWN2	No town 2	SUBSTRUCTURE CONDITION	N	Not Applicable
BRIDGE NO.: 2350	BRIDGE REGION:	Western	SUPERSTRUCTURE CONDITION	N	Not Applicable
LOCATION: 4.0 MI E JCT OF RTE 142	YEAR BUILT	2008	DECK CONDITION	N	Not Applicable
BRDGNAME: HANNAFORD	SPAN MATERIAL	1 Steel	CHANNEL CONDITION:	8	Very Good
OWNER: 1 State DOT	SPAN TYPE:	4 Culvert	CULVERT CONDITION:	8	Very Good
MAINTAINER 1 State DOT	NUMBER OF MAIN	SPANS: 1	APPROACH CONDITION:	8	Very Good
FEATURE ON: ROUTES US2 & 17	STRUCTURE LENGT	TH IN FEET 29	DATE OF INSPECTION:	4.	/3/2012
FEATURE UNDER NEWTON BROOK	POSTING STATUS:	1 Open	FEDERAL SUFFICIENCY RATING	96.6	
ROAD INV NO: 000000002X	POSTING TYPE:	0 None needed			
ROUTE NO: 00002	FEDERAL BRIDGE				
ROAD WIDTH 0 FEET	INDICATOR:	Y			
CLASS: BRIDGE ON STATE HIGHWAY					

			CONDITION RATI	INGS	
TOWN1: Dixfield	TOWN2	No town 2	SUBSTRUCTURE CONDITION	N	Not Applicable
BRIDGE NO.: 0658	BRIDGE REGION:	Western	SUPERSTRUCTURE CONDITION	N	Not Applicable
LOCATION: 200 FT W OF JCT US 2	YEAR BUILT	1970	DECK CONDITION	N	Not Applicable
BRDGNAME: DURRELLS MILL	SPAN MATERIAL	1 Steel	CHANNEL CONDITION:	4	Poor
OWNER: 1 State DOT	SPAN TYPE:	4 Culvert	CULVERT CONDITION:	4	Poor
MAINTAINER 1 State DOT	NUMBER OF MAIN S	SPANS: 3	APPROACH CONDITION:	5	Fair
FEATURE ON: NORTON ROAD	STRUCTURE LENGT	H IN FEET 20	DATE OF INSPECTION:	4	1/3/2012
FEATURE UNDER NEWTON BROOK	POSTING STATUS:	1 Open	FEDERAL SUFFICIENCY RATING	64	
ROAD INV NO: 0001700391	POSTING TYPE:	0 None needed			
ROUTE NO: 00000	FEDERAL BRIDGE				
ROAD WIDTH 0 FEET		Y			
CLASS: LOW USE/REDUNDANT BRIDGE					

		C			
TOWN1: Dixfield	TOWN2	No town 2	SUBSTRUCTURE CONDITION	4	Poor
BRIDGE NO.: 0656	BRIDGE REGION:	Western	SUPERSTRUCTURE CONDITION	4	Poor
LOCATION: 0.1 MI NW CANTON TL	YEAR BUILT	1950	DECK CONDITION	5	Fair
BRDGNAME: BIG RUSSELL	SPAN MATERIAL	3 Wood	CHANNEL CONDITION:	5	Fair
OWNER: 7 Private	SPAN TYPE:	1 Girder	CULVERT CONDITION:	N	Not Applicable
MAINTAINER 7 Private	NUMBER OF MAIN S	SPANS: 1	APPROACH CONDITION:		
FEATURE ON: PRIVATE WAY	STRUCTURE LENGT	TH IN FEET 30	DATE OF INSPECTION:	8/	/9/1984
FEATURE UNDER LUDDEN BROOK	POSTING STATUS:	1 Open	FEDERAL SUFFICIENCY RATING	27	
ROAD INV NO: -1	POSTING TYPE:				
ROUTE NO: 0					
ROAD WIDTH 11 FEE	FEDERAL BRIDGE T INDICATOR:	N			
CLASS:					

			CONDITION RATI	INGS	
TOWN1: Dixfield	TOWN2	No town 2	SUBSTRUCTURE CONDITION	N	Not Applicable
BRIDGE NO.: 0003	BRIDGE REGION:	Western	SUPERSTRUCTURE CONDITION	N	Not Applicable
LOCATION: 0.75 MI S RT 17	YEAR BUILT	1982	DECK CONDITION	N	Not Applicable
BRDGNAME: TUCKER BROOK	SPAN MATERIAL	1 Steel	CHANNEL CONDITION:	4	Poor
OWNER: 4 Municipal	SPAN TYPE:	4 Culvert	CULVERT CONDITION:	5	Fair
MAINTAINER 4 Municipal	NUMBER OF MAIN	SPANS: 1	APPROACH CONDITION:	5	Fair
FEATURE ON: VALLEY BROOK RD	STRUCTURE LENGT	TH IN FEET 12	DATE OF INSPECTION:	9/1	14/2011
FEATURE UNDER TUCKER BROOK	POSTING STATUS:	1 Open	FEDERAL SUFFICIENCY RATING	89	
ROAD INV NO: 0001702730	POSTING TYPE:	0 None needed			
ROUTE NO: 00000	FEDERAL BRIDGE				
ROAD WIDTH 0 FEET	INDICATOR:	N			
CLASS: MINOR SPAN ON TOWN WAY					

Tuesday, July 23, 2013

Structures in the Municipality of Mexico

				CONDITION RATINGS				
TOWN1: Mexico	TOWN2	Dixfield	SUBSTRUCTURE CONDITION	7	Good			
BRIDGE NO.: 3326	BRIDGE REGION:	Western	SUPERSTRUCTURE CONDITION	8	Very Good			
LOCATION: 0.4 MI W RT 142	YEAR BUILT	2008	DECK CONDITION	9	Excellent			
BRDGNAME: THAD WHITE BRIDGE	SPAN MATERIAL	1 Steel	CHANNEL CONDITION:	7	Good			
OWNER: 4 Municipal	SPAN TYPE:	5 Truss	CULVERT CONDITION:	N	Not Applicable			
MAINTAINER 4 Municipal	NUMBER OF MAIN	SPANS: 1	APPROACH CONDITION:	5	Fair			
FEATURE ON: COBURN AVE	STRUCTURE LENGT	CH IN FEET 95	DATE OF INSPECTION:	10/17	7/2011			
FEATURE UNDER WEBB RIVER	POSTING STATUS:	1 Open	FEDERAL SUFFICIENCY RATING	73.9				
ROAD INV NO: 0001701524	POSTING TYPE:	0 None needed						
ROUTE NO: 000000	FEDERAL BRIDGE							
ROAD WIDTH 14 FEET	INDICATOR:	Y						
CLASS: LOW USE/REDUNDANT BRIDGE								

Structures in the Municipality of Mexico

			CONDITION RATINGS		
TOWN1: Mexico	TOWN2	Dixfield	SUBSTRUCTURE CONDITION	8	Very Good
BRIDGE NO.: 2917	BRIDGE REGION:	Western	SUPERSTRUCTURE CONDITION	9	Excellent
LOCATION: DIXFIELD-MEXICO TOWNLIN	YEAR BUILT	2012	DECK CONDITION	9	Excellent
BRDGNAME: WEBB RIVER	SPAN MATERIAL	1 Steel	CHANNEL CONDITION:	8	Very Good
OWNER: 1 State DOT	SPAN TYPE:	1 Girder	CULVERT CONDITION:	N	Not Applicable
MAINTAINER 1 State DOT	INTAINER 1 State DOT NUMBER OF MAIN SPANS: 1		APPROACH CONDITION:	9	Excellent
FEATURE ON: #2	STRUCTURE LENGTH IN FEET 120		DATE OF INSPECTION:	2/5/2013	
FEATURE UNDER WEBB RIVER	POSTING STATUS: 1 Open		FEDERAL SUFFICIENCY RATING	66.9	
ROAD INV NO: 000000002X	POSTING TYPE:	0 None needed			
ROUTE NO: 00002	FEDERAL BRIDGE				
ROAD WIDTH 26 FEET	INDICATOR:	Y			
CLASS: BRIDGE ON STATE HIGHWAY					

Page 13 of 13