

2-21-2008

Structures in the Municipality of Madrid, 2008

Maine Department of Transportation

Follow this and additional works at: https://digitalmaine.com/mdot_docs

Recommended Citation

Maine Department of Transportation, "Structures in the Municipality of Madrid, 2008" (2008).
Transportation Documents. 2741.
https://digitalmaine.com/mdot_docs/2741

This Text is brought to you for free and open access by the Transportation at Digital Maine. It has been accepted for inclusion in Transportation Documents by an authorized administrator of Digital Maine. For more information, please contact statedocs@maine.gov.

Structures in the Municipality of Madrid

CONDITION RATINGS

TOWN1: Madrid	TOWN2: No town 2	SUBSTRUCTURE CONDITION: 6 Satisfactory
BRIDGE NO.: 5929	BRIDGE REGION: Western	SUPERSTRUCTURE CONDITION: 6 Satisfactory
LOCATION: 4.8 MI NE OF JCT RTE 4	YEAR BUILT: 1964	DECK CONDITION: 6 Satisfactory
BRDGNAME: REEDS MILL	SPAN MATERIAL: 1 Steel	CHANNEL CONDITION: 6 Satisfactory
OWNER: 4 Municipal	SPAN TYPE: 1 Girder	CULVERT CONDITION: N Not Applicable
MAINTAINER: 4 Municipal	NUMBER OF MAIN SPANS: 1	APPROACH CONDITION: 7 Good
FEATURE ON: REEDS MILL ROAD	STRUCTURE LENGTH IN FEET: 57	DATE OF INSPECTION: 8/14/2012
FEATURE UNDER: ORBETON STREAM	POSTING STATUS: 1 Open	FEDERAL SUFFICIENCY RATING: 90.7
ROAD INV NO: 0000700327	POSTING TYPE: 0 None needed	
ROUTE NO: 00000		
ROAD WIDTH: 26 FEET	FEDERAL BRIDGE INDICATOR: Y	
CLASS: LOW USE/REDUNDANT BRIDGE		

Structures in the Municipality of Madrid

CONDITION RATINGS

TOWN1: Madrid	TOWN2: No town 2	SUBSTRUCTURE CONDITION: 7 Good
BRIDGE NO.: 3391	BRIDGE REGION: Western	SUPERSTRUCTURE CONDITION: 6 Satisfactory
LOCATION: 3.1 MI NE OF JCT RTE 4	YEAR BUILT: 1953	DECK CONDITION: 6 Satisfactory
BRDGNAME: WEBBER	SPAN MATERIAL: 2 Concrete	CHANNEL CONDITION: 4 Poor
OWNER: 1 State DOT	SPAN TYPE: 3 Slab	CULVERT CONDITION: N Not Applicable
MAINTAINER: 1 State DOT	NUMBER OF MAIN SPANS: 1	APPROACH CONDITION: 5 Fair
FEATURE ON: REEDS MILL ROAD	STRUCTURE LENGTH IN FEET: 34	DATE OF INSPECTION: 4/17/2012
FEATURE UNDER: WHINSHIP (CONANT) ST	POSTING STATUS: 1 Open	FEDERAL SUFFICIENCY RATING: 70.6
ROAD INV NO: 0000700327	POSTING TYPE: 0 None needed	
ROUTE NO: 00000		
ROAD WIDTH: 14 FEET	FEDERAL BRIDGE INDICATOR: Y	
CLASS: BRIDGE ON TOWN WAY OR STATE AID ROAD		

Structures in the Municipality of Madrid

CONDITION RATINGS

TOWN1: Madrid	TOWN2: No town 2	SUBSTRUCTURE CONDITION: 5 Fair
BRIDGE NO.: 3186	BRIDGE REGION: Western	SUPERSTRUCTURE CONDITION: 5 Fair
LOCATION: 50 FT N JCT RTE 4	YEAR BUILT: 1935	DECK CONDITION: 5 Fair
BRDGNAME: VILLAGE	SPAN MATERIAL: 1 Steel	CHANNEL CONDITION: 7 Good
OWNER: 1 State DOT	SPAN TYPE: 1 Girder	CULVERT CONDITION: N Not Applicable
MAINTAINER: 1 State DOT	NUMBER OF MAIN SPANS: 1	APPROACH CONDITION: 4 Poor
FEATURE ON: REEDS MILL ROAD	STRUCTURE LENGTH IN FEET: 66	DATE OF INSPECTION: 4/17/2012
FEATURE UNDER: SANDY RIVER	POSTING STATUS: 1 Open	FEDERAL SUFFICIENCY RATING: 57.3
ROAD INV NO: 0000700546	POSTING TYPE: 0 None needed	
ROUTE NO: 00000		
ROAD WIDTH: 12 FEET	FEDERAL BRIDGE INDICATOR: Y	
CLASS: BRIDGE ON TOWN WAY OR STATE AID ROAD		

Structures in the Municipality of Madrid

CONDITION RATINGS

TOWN1: Madrid	TOWN2: No town 2	SUBSTRUCTURE CONDITION: 4 Poor
BRIDGE NO.: 2934	BRIDGE REGION: Western	SUPERSTRUCTURE CONDITION: 6 Satisfactory
LOCATION: 1.7 MI W OF PHILLIPS TL	YEAR BUILT: 1933	DECK CONDITION: 5 Fair
BRDGNAME: WEYMOUTH	SPAN MATERIAL: 2 Concrete	CHANNEL CONDITION: 6 Satisfactory
OWNER: 1 State DOT	SPAN TYPE: 1 Girder	CULVERT CONDITION: N Not Applicable
MAINTAINER: 1 State DOT	NUMBER OF MAIN SPANS: 1	APPROACH CONDITION: 7 Good
FEATURE ON: ROUTE 4	STRUCTURE LENGTH IN FEET: 49	DATE OF INSPECTION: 9/10/2012
FEATURE UNDER: SANDY RIVER	POSTING STATUS: 1 Open	FEDERAL SUFFICIENCY RATING: 17.1
ROAD INV NO: 000000004X	POSTING TYPE: 0 None needed	
ROUTE NO: 00004		
ROAD WIDTH: 22 FEET	FEDERAL BRIDGE INDICATOR: Y	
CLASS: BRIDGE ON STATE HIGHWAY		

Structures in the Municipality of Madrid

CONDITION RATINGS

TOWN1: Madrid	TOWN2: No town 2	SUBSTRUCTURE CONDITION: 5 Fair
BRIDGE NO.: 0422	BRIDGE REGION: Western	SUPERSTRUCTURE CONDITION: 7 Good
LOCATION: 0.9 NW RT 4	YEAR BUILT: 1979	DECK CONDITION: 5 Fair
BRDGNAME: HINCKLEY	SPAN MATERIAL: 1 Steel	CHANNEL CONDITION: 7 Good
OWNER: 4 Municipal	SPAN TYPE: 1 Girder	CULVERT CONDITION: N Not Applicable
MAINTAINER: 4 Municipal	NUMBER OF MAIN SPANS: 1	APPROACH CONDITION: 4 Poor
FEATURE ON: BEECH RIDGE RD.	STRUCTURE LENGTH IN FEET: 40	DATE OF INSPECTION: 8/4/2011
FEATURE UNDER: SADDLEBACK STREAM	POSTING STATUS: 3 Posted	FEDERAL SUFFICIENCY RATING: 18.7
ROAD INV NO: 0000700575	POSTING TYPE: 1 Weight Limit	
ROUTE NO: 00000		
ROAD WIDTH: 12 FEET	FEDERAL BRIDGE INDICATOR: Y	
CLASS: LOW USE/REDUNDANT BRIDGE		

Structures in the Municipality of Madrid

CONDITION RATINGS

TOWN1: Madrid	TOWN2: No town 2	SUBSTRUCTURE CONDITION: 7 Good
BRIDGE NO.: 0383	BRIDGE REGION: Western	SUPERSTRUCTURE CONDITION: 7 Good
LOCATION: 4 MI NW RTE 142	YEAR BUILT: 1996	DECK CONDITION: 6 Satisfactory
BRDGNAME: EAST MADRID	SPAN MATERIAL: 1 Steel	CHANNEL CONDITION: 8 Very Good
OWNER: 4 Municipal	SPAN TYPE: 1 Girder	CULVERT CONDITION: N Not Applicable
MAINTAINER: 4 Municipal	NUMBER OF MAIN SPANS: 1	APPROACH CONDITION: 5 Fair
FEATURE ON: EAST MADRID ROAD	STRUCTURE LENGTH IN FEET: 72	DATE OF INSPECTION: 8/3/2011
FEATURE UNDER: PERHAM STREAM	POSTING STATUS: 1 Open	FEDERAL SUFFICIENCY RATING: 76.3
ROAD INV NO: 0000700323	POSTING TYPE: 0 None needed	
ROUTE NO: 00000		
ROAD WIDTH: 14 FEET	FEDERAL BRIDGE INDICATOR: Y	
CLASS: LOW USE/REDUNDANT BRIDGE		