

11-2-1995

Piscataquis River Bridge, Howland : Bridge Scour Evaluation, November 2, 1995 [PAGE 2]

Maine Department of Transportation

Follow this and additional works at: https://digitalmaine.com/mdot_docs

Recommended Citation

Maine Department of Transportation, "Piscataquis River Bridge, Howland : Bridge Scour Evaluation, November 2, 1995 [PAGE 2]" (1995). *Transportation Documents*. 1950.
https://digitalmaine.com/mdot_docs/1950

This Text is brought to you for free and open access by the Transportation at Digital Maine. It has been accepted for inclusion in Transportation Documents by an authorized administrator of Digital Maine. For more information, please contact statedocs@maine.gov.

BRIDGE SCOUR EVALUATION

Recommended NBI Rating

Item 61: 8

Item 71: 8

Item 113 3C

BRIDGE DESCRIPTION

Bridge Description: Multi Span

Number of Spans: 3

Bridge Datum: Assumed

Bridge Datum Location Top of abut. bridge seat

Bridge Datum Elev 101.6

Date Built: 1928

Date of Widening/Major Repairs: None

Low Chord Elev (ft): 102.4

102.7

Bridge Deck Elev (ft): 107.0

- 107.3

Thalweg Elev (ft): 81.0

Overtopping Elev (ft): 97.6

Overtopping Location: Left Approach

MDOT Underwater Inspection

Frequency (months): 60

Debris: Low

Streambed:

Silt/Clay:

Bedrock:

Natural Armoring:

Cobbles/Boulder:

Gravel:

Sand:

Other:

Bed Material D50 (Visual Classification) Unknown