

10-18-1995

Piscataquis River Bridge, Howland : Underwater Inspection Report [accompanying sticky notes], October 18, 1995

Maine Department of Transportation

Follow this and additional works at: https://digitalmaine.com/mdot_docs

Recommended Citation

Maine Department of Transportation, "Piscataquis River Bridge, Howland : Underwater Inspection Report [accompanying sticky notes], October 18, 1995" (1995). *Transportation Documents*. 1960.
https://digitalmaine.com/mdot_docs/1960

This Text is brought to you for free and open access by the Transportation at Digital Maine. It has been accepted for inclusion in Transportation Documents by an authorized administrator of Digital Maine. For more information, please contact statedocs@maine.gov.

1995 U.W. (copy enclosed)
report shows
increased score.
Should be high
priority score
repair.

May

Recommend SC Co
repairs to pier. Looks
like there is also a
hole in front of the
abutment.
Group Review.

JM.