

1-9-1997

## Piscataquis River Bridge, Howland [Photographs 3], January 9, 1997

Maine Department of Transportation

Follow this and additional works at: [https://digitalmaine.com/mdot\\_docs](https://digitalmaine.com/mdot_docs)

---

### Recommended Citation

Maine Department of Transportation, "Piscataquis River Bridge, Howland [Photographs 3], January 9, 1997" (1997). *Transportation Documents*. 1850.  
[https://digitalmaine.com/mdot\\_docs/1850](https://digitalmaine.com/mdot_docs/1850)

This Text is brought to you for free and open access by the Transportation at Digital Maine. It has been accepted for inclusion in Transportation Documents by an authorized administrator of Digital Maine. For more information, please contact [statedocs@maine.gov](mailto:statedocs@maine.gov).



BK 3040

1-9-97

(CONT)



ABUTMENT 2 PORTAL COLLISION DAMAGE



TYP. PIER



BRIDGE RAIL PAINT FAILURE



ABUTMENT # 2