

2-21-2008

Structures in the Municipality of Auburn, 2008

Maine Department of Transportation

Follow this and additional works at: https://digitalmaine.com/mdot_docs

Recommended Citation

Maine Department of Transportation, "Structures in the Municipality of Auburn, 2008" (2008).
Transportation Documents. 2478.
https://digitalmaine.com/mdot_docs/2478

This Text is brought to you for free and open access by the Transportation at Digital Maine. It has been accepted for inclusion in Transportation Documents by an authorized administrator of Digital Maine. For more information, please contact statedocs@maine.gov.

Structures in the Municipality of Auburn

| | | | | CONDITION RATINGS | |
|----------------------|---------------------------|--------------------------------------|---------------|-----------------------------------|-----------------------|
| TOWN1: | Auburn | TOWN2 | No town 2 | SUBSTRUCTURE CONDITION | 1 Imminent Failure |
| BRIDGE NO.: | 0075 | MAINT REGION | Southern | SUPERSTRUCTURE CONDITION | 5 Fair |
| LOCATION: | 0.7 MI E OLD DANVILLE | YEAR BUILT | 1950 | DECK CONDITION | 7 Good |
| BRIDGE NAME | BROWN | SPAN MATERIAL | 1 Steel | CHANNEL CONDITION: | 4 Poor |
| OWNER: | 4 Municipal | SPAN TYPE: | 1 Girder | CULVERT CONDITION: | N Not Applicable |
| MAINTAINER | 4 Municipal | NUMBER OF MAIN SPANS: | 1 | APPROACH CONDITION: | 2 Critical |
| FEATURE ON: | BROWNS CROSSING RO | STRUCTURE LENGTH IN FEET | 28 | DATE OF INSPECTION: | 7/3/2001 |
| FEATURE UNDER | ROYAL RIVER | | | FEDERAL SUFFICIENCY RATING | 18.6 |
| ROAD INV NO: | 0000110051 | POSTING STATUS: | 2 Closed | | |
| ROUTE NO: | 00000 | POSTING TYPE: | 0 None needed | | |
| ROAD WIDTH | 22 | | | | |
| | FEET | | | | |
| CLASS: | MINOR SPAN ON TOWN WAY | FEDERAL BRIDGE INDICATOR: | N | | |

Structures in the Municipality of Auburn

| | | | | CONDITION RATINGS | |
|----------------------|-----------------------------|--------------------------------------|------------------------|-----------------------------------|------------------|
| TOWN1: | Auburn | TOWN2 | No town 2 | SUBSTRUCTURE CONDITION | 6 Satisfactory |
| BRIDGE NO.: | 0085 | MAINT REGION | Southern | SUPERSTRUCTURE CONDITION | 4 Poor |
| LOCATION: | 77.6 MILE POINT | YEAR BUILT | 1955 | DECK CONDITION | 4 Poor |
| BRIDGE NAME | SOUTH MAIN STREET/M | SPAN MATERIAL | 1 Steel | CHANNEL CONDITION: | N Not Applicable |
| OWNER: | 8 ME TPK | SPAN TYPE: | 1 Girder | CULVERT CONDITION: | N Not Applicable |
| MAINTAINER | 8 ME TPK | NUMBER OF MAIN SPANS: | 4 | APPROACH CONDITION: | |
| FEATURE ON: | SOUTH MAIN STREET | STRUCTURE LENGTH IN FEET | 220 | DATE OF INSPECTION: | 4/13/2006 |
| FEATURE UNDER | MTPK | | | FEDERAL SUFFICIENCY RATING | 49 |
| ROAD INV NO: | 0000110368 | POSTING STATUS: | 3 Posted | | |
| ROUTE NO: | 00000 | POSTING TYPE: | 3 Underclearance Limit | | |
| ROAD WIDTH | 24 FEET | | | | |
| CLASS: | MAINE TURNPIKE AUTHORITY | FEDERAL BRIDGE INDICATOR: | Y | | |

Structures in the Municipality of Auburn

| | | | | CONDITION RATINGS | |
|----------------------|-----------------------------|--------------------------------------|---------------|-----------------------------------|---------------------|
| TOWN1: | Auburn | TOWN2 | No town 2 | SUBSTRUCTURE CONDITION | 7 Good |
| BRIDGE NO.: | 0084 | MAINT REGION | Southern | SUPERSTRUCTURE CONDITION | 7 Good |
| LOCATION: | 76.9 MILE POINT | YEAR BUILT | 1955 | DECK CONDITION | 7 Good |
| BRIDGE NAME | HACKETT ROAD/MTPK | SPAN MATERIAL | 1 Steel | CHANNEL CONDITION: | N Not Applicable |
| OWNER: | 8 ME TPK | SPAN TYPE: | 1 Girder | CULVERT CONDITION: | N Not Applicable |
| MAINTAINER | 8 ME TPK | NUMBER OF MAIN SPANS: | 4 | APPROACH CONDITION: | |
| FEATURE ON: | HACKETT ROAD | STRUCTURE LENGTH IN FEET | 201 | DATE OF INSPECTION: | 4/13/2006 |
| FEATURE UNDER | MTPK | | | FEDERAL SUFFICIENCY RATING | 72.8 |
| ROAD INV NO: | 0000110163 | POSTING STATUS: | 1 Open | | |
| ROUTE NO: | 00000 | POSTING TYPE: | 0 None needed | | |
| ROAD WIDTH | 23 | | | | |
| | FEET | | | | |
| CLASS: | MAINE TURNPIKE AUTHORITY | FEDERAL BRIDGE INDICATOR: | Y | | |

Structures in the Municipality of Auburn

| | | | | CONDITION RATINGS | |
|----------------------|-----------------------------|--------------------------------------|------------------------|-----------------------------------|---------------------|
| TOWN1: | Auburn | TOWN2 | No town 2 | SUBSTRUCTURE CONDITION | 7 Good |
| BRIDGE NO.: | 0083 | MAINT REGION | Southern | SUPERSTRUCTURE CONDITION | 7 Good |
| LOCATION: | 75.80 MILE POINT | YEAR BUILT | 1955 | DECK CONDITION | 7 Good |
| BRIDGE NAME | DANVILLE CORNERS(BE | SPAN MATERIAL | 1 Steel | CHANNEL CONDITION: | N Not Applicable |
| OWNER: | 8 ME TPK | SPAN TYPE: | 1 Girder | CULVERT CONDITION: | N Not Applicable |
| MAINTAINER | 8 ME TPK | NUMBER OF MAIN SPANS: | 4 | APPROACH CONDITION: | |
| FEATURE ON: | DANVILLE CORNER RD | STRUCTURE LENGTH IN FEET | 207 | DATE OF INSPECTION: | 4/13/2006 |
| FEATURE UNDER | MTPK | | | FEDERAL SUFFICIENCY RATING | 75 |
| ROAD INV NO: | 0000110090 | POSTING STATUS: | 3 Posted | | |
| ROUTE NO: | 00000 | POSTING TYPE: | 3 Underclearance Limit | | |
| ROAD WIDTH | 25 | | | | |
| | FEET | | | | |
| CLASS: | MAINE TURNPIKE AUTHORITY | FEDERAL BRIDGE INDICATOR: | Y | | |

Structures in the Municipality of Auburn

| | | | | CONDITION RATINGS | |
|----------------------|--------------------------|-----------------------------------|---------------|---------------------------------|--|
| TOWN1: | Auburn | TOWN2 | No town 2 | SUBSTRUCTURE CONDITION | 7 Good |
| BRIDGE NO.: | 0082 | MAINT REGION | Southern | SUPERSTRUCTURE CONDITION | 5 Fair |
| LOCATION: | 75.60 MILE POINT | YEAR BUILT | 1955 | DECK CONDITION | 5 Fair |
| BRIDGE NAME | MTPK(NB)/RTE 202 & M | SPAN MATERIAL | 1 Steel | CHANNEL CONDITION: | N Not Applicable |
| OWNER: | 8 ME TPK | SPAN TYPE: | 1 Girder | CULVERT CONDITION: | N Not Applicable |
| MAINTAINER | 8 ME TPK | NUMBER OF MAIN SPANS: | 8 | APPROACH CONDITION: | |
| FEATURE ON: | MTPK(NB) | STRUCTURE LENGTH IN FEET | 640 | DATE OF INSPECTION: | 4/12/2006 |
| FEATURE UNDER | WASHINGTON ST & MCR | FEDERAL SUFFICIENCY RATING | 69 | | |
| ROAD INV NO: | 000000095X | POSTING STATUS: | 1 Open | | |
| ROUTE NO: | 00095 | POSTING TYPE: | 0 None needed | | |
| ROAD WIDTH | 30 FEET | FEDERAL BRIDGE INDICATOR: | Y | | |
| CLASS: | MAINE TURNPIKE AUTHORITY | | | | |

Structures in the Municipality of Auburn

| | | | | CONDITION RATINGS | |
|----------------------|-----------------------------|--------------------------------------|------------------------|-----------------------------------|---------------------|
| TOWN1: | Auburn | TOWN2 | No town 2 | SUBSTRUCTURE CONDITION | 7 Good |
| BRIDGE NO.: | 0081 | MAINT REGION | Southern | SUPERSTRUCTURE CONDITION | 7 Good |
| LOCATION: | 75.3 MILE POINT | YEAR BUILT | 1955 | DECK CONDITION | 7 Good |
| BRIDGE NAME | AUBURN INTERCHANG | SPAN MATERIAL | 1 Steel | CHANNEL CONDITION: | N Not Applicable |
| OWNER: | 8 ME TPK | SPAN TYPE: | 1 Girder | CULVERT CONDITION: | N Not Applicable |
| MAINTAINER | 8 ME TPK | NUMBER OF MAIN SPANS: | 1 | APPROACH CONDITION: | |
| FEATURE ON: | MTPK NB | STRUCTURE LENGTH IN FEET | 56 | DATE OF INSPECTION: | 4/12/2006 |
| FEATURE UNDER | AUBURN INTERCHANGE | | | FEDERAL SUFFICIENCY RATING | 75 |
| ROAD INV NO: | 000000095X | POSTING STATUS: | 3 Posted | | |
| ROUTE NO: | 00095 | POSTING TYPE: | 3 Underclearance Limit | | |
| ROAD WIDTH | 43 | | | | |
| | FEET | | | | |
| CLASS: | MAINE TURNPIKE AUTHORITY | FEDERAL BRIDGE INDICATOR: | Y | | |

Structures in the Municipality of Auburn

| | | | | CONDITION RATINGS | |
|----------------------|-----------------------------|--------------------------------------|---------------|-----------------------------------|------------------|
| TOWN1: | Auburn | TOWN2 | No town 2 | SUBSTRUCTURE CONDITION | 6 Satisfactory |
| BRIDGE NO.: | 0080 | MAINT REGION | Southern | SUPERSTRUCTURE CONDITION | 6 Satisfactory |
| LOCATION: | 74.5 MILE POINT | YEAR BUILT | 1955 | DECK CONDITION | 6 Satisfactory |
| BRIDGE NAME | MTPK(NB)/SLR | SPAN MATERIAL | 1 Steel | CHANNEL CONDITION: | N Not Applicable |
| OWNER: | 8 ME TPK | SPAN TYPE: | 1 Girder | CULVERT CONDITION: | N Not Applicable |
| MAINTAINER | 8 ME TPK | NUMBER OF MAIN SPANS: | 3 | APPROACH CONDITION: | |
| FEATURE ON: | MTPK(NB) | STRUCTURE LENGTH IN FEET | 112 | DATE OF INSPECTION: | 4/12/2006 |
| FEATURE UNDER | ST. LAWRENCE-ATLANTI | | | FEDERAL SUFFICIENCY RATING | 90.2 |
| ROAD INV NO: | 000000095X | POSTING STATUS: | 1 Open | | |
| ROUTE NO: | 00095 | POSTING TYPE: | 0 None needed | | |
| ROAD WIDTH | 32 FEET | | | | |
| CLASS: | MAINE TURNPIKE AUTHORITY | FEDERAL BRIDGE INDICATOR: | Y | | |

Structures in the Municipality of Auburn

| | | | | CONDITION RATINGS | |
|----------------------|-----------------------------|--------------------------------------|------------------------|-----------------------------------|--|
| TOWN1: | Auburn | TOWN2 | No town 2 | SUBSTRUCTURE CONDITION | 7 Good |
| BRIDGE NO.: | 0079 | MAINT REGION | Southern | SUPERSTRUCTURE CONDITION | 6 Satisfactory |
| LOCATION: | 74 | YEAR BUILT | 1955 | DECK CONDITION | 6 Satisfactory |
| BRIDGE NAME | RTE 122/OLD HOTEL RD | SPAN MATERIAL | 1 Steel | CHANNEL CONDITION: | N Not Applicable |
| OWNER: | 8 ME TPK | SPAN TYPE: | 1 Girder | CULVERT CONDITION: | N Not Applicable |
| MAINTAINER | 8 ME TPK | NUMBER OF MAIN SPANS: | 6 | APPROACH CONDITION: | |
| FEATURE ON: | POLAND SPRING ROAD | STRUCTURE LENGTH IN FEET | 326 | DATE OF INSPECTION: | 4/12/2006 |
| FEATURE UNDER | MTPK | | | FEDERAL SUFFICIENCY RATING | 67.8 |
| ROAD INV NO: | 000000122X | POSTING STATUS: | 3 Posted | | |
| ROUTE NO: | 00122 | POSTING TYPE: | 3 Underclearance Limit | | |
| ROAD WIDTH | 26 | | | | |
| | FEET | | | | |
| CLASS: | MAINE TURNPIKE AUTHORITY | FEDERAL BRIDGE INDICATOR: | Y | | |

Structures in the Municipality of Auburn

| | | | | CONDITION RATINGS | |
|----------------------|------------------------|----------------------------------|---------------|-----------------------------------|------------------|
| TOWN1: | Auburn | TOWN2 | No town 2 | SUBSTRUCTURE CONDITION | 5 Fair |
| BRIDGE NO.: | 0078 | MAINT REGION | Southern | SUPERSTRUCTURE CONDITION | 5 Fair |
| LOCATION: | 2.0 MI W RT 136 | YEAR BUILT | 1948 | DECK CONDITION | 5 Fair |
| BRIDGE NAME | SOPERS MILL BRIDGE | SPAN MATERIAL | 1 Steel | CHANNEL CONDITION: | 4 Poor |
| OWNER: | 4 Municipal | SPAN TYPE: | 1 Girder | CULVERT CONDITION: | N Not Applicable |
| MAINTAINER | 4 Municipal | NUMBER OF MAIN SPANS: | 1 | APPROACH CONDITION: | 8 Very Good |
| FEATURE ON: | SOPERS MILL ROAD | STRUCTURE LENGTH IN FEET | 15 | DATE OF INSPECTION: | 8/10/2005 |
| FEATURE UNDER | SOPER BROOK | | | FEDERAL SUFFICIENCY RATING | 84 |
| ROAD INV NO: | 0000111438 | POSTING STATUS: | 1 Open | | |
| ROUTE NO: | 00000 | POSTING TYPE: | 0 None needed | | |
| ROAD WIDTH | 22 FEET | | | | |
| CLASS: | MINOR SPAN ON TOWN WAY | FEDERAL BRIDGE INDICATOR: | N | | |

Structures in the Municipality of Auburn

| | | | | CONDITION RATINGS | |
|----------------------|----------------------|----------------------------------|-----------------------|-----------------------------------|------------------|
| TOWN1: | Auburn | TOWN2 | No town 2 | SUBSTRUCTURE CONDITION | 5 Fair |
| BRIDGE NO.: | 0046 | MAINT REGION | Southern | SUPERSTRUCTURE CONDITION | N Not Applicable |
| LOCATION: | E OF RTE4 OVER TURNE | YEAR BUILT | 1912 | DECK CONDITION | N Not Applicable |
| BRIDGE NAME | TURNER STREET | SPAN MATERIAL | 1 Steel | CHANNEL CONDITION: | 6 Satisfactory |
| OWNER: | 6 Railroad | SPAN TYPE: | 2 Girder - floor beam | CULVERT CONDITION: | N Not Applicable |
| MAINTAINER | 6 Railroad | NUMBER OF MAIN SPANS: | 1 | APPROACH CONDITION: | N Not Applicable |
| FEATURE ON: | MAINE CENTRAL RAIL | STRUCTURE LENGTH IN FEET | 98 | DATE OF INSPECTION: | 10/17/2005 |
| FEATURE UNDER | TURNER STREET | | | FEDERAL SUFFICIENCY RATING | |
| ROAD INV NO: | | POSTING STATUS: | 1 Open | | |
| ROUTE NO: | | POSTING TYPE: | 0 None needed | | |
| ROAD WIDTH | | | | | |
| | FEET | | | | |
| CLASS: | | FEDERAL BRIDGE INDICATOR: | Y | | |

Structures in the Municipality of Auburn

| | | | | CONDITION RATINGS | |
|----------------------|-----------------|----------------------------------|---------------|-----------------------------------|--|
| TOWN1: | Auburn | TOWN2 | No town 2 | SUBSTRUCTURE CONDITION | 4 Poor |
| BRIDGE NO.: | 0076 | MAINT REGION | Southern | SUPERSTRUCTURE CONDITION | 6 Satisfactory |
| LOCATION: | 100FT SE RT 202 | YEAR BUILT | 1930 | DECK CONDITION | 6 Satisfactory |
| BRIDGE NAME | ROUNDS CROSSING | SPAN MATERIAL | 2 Concrete | CHANNEL CONDITION: | N Not Applicable |
| OWNER: | 4 Municipal | SPAN TYPE: | 3 Slab | CULVERT CONDITION: | N Not Applicable |
| MAINTAINER | 4 Municipal | NUMBER OF MAIN SPANS: | 1 | APPROACH CONDITION: | 4 Poor |
| FEATURE ON: | DANVILLE CR RD | STRUCTURE LENGTH IN FEET | 42 | DATE OF INSPECTION: | 5/5/2005 |
| FEATURE UNDER | MCRR | | | FEDERAL SUFFICIENCY RATING | 52.8 |
| ROAD INV NO: | 0000110090 | POSTING STATUS: | 1 Open | | |
| ROUTE NO: | 00000 | POSTING TYPE: | 0 None needed | | |
| ROAD WIDTH | 27 FEET | | | | |
| CLASS: | RAILROAD BRIDGE | FEDERAL BRIDGE INDICATOR: | Y | | |

Structures in the Municipality of Auburn

| | | | | CONDITION RATINGS | |
|----------------------|-----------------------------|--------------------------------------|---------------|-----------------------------------|---------------------|
| TOWN1: | Auburn | TOWN2 | No town 2 | SUBSTRUCTURE CONDITION | 7 Good |
| BRIDGE NO.: | 1492 | MAINT REGION | Southern | SUPERSTRUCTURE CONDITION | 6 Satisfactory |
| LOCATION: | 74.51 MILE POINT | YEAR BUILT | 1955 | DECK CONDITION | 6 Satisfactory |
| BRIDGE NAME | MTPK(SB)/SLR | SPAN MATERIAL | 1 Steel | CHANNEL CONDITION: | N Not Applicable |
| OWNER: | 8 ME TPK | SPAN TYPE: | 1 Girder | CULVERT CONDITION: | N Not Applicable |
| MAINTAINER | 8 ME TPK | NUMBER OF MAIN SPANS: | 3 | APPROACH CONDITION: | |
| FEATURE ON: | MTPK(SB) | STRUCTURE LENGTH IN FEET | 112 | DATE OF INSPECTION: | 4/12/2006 |
| FEATURE UNDER | ST. LAWRENCE-ATLANTI | | | FEDERAL SUFFICIENCY RATING | 92.2 |
| ROAD INV NO: | 000000095S | POSTING STATUS: | 1 Open | | |
| ROUTE NO: | 00095 | POSTING TYPE: | 0 None needed | | |
| ROAD WIDTH | 32 | | | | |
| | FEET | | | | |
| CLASS: | MAINE TURNPIKE AUTHORITY | FEDERAL BRIDGE INDICATOR: | Y | | |

Structures in the Municipality of Auburn

| | | | | CONDITION RATINGS | |
|----------------------|--------------------------------|--------------------------------------|----------------|-----------------------------------|---------------------|
| TOWN1: | Auburn | TOWN2 | No town 2 | SUBSTRUCTURE CONDITION | 3 Serious |
| BRIDGE NO.: | 0074 | MAINT REGION | Southern | SUPERSTRUCTURE CONDITION | 3 Serious |
| LOCATION: | 0.3MI E OLD DANVILLE | YEAR BUILT | 1940 | DECK CONDITION | 5 Fair |
| BRIDGE NAME | HELM BRIDGE | SPAN MATERIAL | 1 Steel | CHANNEL CONDITION: | 3 Serious |
| OWNER: | 4 Municipal | SPAN TYPE: | 1 Girder | CULVERT CONDITION: | N Not Applicable |
| MAINTAINER | 4 Municipal | NUMBER OF MAIN SPANS: | 2 | APPROACH CONDITION: | 5 Fair |
| FEATURE ON: | BROWNS CROSSING RO | STRUCTURE LENGTH IN FEET | 51 | DATE OF INSPECTION: | 8/10/2005 |
| FEATURE UNDER | ROYAL RIVER | | | FEDERAL SUFFICIENCY RATING | 29.9 |
| ROAD INV NO: | 0000110051 | POSTING STATUS: | 3 Posted | | |
| ROUTE NO: | 00000 | POSTING TYPE: | 1 Weight Limit | | |
| ROAD WIDTH | 22 | | | | |
| | FEET | | | | |
| CLASS: | LOW USE/REDUNDANT BRIDGE | FEDERAL BRIDGE INDICATOR: | Y | | |

Structures in the Municipality of Auburn

| | | | | CONDITION RATINGS | |
|----------------------|------------------------|----------------------------------|----------------|-----------------------------------|--|
| TOWN1: | Auburn | TOWN2 | No town 2 | SUBSTRUCTURE CONDITION | 4 Poor |
| BRIDGE NO.: | 0073 | MAINT REGION | Southern | SUPERSTRUCTURE CONDITION | 3 Serious |
| LOCATION: | 0.5 MI S.OF W.AUBURN | YEAR BUILT | 1952 | DECK CONDITION | 4 Poor |
| BRIDGE NAME | GARDINER | SPAN MATERIAL | 1 Steel | CHANNEL CONDITION: | 6 Satisfactory |
| OWNER: | 4 Municipal | SPAN TYPE: | 1 Girder | CULVERT CONDITION: | N Not Applicable |
| MAINTAINER | 4 Municipal | NUMBER OF MAIN SPANS: | 1 | APPROACH CONDITION: | 7 Good |
| FEATURE ON: | PERKINS RIDGE ROAD | STRUCTURE LENGTH IN FEET | 21 | DATE OF INSPECTION: | 6/16/2005 |
| FEATURE UNDER | LAPHAM BROOK | | | FEDERAL SUFFICIENCY RATING | 35.2 |
| ROAD INV NO: | 0000110307 | POSTING STATUS: | 3 Posted | | |
| ROUTE NO: | 00000 | POSTING TYPE: | 1 Weight Limit | | |
| ROAD WIDTH | 22 FEET | | | | |
| CLASS: | MINOR SPAN ON TOWN WAY | FEDERAL BRIDGE INDICATOR: | N | | |

Structures in the Municipality of Auburn

| | | | | CONDITION RATINGS | |
|----------------------|--|--------------------------------------|--------------------|-----------------------------------|------------------|
| TOWN1: | Auburn | TOWN2 | No town 2 | SUBSTRUCTURE CONDITION | 6 Satisfactory |
| BRIDGE NO.: | 0072 | MAINT REGION | Southern | SUPERSTRUCTURE CONDITION | 8 Very Good |
| LOCATION: | 0.4 MI W'LY OF HOTEL R | YEAR BUILT | 1991 | DECK CONDITION | 8 Very Good |
| BRIDGE NAME | LAPHAM BRIDGE | SPAN MATERIAL | 7 Precast Concrete | CHANNEL CONDITION: | 7 Good |
| OWNER: | 1 State DOT | SPAN TYPE: | 3 Slab | CULVERT CONDITION: | N Not Applicable |
| MAINTAINER | 1 State DOT | NUMBER OF MAIN SPANS: | 1 | APPROACH CONDITION: | 7 Good |
| FEATURE ON: | YOUNGS CORNER ROAD | STRUCTURE LENGTH IN FEET | 37 | DATE OF INSPECTION: | 11/15/2005 |
| FEATURE UNDER | LAPHAM BROOK | | | FEDERAL SUFFICIENCY RATING | 97.9 |
| ROAD INV NO: | 0000110480 | POSTING STATUS: | 1 Open | | |
| ROUTE NO: | 00000 | POSTING TYPE: | 0 None needed | | |
| ROAD WIDTH | 32 FEET | | | | |
| CLASS: | BRIDGE ON TOWN WAY OR STATE AID ROAD | FEDERAL BRIDGE INDICATOR: | Y | | |

Structures in the Municipality of Auburn

| | | | | CONDITION RATINGS | |
|----------------------|------------------------|----------------------------------|---------------|-----------------------------------|---------------------|
| TOWN1: | Auburn | TOWN2 | No town 2 | SUBSTRUCTURE CONDITION | N Not Applicable |
| BRIDGE NO.: | 0071 | MAINT REGION | Southern | SUPERSTRUCTURE CONDITION | N Not Applicable |
| LOCATION: | 200 FT E RT 4 | YEAR BUILT | 1997 | DECK CONDITION | N Not Applicable |
| BRIDGE NAME | GRISTMILL BRIDGE | SPAN MATERIAL | 1 Steel | CHANNEL CONDITION: | 8 Very Good |
| OWNER: | 4 Municipal | SPAN TYPE: | 4 Culvert | CULVERT CONDITION: | 7 Good |
| MAINTAINER | 4 Municipal | NUMBER OF MAIN SPANS: | 1 | APPROACH CONDITION: | 8 Very Good |
| FEATURE ON: | OAK HILL ROAD | STRUCTURE LENGTH IN FEET | 14 | DATE OF INSPECTION: | 6/16/2005 |
| FEATURE UNDER | BOBBIN MILL BROOK | | | FEDERAL SUFFICIENCY RATING | 98 |
| ROAD INV NO: | 0000110287 | POSTING STATUS: | 1 Open | | |
| ROUTE NO: | 00000 | POSTING TYPE: | 0 None needed | | |
| ROAD WIDTH | 0 FEET | | | | |
| CLASS: | MINOR SPAN ON TOWN WAY | FEDERAL BRIDGE INDICATOR: | N | | |

Structures in the Municipality of Auburn

| | | | | CONDITION RATINGS | |
|----------------------|--|--------------------------------------|---------------|-----------------------------------|------------------|
| TOWN1: | Auburn | TOWN2 | No town 2 | SUBSTRUCTURE CONDITION | 6 Satisfactory |
| BRIDGE NO.: | 0070 | MAINT REGION | Southern | SUPERSTRUCTURE CONDITION | 5 Fair |
| LOCATION: | 300 FT E RT 4 | YEAR BUILT | 1925 | DECK CONDITION | 6 Satisfactory |
| BRIDGE NAME | NORTH BRIDGE | SPAN MATERIAL | 1 Steel | CHANNEL CONDITION: | 4 Poor |
| OWNER: | 1 State DOT | SPAN TYPE: | 1 Girder | CULVERT CONDITION: | N Not Applicable |
| MAINTAINER | 1 State DOT | NUMBER OF MAIN SPANS: | 1 | APPROACH CONDITION: | 2 Critical |
| FEATURE ON: | MARTIN STREET | STRUCTURE LENGTH IN FEET | 24 | DATE OF INSPECTION: | 5/12/2005 |
| FEATURE UNDER | BOBBIN MILL BROOK | | | FEDERAL SUFFICIENCY RATING | 67 |
| ROAD INV NO: | 0000110248 | POSTING STATUS: | 1 Open | | |
| ROUTE NO: | 00000 | POSTING TYPE: | 0 None needed | | |
| ROAD WIDTH | 22 FEET | | | | |
| CLASS: | BRIDGE ON TOWN WAY OR STATE AID ROAD | FEDERAL BRIDGE INDICATOR: | Y | | |

Structures in the Municipality of Auburn

| | | | | CONDITION RATINGS | |
|----------------------|------------------------|----------------------------------|---------------|-----------------------------------|------------------|
| TOWN1: | Auburn | TOWN2 | No town 2 | SUBSTRUCTURE CONDITION | N Not Applicable |
| BRIDGE NO.: | 0069 | MAINT REGION | Southern | SUPERSTRUCTURE CONDITION | N Not Applicable |
| LOCATION: | 0.2 MILES EAST ROUTE | YEAR BUILT | 1993 | DECK CONDITION | N Not Applicable |
| BRIDGE NAME | STETSON ROAD | SPAN MATERIAL | 1 Steel | CHANNEL CONDITION: | 6 Satisfactory |
| OWNER: | 4 Municipal | SPAN TYPE: | 4 Culvert | CULVERT CONDITION: | 7 Good |
| MAINTAINER | 4 Municipal | NUMBER OF MAIN SPANS: | 1 | APPROACH CONDITION: | 7 Good |
| FEATURE ON: | STETSON ROAD | STRUCTURE LENGTH IN FEET | 14 | DATE OF INSPECTION: | 6/16/2005 |
| FEATURE UNDER | BOBBIN MILL BROOK | | | FEDERAL SUFFICIENCY RATING | 97.8 |
| ROAD INV NO: | 0000110375 | POSTING STATUS: | 1 Open | | |
| ROUTE NO: | 00000 | POSTING TYPE: | 0 None needed | | |
| ROAD WIDTH | 0 FEET | | | | |
| CLASS: | MINOR SPAN ON TOWN WAY | FEDERAL BRIDGE INDICATOR: | N | | |

Structures in the Municipality of Auburn

| | | | | CONDITION RATINGS | |
|----------------------|------------------------|----------------------------------|---------------|-----------------------------------|------------------|
| TOWN1: | Auburn | TOWN2 | No town 2 | SUBSTRUCTURE CONDITION | 5 Fair |
| BRIDGE NO.: | 0062 | MAINT REGION | Southern | SUPERSTRUCTURE CONDITION | 6 Satisfactory |
| LOCATION: | 200 FT E STEVENS MILL | YEAR BUILT | 1960 | DECK CONDITION | 6 Satisfactory |
| BRIDGE NAME | STEVENS MILLS ROAD | SPAN MATERIAL | 1 Steel | CHANNEL CONDITION: | 7 Good |
| OWNER: | 4 Municipal | SPAN TYPE: | 1 Girder | CULVERT CONDITION: | N Not Applicable |
| MAINTAINER | 4 Municipal | NUMBER OF MAIN SPANS: | 1 | APPROACH CONDITION: | 5 Fair |
| FEATURE ON: | STEVENS MILL RD EX | STRUCTURE LENGTH IN FEET | 21 | DATE OF INSPECTION: | 8/10/2005 |
| FEATURE UNDER | TAYLOR BROOK | | | FEDERAL SUFFICIENCY RATING | 58.6 |
| ROAD INV NO: | 0000110517 | POSTING STATUS: | 1 Open | | |
| ROUTE NO: | 00000 | POSTING TYPE: | 0 None needed | | |
| ROAD WIDTH | 13 FEET | | | | |
| CLASS: | MINOR SPAN ON TOWN WAY | FEDERAL BRIDGE INDICATOR: | N | | |

Structures in the Municipality of Auburn

| | | | | CONDITION RATINGS | |
|----------------------|------------------------------|----------------------------------|---------------|-----------------------------------|---------------------|
| TOWN1: | Auburn | TOWN2 | No town 2 | SUBSTRUCTURE CONDITION | N Not Applicable |
| BRIDGE NO.: | 0058 | MAINT REGION | Southern | SUPERSTRUCTURE CONDITION | N Not Applicable |
| LOCATION: | .8 MI. WEST RT. 4 ON RT | YEAR BUILT | 1980 | DECK CONDITION | N Not Applicable |
| BRIDGE NAME | TAYLOR BROOK | SPAN MATERIAL | 1 Steel | CHANNEL CONDITION: | 5 Fair |
| OWNER: | 1 State DOT | SPAN TYPE: | 4 Culvert | CULVERT CONDITION: | 6 Satisfactory |
| MAINTAINER | 1 State DOT | NUMBER OF MAIN SPANS: | 1 | APPROACH CONDITION: | 4 Poor |
| FEATURE ON: | POLAND ROAD | STRUCTURE LENGTH IN FEET | 14 | DATE OF INSPECTION: | 7/1/2004 |
| FEATURE UNDER | TAYLOR BRK | | | FEDERAL SUFFICIENCY RATING | 88.4 |
| ROAD INV NO: | 0000110317 | POSTING STATUS: | 1 Open | | |
| ROUTE NO: | 00000 | POSTING TYPE: | 0 None needed | | |
| ROAD WIDTH | 0 FEET | | | | |
| CLASS: | MINOR SPAN ON STATE AID ROAD | FEDERAL BRIDGE INDICATOR: | N | | |

Structures in the Municipality of Auburn

| | | | | CONDITION RATINGS | |
|----------------------|--------------------|----------------------------------|--------------------|-----------------------------------|------------------|
| TOWN1: | Auburn | TOWN2 | No town 2 | SUBSTRUCTURE CONDITION | 6 Satisfactory |
| BRIDGE NO.: | 0057 | MAINT REGION | Southern | SUPERSTRUCTURE CONDITION | 6 Satisfactory |
| LOCATION: | .1 MI W TOWNLINE | YEAR BUILT | 1975 | DECK CONDITION | 6 Satisfactory |
| BRIDGE NAME | MAIN ST. BRIDGE | SPAN MATERIAL | 7 Precast Concrete | CHANNEL CONDITION: | N Not Applicable |
| OWNER: | 6 Railroad | SPAN TYPE: | 3 Slab | CULVERT CONDITION: | N Not Applicable |
| MAINTAINER | 6 Railroad | NUMBER OF MAIN SPANS: | 1 | APPROACH CONDITION: | 8 Very Good |
| FEATURE ON: | 136 | STRUCTURE LENGTH IN FEET | 27 | DATE OF INSPECTION: | 5/5/2005 |
| FEATURE UNDER | PEDESTRIAN WALKWAY | | | FEDERAL SUFFICIENCY RATING | 88.9 |
| ROAD INV NO: | 000000136X | POSTING STATUS: | 1 Open | | |
| ROUTE NO: | 00136 | POSTING TYPE: | 0 None needed | | |
| ROAD WIDTH | 49 FEET | | | | |
| CLASS: | RAILROAD BRIDGE | FEDERAL BRIDGE INDICATOR: | Y | | |

Structures in the Municipality of Auburn

| | | | | CONDITION RATINGS | |
|----------------------|---|----------------------------------|--|-----------------------------------|--|
| TOWN1: | <input type="text" value="Auburn"/> | TOWN2 | <input type="text" value="No town 2"/> | SUBSTRUCTURE CONDITION | <input type="text" value="4"/> <input type="text" value="Poor"/> |
| BRIDGE NO.: | <input type="text" value="0077"/> | MAINT REGION | <input type="text" value="Southern"/> | SUPERSTRUCTURE CONDITION | <input type="text" value="6"/> <input type="text" value="Satisfactory"/> |
| LOCATION: | <input type="text" value="1.8 MI N RT 5 202 /100/4"/> | YEAR BUILT | <input type="text" value="1970"/> | DECK CONDITION | <input type="text" value="5"/> <input type="text" value="Fair"/> |
| BRIDGE NAME | <input type="text" value="ROYAL RIVER BRIDGE"/> | SPAN MATERIAL | <input type="text" value="1 Steel"/> | CHANNEL CONDITION: | <input type="text" value="4"/> <input type="text" value="Poor"/> |
| OWNER: | <input type="text" value="1 State DOT"/> | SPAN TYPE: | <input type="text" value="1 Girder"/> | CULVERT CONDITION: | <input type="text" value="N"/> <input type="text" value="Not Applicable"/> |
| MAINTAINER | <input type="text" value="1 State DOT"/> | NUMBER OF MAIN SPANS: | <input type="text" value="1"/> | APPROACH CONDITION: | <input type="text" value="2"/> <input type="text" value="Critical"/> |
| FEATURE ON: | <input type="text" value="OLD DANVILLE RD"/> | STRUCTURE LENGTH IN FEET | <input type="text" value="24"/> | DATE OF INSPECTION: | <input type="text" value="10/13/2005"/> |
| FEATURE UNDER | <input type="text" value="ROYAL RIVER"/> | | | FEDERAL SUFFICIENCY RATING | <input type="text" value="63.9"/> |
| ROAD INV NO: | <input type="text" value="0000110290"/> | POSTING STATUS: | <input type="text" value="1 Open"/> | | |
| ROUTE NO: | <input type="text" value="00000"/> | POSTING TYPE: | <input type="text" value="0 None needed"/> | | |
| ROAD WIDTH | <input type="text" value="25"/> FEET | | | | |
| CLASS: | <input type="text" value="BRIDGE ON TOWN WAY OR STATE AID ROAD"/> | FEDERAL BRIDGE INDICATOR: | <input type="text" value="Y"/> | | |

Structures in the Municipality of Auburn

| | | | | CONDITION RATINGS | |
|----------------------|-------------------------|----------------------------------|---------------|-----------------------------------|------------------|
| TOWN1: | Auburn | TOWN2 | Lewiston | SUBSTRUCTURE CONDITION | 6 Satisfactory |
| BRIDGE NO.: | 3330 | MAINT REGION | Southern | SUPERSTRUCTURE CONDITION | 6 Satisfactory |
| LOCATION: | TOWNLINE | YEAR BUILT | 1936 | DECK CONDITION | 8 Very Good |
| BRIDGE NAME | SOUTH BRIDGE | SPAN MATERIAL | 1 Steel | CHANNEL CONDITION: | 7 Good |
| OWNER: | 1 State DOT | SPAN TYPE: | 5 Truss | CULVERT CONDITION: | N Not Applicable |
| MAINTAINER | 1 State DOT | NUMBER OF MAIN SPANS: | 3 | APPROACH CONDITION: | 7 Good |
| FEATURE ON: | CEDAR ST | STRUCTURE LENGTH IN FEET | 723 | DATE OF INSPECTION: | 2/12/2007 |
| FEATURE UNDER | ANDROSCOGGIN RIVER | | | FEDERAL SUFFICIENCY RATING | 50.3 |
| ROAD INV NO: | 0000120069 | POSTING STATUS: | 1 Open | | |
| ROUTE NO: | 00000 | POSTING TYPE: | 0 None needed | | |
| ROAD WIDTH | 41 FEET | | | | |
| CLASS: | BRIDGE ON STATE HIGHWAY | FEDERAL BRIDGE INDICATOR: | Y | | |

Structures in the Municipality of Auburn

| | | | | CONDITION RATINGS | |
|----------------------|-------------------------|----------------------------------|---------------|-----------------------------------|---------------------|
| TOWN1: | Auburn | TOWN2 | Lewiston | SUBSTRUCTURE CONDITION | 7 Good |
| BRIDGE NO.: | 6260 | MAINT REGION | Southern | SUPERSTRUCTURE CONDITION | 7 Good |
| LOCATION: | .5 MI W US 202 | YEAR BUILT | 1973 | DECK CONDITION | 7 Good |
| BRIDGE NAME | VIET NAM MEMORIAL | SPAN MATERIAL | 1 Steel | CHANNEL CONDITION: | 5 Fair |
| OWNER: | 1 State DOT | SPAN TYPE: | 1 Girder | CULVERT CONDITION: | N Not Applicable |
| MAINTAINER | 1 State DOT | NUMBER OF MAIN SPANS: | 3 | APPROACH CONDITION: | 7 Good |
| FEATURE ON: | VIETNAM VET WB | STRUCTURE LENGTH IN FEET | 505 | DATE OF INSPECTION: | 1/24/2007 |
| FEATURE UNDER | W CHAN ANDRO R & RIV | | | FEDERAL SUFFICIENCY RATING | 96 |
| ROAD INV NO: | 0000120510 | POSTING STATUS: | 1 Open | | |
| ROUTE NO: | 00000 | POSTING TYPE: | 0 None needed | | |
| ROAD WIDTH | 72 | | | | |
| | FEET | | | | |
| CLASS: | BRIDGE ON STATE HIGHWAY | FEDERAL BRIDGE INDICATOR: | Y | | |

Structures in the Municipality of Auburn

| | | | | CONDITION RATINGS | |
|----------------------|-------------------------|----------------------------------|---------------|-----------------------------------|------------------|
| TOWN1: | Auburn | TOWN2 | No town 2 | SUBSTRUCTURE CONDITION | 6 Satisfactory |
| BRIDGE NO.: | 5952 | MAINT REGION | Southern | SUPERSTRUCTURE CONDITION | 6 Satisfactory |
| LOCATION: | 1 MI NO TOWNLINE | YEAR BUILT | 1961 | DECK CONDITION | 4 Poor |
| BRIDGE NAME | CNR-X-ING | SPAN MATERIAL | 1 Steel | CHANNEL CONDITION: | 5 Fair |
| OWNER: | 1 State DOT | SPAN TYPE: | 1 Girder | CULVERT CONDITION: | N Not Applicable |
| MAINTAINER | 1 State DOT | NUMBER OF MAIN SPANS: | 3 | APPROACH CONDITION: | 7 Good |
| FEATURE ON: | #4-100-202 | STRUCTURE LENGTH IN FEET | 138 | DATE OF INSPECTION: | 11/13/2006 |
| FEATURE UNDER | CNR | | | FEDERAL SUFFICIENCY RATING | 57.8 |
| ROAD INV NO: | 000000202X | POSTING STATUS: | 1 Open | | |
| ROUTE NO: | 00202 | POSTING TYPE: | 0 None needed | | |
| ROAD WIDTH | 30 FEET | | | | |
| CLASS: | BRIDGE ON STATE HIGHWAY | FEDERAL BRIDGE INDICATOR: | Y | | |

Structures in the Municipality of Auburn

| | | | | CONDITION RATINGS | |
|----------------------|--|--------------------------------------|---------------|-----------------------------------|------------------|
| TOWN1: | Auburn | TOWN2 | No town 2 | SUBSTRUCTURE CONDITION | 7 Good |
| BRIDGE NO.: | 5863 | MAINT REGION | Southern | SUPERSTRUCTURE CONDITION | 7 Good |
| LOCATION: | .1 MI NE JCT LAKE SHO | YEAR BUILT | 1960 | DECK CONDITION | 7 Good |
| BRIDGE NAME | BASIN OUTLET | SPAN MATERIAL | 2 Concrete | CHANNEL CONDITION: | 6 Satisfactory |
| OWNER: | 1 State DOT | SPAN TYPE: | 3 Slab | CULVERT CONDITION: | N Not Applicable |
| MAINTAINER | 1 State DOT | NUMBER OF MAIN SPANS: | 1 | APPROACH CONDITION: | 5 Fair |
| FEATURE ON: | N AUBURN RD | STRUCTURE LENGTH IN FEET | 23 | DATE OF INSPECTION: | 5/24/2006 |
| FEATURE UNDER | WILSON STREAM | | | FEDERAL SUFFICIENCY RATING | 75.4 |
| ROAD INV NO: | 0000110361 | POSTING STATUS: | 1 Open | | |
| ROUTE NO: | 00000 | POSTING TYPE: | 0 None needed | | |
| ROAD WIDTH | 28 FEET | | | | |
| CLASS: | BRIDGE ON TOWN WAY OR STATE AID ROAD | FEDERAL BRIDGE INDICATOR: | Y | | |

Structures in the Municipality of Auburn

| | | | | CONDITION RATINGS | |
|----------------------|-------------------------|----------------------------------|---------------|-----------------------------------|------------------|
| TOWN1: | Auburn | TOWN2 | No town 2 | SUBSTRUCTURE CONDITION | 6 Satisfactory |
| BRIDGE NO.: | 5786 | MAINT REGION | Southern | SUPERSTRUCTURE CONDITION | 7 Good |
| LOCATION: | 2.3 MI SO 11-121 | YEAR BUILT | 1958 | DECK CONDITION | 5 Fair |
| BRIDGE NAME | OAKDALE(RT 100,4,202) | SPAN MATERIAL | 1 Steel | CHANNEL CONDITION: | 7 Good |
| OWNER: | 1 State DOT | SPAN TYPE: | 1 Girder | CULVERT CONDITION: | N Not Applicable |
| MAINTAINER | 1 State DOT | NUMBER OF MAIN SPANS: | 3 | APPROACH CONDITION: | 7 Good |
| FEATURE ON: | WASHINGTON ST RT 4 | STRUCTURE LENGTH IN FEET | 229 | DATE OF INSPECTION: | 11/20/2006 |
| FEATURE UNDER | LITTLE ANDROSCOGGIN | | | FEDERAL SUFFICIENCY RATING | 66.5 |
| ROAD INV NO: | 000000202S | POSTING STATUS: | 1 Open | | |
| ROUTE NO: | 00202 | POSTING TYPE: | 0 None needed | | |
| ROAD WIDTH | 30 FEET | | | | |
| CLASS: | BRIDGE ON STATE HIGHWAY | FEDERAL BRIDGE INDICATOR: | Y | | |

Structures in the Municipality of Auburn

| | | | | CONDITION RATINGS | |
|----------------------|------------------------------|----------------------------------|---------------|-----------------------------------|------------------|
| TOWN1: | Auburn | TOWN2 | No town 2 | SUBSTRUCTURE CONDITION | N Not Applicable |
| BRIDGE NO.: | 5548 | MAINT REGION | Southern | SUPERSTRUCTURE CONDITION | N Not Applicable |
| LOCATION: | .25 MI NW RTE 11-121 | YEAR BUILT | 1994 | DECK CONDITION | N Not Applicable |
| BRIDGE NAME | COURT ST/TAYLOR BR | SPAN MATERIAL | 1 Steel | CHANNEL CONDITION: | 8 Very Good |
| OWNER: | 1 State DOT | SPAN TYPE: | 4 Culvert | CULVERT CONDITION: | 6 Satisfactory |
| MAINTAINER | 1 State DOT | NUMBER OF MAIN SPANS: | 1 | APPROACH CONDITION: | 8 Very Good |
| FEATURE ON: | COURT STREET | STRUCTURE LENGTH IN FEET | 15 | DATE OF INSPECTION: | 9/21/2006 |
| FEATURE UNDER | TAYLOR BROOK | | | FEDERAL SUFFICIENCY RATING | 95.4 |
| ROAD INV NO: | 0000110079 | POSTING STATUS: | 1 Open | | |
| ROUTE NO: | 00000 | POSTING TYPE: | 0 None needed | | |
| ROAD WIDTH | 0 FEET | | | | |
| CLASS: | MINOR SPAN ON STATE AID ROAD | FEDERAL BRIDGE INDICATOR: | N | | |

Structures in the Municipality of Auburn

| | | | | CONDITION RATINGS | |
|----------------------|--|--------------------------------------|---------------|-----------------------------------|---------------------|
| TOWN1: | Auburn | TOWN2 | No town 2 | SUBSTRUCTURE CONDITION | 7 Good |
| BRIDGE NO.: | 5454 | MAINT REGION | Southern | SUPERSTRUCTURE CONDITION | 7 Good |
| LOCATION: | 2.6 MI W OF JCT 4 | YEAR BUILT | 1952 | DECK CONDITION | 7 Good |
| BRIDGE NAME | AUBURN ROAD | SPAN MATERIAL | 2 Concrete | CHANNEL CONDITION: | 6 Satisfactory |
| OWNER: | 1 State DOT | SPAN TYPE: | 3 Slab | CULVERT CONDITION: | N Not Applicable |
| MAINTAINER | 1 State DOT | NUMBER OF MAIN SPANS: | 1 | APPROACH CONDITION: | 6 Satisfactory |
| FEATURE ON: | LAKE SHORE DR | STRUCTURE LENGTH IN FEET | 23 | DATE OF INSPECTION: | 5/24/2006 |
| FEATURE UNDER | INLET TO LAKE | | | FEDERAL SUFFICIENCY RATING | 74.4 |
| ROAD INV NO: | 0000110217 | POSTING STATUS: | 1 Open | | |
| ROUTE NO: | 00000 | POSTING TYPE: | 0 None needed | | |
| ROAD WIDTH | 24 | | | | |
| | FEET | | | | |
| CLASS: | BRIDGE ON TOWN WAY OR STATE AID ROAD | FEDERAL BRIDGE INDICATOR: | Y | | |

Structures in the Municipality of Auburn

| | | | | CONDITION RATINGS | |
|----------------------|------------------------------|----------------------------------|---------------|-----------------------------------|---------------------|
| TOWN1: | Auburn | TOWN2 | No town 2 | SUBSTRUCTURE CONDITION | N Not Applicable |
| BRIDGE NO.: | 5321 | MAINT REGION | Southern | SUPERSTRUCTURE CONDITION | N Not Applicable |
| LOCATION: | 1.5*MI*NO*TOWNLIN | YEAR BUILT | 1976 | DECK CONDITION | N Not Applicable |
| BRIDGE NAME | WAGG | SPAN MATERIAL | 1 Steel | CHANNEL CONDITION: | 6 Satisfactory |
| OWNER: | 1 State DOT | SPAN TYPE: | 4 Culvert | CULVERT CONDITION: | 5 Fair |
| MAINTAINER | 1 State DOT | NUMBER OF MAIN SPANS: | 1 | APPROACH CONDITION: | 6 Satisfactory |
| FEATURE ON: | RIVERSIDE DR | STRUCTURE LENGTH IN FEET | 14 | DATE OF INSPECTION: | 7/1/2004 |
| FEATURE UNDER | WAGG BRK | | | FEDERAL SUFFICIENCY RATING | 85.8 |
| ROAD INV NO: | 000000136X | POSTING STATUS: | 1 Open | | |
| ROUTE NO: | 00136 | POSTING TYPE: | 0 None needed | | |
| ROAD WIDTH | 0 FEET | | | | |
| CLASS: | MINOR SPAN ON STATE AID ROAD | FEDERAL BRIDGE INDICATOR: | N | | |

Structures in the Municipality of Auburn

| | | | | CONDITION RATINGS | |
|----------------------|------------------------|----------------------------------|---------------|-----------------------------------|---------------------|
| TOWN1: | Auburn | TOWN2 | No town 2 | SUBSTRUCTURE CONDITION | N Not Applicable |
| BRIDGE NO.: | 3999 | MAINT REGION | Southern | SUPERSTRUCTURE CONDITION | N Not Applicable |
| LOCATION: | 400 FT N RTE #202-4 | YEAR BUILT | 1928 | DECK CONDITION | N Not Applicable |
| BRIDGE NAME | CRYSTAL SPRING | SPAN MATERIAL | 2 Concrete | CHANNEL CONDITION: | 6 Satisfactory |
| OWNER: | 4 Municipal | SPAN TYPE: | 3 Slab | CULVERT CONDITION: | 5 Fair |
| MAINTAINER | 4 Municipal | NUMBER OF MAIN SPANS: | 1 | APPROACH CONDITION: | 3 Serious |
| FEATURE ON: | BRICKYARD CIRCLE | STRUCTURE LENGTH IN FEET | 13 | DATE OF INSPECTION: | 12/7/2005 |
| FEATURE UNDER | TAYLOR BROOK | | | FEDERAL SUFFICIENCY RATING | 73 |
| ROAD INV NO: | 0000110456 | POSTING STATUS: | 1 Open | | |
| ROUTE NO: | 00000 | POSTING TYPE: | 0 None needed | | |
| ROAD WIDTH | 0 FEET | | | | |
| CLASS: | MINOR SPAN ON TOWN WAY | FEDERAL BRIDGE INDICATOR: | N | | |

Structures in the Municipality of Auburn

| | | | | CONDITION RATINGS | |
|----------------------|-------------------------|----------------------------------|-----------------------|-----------------------------------|---|
| TOWN1: | Auburn | TOWN2 | No town 2 | SUBSTRUCTURE CONDITION | 7 Good |
| BRIDGE NO.: | 3895 | MAINT REGION | Southern | SUPERSTRUCTURE CONDITION | 7 Good |
| LOCATION: | 0.4 MI S'LY RTE 202 & 4 | YEAR BUILT | 1948 | DECK CONDITION | 8 Very Good |
| BRIDGE NAME | IRON | SPAN MATERIAL | 1 Steel | CHANNEL CONDITION: | 5 Fair |
| OWNER: | 1 State DOT | SPAN TYPE: | 2 Girder - floor beam | CULVERT CONDITION: | N Not Applicable |
| MAINTAINER | 1 State DOT | NUMBER OF MAIN SPANS: | 1 | APPROACH CONDITION: | 7 Good |
| FEATURE ON: | S MAIN ST RTE 136 | STRUCTURE LENGTH IN FEET | 95 | DATE OF INSPECTION: | 12/19/2006 |
| FEATURE UNDER | LITTLE ANDROSCOGGIN | | | FEDERAL SUFFICIENCY RATING | 95.9 |
| ROAD INV NO: | 000000136X | POSTING STATUS: | 1 Open | | |
| ROUTE NO: | 00136 | POSTING TYPE: | 0 None needed | | |
| ROAD WIDTH | 45 FEET | | | | |
| CLASS: | BRIDGE ON STATE HIGHWAY | FEDERAL BRIDGE INDICATOR: | Y | | |

Structures in the Municipality of Auburn

| | | | | CONDITION RATINGS | |
|----------------------|-----------------------------|--------------------------------------|------------------------|-----------------------------------|---|
| TOWN1: | Auburn | TOWN2 | Lewiston | SUBSTRUCTURE CONDITION | 7 Good |
| BRIDGE NO.: | 0086 | MAINT REGION | Southern | SUPERSTRUCTURE CONDITION | 6 Satisfactory |
| LOCATION: | 076.29 MILE POINT | YEAR BUILT | 1955 | DECK CONDITION | 7 Good |
| BRIDGE NAME | MTPK(NB)/ANDROSCOG | SPAN MATERIAL | 1 Steel | CHANNEL CONDITION: | 8 Very Good |
| OWNER: | 8 ME TPK | SPAN TYPE: | 1 Girder | CULVERT CONDITION: | N Not Applicable |
| MAINTAINER | 8 ME TPK | NUMBER OF MAIN SPANS: | 6 | APPROACH CONDITION: | 6 Satisfactory |
| FEATURE ON: | MTPK(NB) | STRUCTURE LENGTH IN FEET | 846 | DATE OF INSPECTION: | 4/28/2004 |
| FEATURE UNDER | ANDROSCOGGIN RIVER | | | FEDERAL SUFFICIENCY RATING | 92.2 |
| ROAD INV NO: | 000000095X | POSTING STATUS: | 3 Posted | | |
| ROUTE NO: | 00095 | POSTING TYPE: | 3 Underclearance Limit | | |
| ROAD WIDTH | 38 FEET | | | | |
| CLASS: | MAINE TURNPIKE AUTHORITY | FEDERAL BRIDGE INDICATOR: | Y | | |

Structures in the Municipality of Auburn

| | | | | CONDITION RATINGS | |
|----------------------|--|--------------------------------------|---------------|-----------------------------------|------------------|
| TOWN1: | Auburn | TOWN2 | No town 2 | SUBSTRUCTURE CONDITION | 6 Satisfactory |
| BRIDGE NO.: | 3338 | MAINT REGION | Southern | SUPERSTRUCTURE CONDITION | 5 Fair |
| LOCATION: | 1.5 MI S 11-121 | YEAR BUILT | 1937 | DECK CONDITION | 6 Satisfactory |
| BRIDGE NAME | LITTLEFIELDS | SPAN MATERIAL | 1 Steel | CHANNEL CONDITION: | 6 Satisfactory |
| OWNER: | 1 State DOT | SPAN TYPE: | 5 Truss | CULVERT CONDITION: | N Not Applicable |
| MAINTAINER | 1 State DOT | NUMBER OF MAIN SPANS: | 1 | APPROACH CONDITION: | 6 Satisfactory |
| FEATURE ON: | HOTEL RD | STRUCTURE LENGTH IN FEET | 115 | DATE OF INSPECTION: | 10/17/2006 |
| FEATURE UNDER | LITTLE ANDROSCOGGIN | | | FEDERAL SUFFICIENCY RATING | 46.5 |
| ROAD INV NO: | 0000110190 | POSTING STATUS: | 1 Open | | |
| ROUTE NO: | 00000 | POSTING TYPE: | 0 None needed | | |
| ROAD WIDTH | 22 FEET | | | | |
| CLASS: | BRIDGE ON TOWN WAY OR STATE AID ROAD | FEDERAL BRIDGE INDICATOR: | Y | | |

Structures in the Municipality of Auburn

| | | | | CONDITION RATINGS | |
|----------------------|-----------------------------|--------------------------------------|---------------|-----------------------------------|---|
| TOWN1: | Auburn | TOWN2 | No town 2 | SUBSTRUCTURE CONDITION | 7 Good |
| BRIDGE NO.: | 1275 | MAINT REGION | Southern | SUPERSTRUCTURE CONDITION | 7 Good |
| LOCATION: | 71.98 | YEAR BUILT | 1987 | DECK CONDITION | 7 Good |
| BRIDGE NAME | KITTYHAWK AVE | SPAN MATERIAL | 1 Steel | CHANNEL CONDITION: | N Not Applicable |
| OWNER: | 8 ME TPK | SPAN TYPE: | 1 Girder | CULVERT CONDITION: | N Not Applicable |
| MAINTAINER | 8 ME TPK | NUMBER OF MAIN SPANS: | 3 | APPROACH CONDITION: | 7 Good |
| FEATURE ON: | INDUSTRIAL SPUR | STRUCTURE LENGTH IN FEET | 304 | DATE OF INSPECTION: | 4/15/2004 |
| FEATURE UNDER | ME.TPKE NB. & SB. | | | FEDERAL SUFFICIENCY RATING | 95.8 |
| ROAD INV NO: | 0000110766 | POSTING STATUS: | 1 Open | | |
| ROUTE NO: | 00000 | POSTING TYPE: | 0 None needed | | |
| ROAD WIDTH | 39 | | | | |
| | FEET | | | | |
| CLASS: | MAINE TURNPIKE AUTHORITY | FEDERAL BRIDGE INDICATOR: | Y | | |

Structures in the Municipality of Auburn

| | | | | CONDITION RATINGS | |
|----------------------|--|--------------------------------------|---------------|-----------------------------------|------------------|
| TOWN1: | Auburn | TOWN2 | No town 2 | SUBSTRUCTURE CONDITION | N Not Applicable |
| BRIDGE NO.: | 3225 | MAINT REGION | Southern | SUPERSTRUCTURE CONDITION | N Not Applicable |
| LOCATION: | 1.3 MI N RTE 11&121 | YEAR BUILT | 1982 | DECK CONDITION | N Not Applicable |
| BRIDGE NAME | TAYLOR BROOK | SPAN MATERIAL | 1 Steel | CHANNEL CONDITION: | 7 Good |
| OWNER: | 1 State DOT | SPAN TYPE: | 4 Culvert | CULVERT CONDITION: | 5 Fair |
| MAINTAINER | 1 State DOT | NUMBER OF MAIN SPANS: | 2 | APPROACH CONDITION: | 6 Satisfactory |
| FEATURE ON: | HOTEL ROAD | STRUCTURE LENGTH IN FEET | 28 | DATE OF INSPECTION: | 12/19/2006 |
| FEATURE UNDER | TAYLOR BRK | | | FEDERAL SUFFICIENCY RATING | 87.4 |
| ROAD INV NO: | 0000110190 | POSTING STATUS: | 1 Open | | |
| ROUTE NO: | 00000 | POSTING TYPE: | 0 None needed | | |
| ROAD WIDTH | 0 FEET | | | | |
| CLASS: | BRIDGE ON TOWN WAY OR STATE AID ROAD | FEDERAL BRIDGE INDICATOR: | Y | | |

Structures in the Municipality of Auburn

| | | | | CONDITION RATINGS | |
|----------------------|-------------------------|----------------------------------|---------------|-----------------------------------|---------------------|
| TOWN1: | Auburn | TOWN2 | Lewiston | SUBSTRUCTURE CONDITION | 7 Good |
| BRIDGE NO.: | 3076 | MAINT REGION | Southern | SUPERSTRUCTURE CONDITION | 8 Very Good |
| LOCATION: | LEWISTON-AUBURN TL | YEAR BUILT | 1983 | DECK CONDITION | 7 Good |
| BRIDGE NAME | JAMES B. LONGLEY ME | SPAN MATERIAL | 1 Steel | CHANNEL CONDITION: | 6 Satisfactory |
| OWNER: | 1 State DOT | SPAN TYPE: | 1 Girder | CULVERT CONDITION: | N Not Applicable |
| MAINTAINER | 1 State DOT | NUMBER OF MAIN SPANS: | 7 | APPROACH CONDITION: | 7 Good |
| FEATURE ON: | MAIN ST US 202 | STRUCTURE LENGTH IN FEET | 600 | DATE OF INSPECTION: | 1/24/2007 |
| FEATURE UNDER | ANDROSCOGGIN RIVER | | | FEDERAL SUFFICIENCY RATING | 82 |
| ROAD INV NO: | 000000202X | POSTING STATUS: | 1 Open | | |
| ROUTE NO: | 00202 | POSTING TYPE: | 0 None needed | | |
| ROAD WIDTH | 64 FEET | | | | |
| CLASS: | BRIDGE ON STATE HIGHWAY | FEDERAL BRIDGE INDICATOR: | Y | | |

Structures in the Municipality of Auburn

| | | | | CONDITION RATINGS | |
|----------------------|-------------------------|----------------------------------|---------------|-----------------------------------|---------------------|
| TOWN1: | Auburn | TOWN2 | No town 2 | SUBSTRUCTURE CONDITION | 8 Very Good |
| BRIDGE NO.: | 2875 | MAINT REGION | Southern | SUPERSTRUCTURE CONDITION | 7 Good |
| LOCATION: | 3.3 MI NO US 202 | YEAR BUILT | 1953 | DECK CONDITION | 7 Good |
| BRIDGE NAME | TURNER STREET | SPAN MATERIAL | 2 Concrete | CHANNEL CONDITION: | 7 Good |
| OWNER: | 1 State DOT | SPAN TYPE: | 3 Slab | CULVERT CONDITION: | N Not Applicable |
| MAINTAINER | 1 State DOT | NUMBER OF MAIN SPANS: | 2 | APPROACH CONDITION: | 7 Good |
| FEATURE ON: | ROUTE 4 | STRUCTURE LENGTH IN FEET | 24 | DATE OF INSPECTION: | 9/27/2006 |
| FEATURE UNDER | LAKE AUBURN OUTLET | | | FEDERAL SUFFICIENCY RATING | 84 |
| ROAD INV NO: | 000000004X | POSTING STATUS: | 1 Open | | |
| ROUTE NO: | 00004 | POSTING TYPE: | 0 None needed | | |
| ROAD WIDTH | 69 FEET | | | | |
| CLASS: | BRIDGE ON STATE HIGHWAY | FEDERAL BRIDGE INDICATOR: | Y | | |

Structures in the Municipality of Auburn

| | | | | CONDITION RATINGS | |
|----------------------|-------------------------|----------------------------------|---------------|-----------------------------------|------------------|
| TOWN1: | Auburn | TOWN2 | No town 2 | SUBSTRUCTURE CONDITION | 6 Satisfactory |
| BRIDGE NO.: | 2648 | MAINT REGION | Southern | SUPERSTRUCTURE CONDITION | 6 Satisfactory |
| LOCATION: | 1 MI W #4 | YEAR BUILT | 1930 | DECK CONDITION | 6 Satisfactory |
| BRIDGE NAME | PARSONS MILL | SPAN MATERIAL | 2 Concrete | CHANNEL CONDITION: | 7 Good |
| OWNER: | 1 State DOT | SPAN TYPE: | 3 Slab | CULVERT CONDITION: | N Not Applicable |
| MAINTAINER | 1 State DOT | NUMBER OF MAIN SPANS: | 1 | APPROACH CONDITION: | 7 Good |
| FEATURE ON: | MINOT AVE RTE 11-1 | STRUCTURE LENGTH IN FEET | 24 | DATE OF INSPECTION: | 10/17/2006 |
| FEATURE UNDER | TAYLOR BROOK | | | FEDERAL SUFFICIENCY RATING | 59.9 |
| ROAD INV NO: | 000000011X | POSTING STATUS: | 1 Open | | |
| ROUTE NO: | 00011 | POSTING TYPE: | 0 None needed | | |
| ROAD WIDTH | 52 FEET | | | | |
| CLASS: | BRIDGE ON STATE HIGHWAY | FEDERAL BRIDGE INDICATOR: | Y | | |

Structures in the Municipality of Auburn

| | | | | CONDITION RATINGS | |
|----------------------|-------------------------|----------------------------------|---------------|-----------------------------------|------------------|
| TOWN1: | Auburn | TOWN2 | No town 2 | SUBSTRUCTURE CONDITION | 6 Satisfactory |
| BRIDGE NO.: | 2625 | MAINT REGION | Southern | SUPERSTRUCTURE CONDITION | 6 Satisfactory |
| LOCATION: | 2.3 MI S 11,121 | YEAR BUILT | 1931 | DECK CONDITION | 6 Satisfactory |
| BRIDGE NAME | OAKDALE NB/RT 100,4,2 | SPAN MATERIAL | 2 Concrete | CHANNEL CONDITION: | 6 Satisfactory |
| OWNER: | 1 State DOT | SPAN TYPE: | 1 Girder | CULVERT CONDITION: | N Not Applicable |
| MAINTAINER | 1 State DOT | NUMBER OF MAIN SPANS: | 3 | APPROACH CONDITION: | 6 Satisfactory |
| FEATURE ON: | OAKDALE(RT 100,4,2 | STRUCTURE LENGTH IN FEET | 166 | DATE OF INSPECTION: | 11/20/2006 |
| FEATURE UNDER | LITTLE ANDROSCOGGIN | | | FEDERAL SUFFICIENCY RATING | 48.2 |
| ROAD INV NO: | 000000202X | POSTING STATUS: | 1 Open | | |
| ROUTE NO: | 00202 | POSTING TYPE: | 0 None needed | | |
| ROAD WIDTH | 25 FEET | | | | |
| CLASS: | BRIDGE ON STATE HIGHWAY | FEDERAL BRIDGE INDICATOR: | Y | | |

Structures in the Municipality of Auburn

| | | | | CONDITION RATINGS | |
|----------------------|-----------------------------|----------------------------------|---------------|-----------------------------------|------------------|
| TOWN1: | Auburn | TOWN2 | No town 2 | SUBSTRUCTURE CONDITION | N Not Applicable |
| BRIDGE NO.: | 2209 | MAINT REGION | Southern | SUPERSTRUCTURE CONDITION | N Not Applicable |
| LOCATION: | 4 MI NO TOWNLINE | YEAR BUILT | 1939 | DECK CONDITION | N Not Applicable |
| BRIDGE NAME | CRYSTAL SPRING | SPAN MATERIAL | 2 Concrete | CHANNEL CONDITION: | 8 Very Good |
| OWNER: | 1 State DOT | SPAN TYPE: | 4 Culvert | CULVERT CONDITION: | 7 Good |
| MAINTAINER | 1 State DOT | NUMBER OF MAIN SPANS: | 1 | APPROACH CONDITION: | 6 Satisfactory |
| FEATURE ON: | ROUTES 4&202 | STRUCTURE LENGTH IN FEET | 10 | DATE OF INSPECTION: | 7/22/2004 |
| FEATURE UNDER | TAYLOR BROOK | | | FEDERAL SUFFICIENCY RATING | 69 |
| ROAD INV NO: | 000000202X | POSTING STATUS: | 1 Open | | |
| ROUTE NO: | 00202 | POSTING TYPE: | 0 None needed | | |
| ROAD WIDTH | 0 FEET | | | | |
| CLASS: | MINOR SPAN ON STATE HIGHWAY | FEDERAL BRIDGE INDICATOR: | N | | |

Structures in the Municipality of Auburn

| | | | | CONDITION RATINGS | |
|----------------------|-----------------------------|--------------------------------------|---------------|-----------------------------------|------------------|
| TOWN1: | Auburn | TOWN2 | No town 2 | SUBSTRUCTURE CONDITION | 6 Satisfactory |
| BRIDGE NO.: | 1493 | MAINT REGION | Southern | SUPERSTRUCTURE CONDITION | 5 Fair |
| LOCATION: | 75.61 MILE POINT | YEAR BUILT | 1955 | DECK CONDITION | 5 Fair |
| BRIDGE NAME | MTPK(SB)/RTE 202 & CR | SPAN MATERIAL | 1 Steel | CHANNEL CONDITION: | N Not Applicable |
| OWNER: | 8 ME TPK | SPAN TYPE: | 1 Girder | CULVERT CONDITION: | N Not Applicable |
| MAINTAINER | 8 ME TPK | NUMBER OF MAIN SPANS: | 8 | APPROACH CONDITION: | |
| FEATURE ON: | MTPK (SB) | STRUCTURE LENGTH IN FEET | 640 | DATE OF INSPECTION: | 4/12/2006 |
| FEATURE UNDER | WASHINGTON ST & MCR | | | FEDERAL SUFFICIENCY RATING | 70 |
| ROAD INV NO: | 000000095S | POSTING STATUS: | 1 Open | | |
| ROUTE NO: | 00095 | POSTING TYPE: | 0 None needed | | |
| ROAD WIDTH | 30 FEET | | | | |
| CLASS: | MAINE TURNPIKE AUTHORITY | FEDERAL BRIDGE INDICATOR: | Y | | |

Structures in the Municipality of Auburn

| | | | | CONDITION RATINGS | |
|----------------------|----------------------------|--------------------------------------|--------------------|-----------------------------------|---------------------|
| TOWN1: | Auburn | TOWN2 | No town 2 | SUBSTRUCTURE CONDITION | 7 Good |
| BRIDGE NO.: | 6385 | MAINT REGION | Southern | SUPERSTRUCTURE CONDITION | 8 Very Good |
| LOCATION: | At intersection of Rout 4 | YEAR BUILT | 2001 | DECK CONDITION | 7 Good |
| BRIDGE NAME | Mt Auburn Ave. | SPAN MATERIAL | 7 Precast Concrete | CHANNEL CONDITION: | 8 Very Good |
| OWNER: | 1 State DOT | SPAN TYPE: | 1 Girder | CULVERT CONDITION: | N Not Applicable |
| MAINTAINER | 1 State DOT | NUMBER OF MAIN SPANS: | 1 | APPROACH CONDITION: | 8 Very Good |
| FEATURE ON: | Mt. Auburn Ave. | STRUCTURE LENGTH IN FEET | 124 | DATE OF INSPECTION: | 3/30/2007 |
| FEATURE UNDER | Center Street | | | FEDERAL SUFFICIENCY RATING | 93 |
| ROAD INV NO: | -1 | POSTING STATUS: | 1 Open | | |
| ROUTE NO: | - | POSTING TYPE: | 0 None needed | | |
| ROAD WIDTH | 32 | | | | |
| | FEET | | | | |
| CLASS: | BRIDGE ON STATE HIGHWAY | FEDERAL BRIDGE INDICATOR: | Y | | |

Structures in the Municipality of Auburn

| | | | | CONDITION RATINGS | |
|----------------------|--------------------------------------|----------------------------------|----------------|-----------------------------------|------------------|
| TOWN1: | Auburn | TOWN2 | No town 2 | SUBSTRUCTURE CONDITION | 6 Satisfactory |
| BRIDGE NO.: | 3339 | MAINT REGION | Southern | SUPERSTRUCTURE CONDITION | 7 Good |
| LOCATION: | 1.5 MI N RT 4 | YEAR BUILT | 1936 | DECK CONDITION | 6 Satisfactory |
| BRIDGE NAME | BOBBIN MILL BROOK | SPAN MATERIAL | 2 Concrete | CHANNEL CONDITION: | 5 Fair |
| OWNER: | 1 State DOT | SPAN TYPE: | 1 Girder | CULVERT CONDITION: | N Not Applicable |
| MAINTAINER | 1 State DOT | NUMBER OF MAIN SPANS: | 1 | APPROACH CONDITION: | 3 Serious |
| FEATURE ON: | NORTH RIVER RD | STRUCTURE LENGTH IN FEET | 29 | DATE OF INSPECTION: | 5/12/2005 |
| FEATURE UNDER | BOBBIN MILL BROOK | | | FEDERAL SUFFICIENCY RATING | 78.7 |
| ROAD INV NO: | 0000110284 | POSTING STATUS: | 3 Posted | | |
| ROUTE NO: | 00000 | POSTING TYPE: | 1 Weight Limit | | |
| ROAD WIDTH | 20 FEET | | | | |
| CLASS: | BRIDGE ON TOWN WAY OR STATE AID ROAD | FEDERAL BRIDGE INDICATOR: | Y | | |

Structures in the Municipality of Lewiston

| | | | | CONDITION RATINGS | |
|----------------------|-----------------------------|--------------------------------------|------------------------|-----------------------------------|---|
| TOWN1: | Lewiston | TOWN2 | Auburn | SUBSTRUCTURE CONDITION | 7 Good |
| BRIDGE NO.: | 1494 | MAINT REGION | Southern | SUPERSTRUCTURE CONDITION | 6 Satisfactory |
| LOCATION: | 076.29 MILE POINT | YEAR BUILT | 1955 | DECK CONDITION | 7 Good |
| BRIDGE NAME | MTPK(SB)/ANDROSCOG | SPAN MATERIAL | 1 Steel | CHANNEL CONDITION: | 8 Very Good |
| OWNER: | 8 ME TPK | SPAN TYPE: | 1 Girder | CULVERT CONDITION: | N Not Applicable |
| MAINTAINER | 8 ME TPK | NUMBER OF MAIN SPANS: | 6 | APPROACH CONDITION: | 8 Very Good |
| FEATURE ON: | MTPK(SB) | STRUCTURE LENGTH IN FEET | 846 | DATE OF INSPECTION: | 4/28/2004 |
| FEATURE UNDER | ANDROSCOGGIN RIVER | | | FEDERAL SUFFICIENCY RATING | 99 |
| ROAD INV NO: | 000000095S | POSTING STATUS: | 3 Posted | | |
| ROUTE NO: | 00095 | POSTING TYPE: | 3 Underclearance Limit | | |
| ROAD WIDTH | 38 FEET | | | | |
| CLASS: | MAINE TURNPIKE AUTHORITY | FEDERAL BRIDGE INDICATOR: | Y | | |