

2-21-2008

## Structures in the Municipality of Enfield, 2008

Maine Department of Transportation

Follow this and additional works at: [https://digitalmaine.com/mdot\\_docs](https://digitalmaine.com/mdot_docs)

---

### Recommended Citation

Maine Department of Transportation, "Structures in the Municipality of Enfield, 2008" (2008).  
*Transportation Documents*. 2613.  
[https://digitalmaine.com/mdot\\_docs/2613](https://digitalmaine.com/mdot_docs/2613)

This Text is brought to you for free and open access by the Transportation at Digital Maine. It has been accepted for inclusion in Transportation Documents by an authorized administrator of Digital Maine. For more information, please contact [statedocs@maine.gov](mailto:statedocs@maine.gov).

## Structures in the Municipality of Enfield

### CONDITION RATINGS

<b>TOWN1:</b> <input type="text" value="Enfield"/>	<b>TOWN2:</b> <input type="text" value="No town 2"/>	<b>SUBSTRUCTURE CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>BRIDGE NO.:</b> <input type="text" value="2436"/>	<b>BRIDGE REGION:</b> <input type="text" value="Eastern"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>LOCATION:</b> <input type="text" value="1 MI NO TOWNLINE"/>	<b>YEAR BUILT:</b> <input type="text" value="2011"/>	<b>DECK CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>BRDGNAME:</b> <b>KIMBALL</b>	<b>SPAN MATERIAL:</b> <input type="text" value="1 Steel"/>	<b>CHANNEL CONDITION:</b> <input type="text" value="5"/> <input type="text" value="Fair"/>
<b>OWNER:</b> <input type="text" value="1 State DOT"/>	<b>SPAN TYPE:</b> <input type="text" value="4 Culvert"/>	<b>CULVERT CONDITION:</b> <input type="text" value="9"/> <input type="text" value="Excellent"/>
<b>MAINTAINER:</b> <input type="text" value="1 State DOT"/>	<b>NUMBER OF MAIN SPANS:</b> <input type="text" value="1"/>	<b>APPROACH CONDITION:</b> <input type="text" value="9"/> <input type="text" value="Excellent"/>
<b>FEATURE ON:</b> <input type="text" value="SA 1/CARIBOU RD"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input type="text" value="13"/>	<b>DATE OF INSPECTION:</b> <input type="text" value="8/29/2012"/>
<b>FEATURE UNDER:</b> <input type="text" value="COLD STREAM"/>	<b>POSTING STATUS:</b> <input type="text" value="1 Open"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input type="text" value="54.5"/>
<b>ROAD INV NO:</b> <input type="text" value="0001900577"/>	<b>POSTING TYPE:</b> <input type="text" value="0 None needed"/>	
<b>ROUTE NO:</b> <input type="text" value="00000"/>		
<b>ROAD WIDTH:</b> <input type="text" value="0"/> <b>FEET</b>	<b>FEDERAL BRIDGE INDICATOR:</b> <input type="text" value="N"/>	
<b>CLASS:</b> <input type="text" value="MINOR SPAN ON STATE AID ROAD"/>		

## Structures in the Municipality of Enfield

### CONDITION RATINGS

<b>TOWN1:</b> <input type="text" value="Enfield"/>	<b>TOWN2:</b> <input type="text" value="No town 2"/>	<b>SUBSTRUCTURE CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>BRIDGE NO.:</b> <input type="text" value="2164"/>	<b>BRIDGE REGION:</b> <input type="text" value="Eastern"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>LOCATION:</b> <input type="text" value="1.8 MI W TOWNLIN"/>	<b>YEAR BUILT:</b> <input type="text" value="1938"/>	<b>DECK CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>BRDGNAME:</b> <input type="text" value="COLD STREAM"/>	<b>SPAN MATERIAL:</b> <input type="text" value="2 Concrete"/>	<b>CHANNEL CONDITION:</b> <input type="text" value="5"/> <input type="text" value="Fair"/>
<b>OWNER:</b> <input type="text" value="1 State DOT"/>	<b>SPAN TYPE:</b> <input type="text" value="4 Culvert"/>	<b>CULVERT CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
<b>MAINTAINER:</b> <input type="text" value="1 State DOT"/>	<b>NUMBER OF MAIN SPANS:</b> <input type="text" value="1"/>	<b>APPROACH CONDITION:</b> <input type="text" value="4"/> <input type="text" value="Poor"/>
<b>FEATURE ON:</b> <input type="text" value="#155"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input type="text" value="15"/>	<b>DATE OF INSPECTION:</b> <input type="text" value="8/28/2012"/>
<b>FEATURE UNDER:</b> <input type="text" value="COLD STREAM"/>	<b>POSTING STATUS:</b> <input type="text" value="1 Open"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input type="text" value="91.9"/>
<b>ROAD INV NO:</b> <input type="text" value="000000188X"/>	<b>POSTING TYPE:</b> <input type="text" value="0 None needed"/>	
<b>ROUTE NO:</b> <input type="text" value="00188"/>		
<b>ROAD WIDTH:</b> <input type="text" value="0"/> FEET	<b>FEDERAL BRIDGE INDICATOR:</b> <input type="text" value="N"/>	
<b>CLASS:</b> <input type="text" value="MINOR SPAN ON STATE AID ROAD"/>		

## Structures in the Municipality of Howland

### CONDITION RATINGS

<b>TOWN1:</b> <input type="text" value="Howland"/>	<b>TOWN2:</b> <input type="text" value="Enfield"/>	<b>SUBSTRUCTURE CONDITION:</b> <input type="text" value="5"/> <input type="text" value="Fair"/>
<b>BRIDGE NO.:</b> <input type="text" value="2660"/>	<b>BRIDGE REGION:</b> <input type="text" value="Eastern"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
<b>LOCATION:</b> <input type="text" value=".3 MI.W. US#2"/>	<b>YEAR BUILT:</b> <input type="text" value="1946"/>	<b>DECK CONDITION:</b> <input type="text" value="4"/> <input type="text" value="Poor"/>
<b>BRDGNAME:</b> <input type="text" value="PENOBSCOT RIVER"/>	<b>SPAN MATERIAL:</b> <input type="text" value="1 Steel"/>	<b>CHANNEL CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>OWNER:</b> <input type="text" value="1 State DOT"/>	<b>SPAN TYPE:</b> <input type="text" value="5 Truss"/>	<b>CULVERT CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>MAINTAINER:</b> <input type="text" value="1 State DOT"/>	<b>NUMBER OF MAIN SPANS:</b> <input type="text" value="5"/>	<b>APPROACH CONDITION:</b> <input type="text" value="5"/> <input type="text" value="Fair"/>
<b>FEATURE ON:</b> <input type="text" value="ROUTE 155"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input type="text" value="926"/>	<b>DATE OF INSPECTION:</b> <input type="text" value="2/14/2013"/>
<b>FEATURE UNDER:</b> <input type="text" value="PENOBSCOT RIVER"/>	<b>POSTING STATUS:</b> <input type="text" value="1 Open"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input type="text" value="42.2"/>
<b>ROAD INV NO:</b> <input type="text" value="000000006X"/>	<b>POSTING TYPE:</b> <input type="text" value="0 None needed"/>	
<b>ROUTE NO:</b> <input type="text" value="00006"/>		
<b>ROAD WIDTH:</b> <input type="text" value="26"/> <b>FEET</b>	<b>FEDERAL BRIDGE INDICATOR:</b> <input type="text" value="Y"/>	
<b>CLASS:</b> <input type="text" value="BRIDGE ON STATE HIGHWAY"/>		