

2-21-2008

Structures in the Municipality of Mars Hill, 2008

Maine Department of Transportation

Follow this and additional works at: https://digitalmaine.com/mdot_docs

Recommended Citation

Maine Department of Transportation, "Structures in the Municipality of Mars Hill, 2008" (2008).
Transportation Documents. 2735.
https://digitalmaine.com/mdot_docs/2735

This Text is brought to you for free and open access by the Transportation at Digital Maine. It has been accepted for inclusion in Transportation Documents by an authorized administrator of Digital Maine. For more information, please contact statedocs@maine.gov.

Structures in the Municipality of Mars Hill

CONDITION RATINGS

TOWN1: Mars Hill	TOWN2: No town 2	SUBSTRUCTURE CONDITION: N Not Applicable
BRIDGE NO.: 6154	BRIDGE REGION: Northern	SUPERSTRUCTURE CONDITION: N Not Applicable
LOCATION: 2.1 MI S TOWNLIN	YEAR BUILT: 1955	DECK CONDITION: N Not Applicable
BRDGNAME: ROCKY BROOK	SPAN MATERIAL: 1 Steel	CHANNEL CONDITION: 4 Poor
OWNER: 1 State DOT	SPAN TYPE: 4 Culvert	CULVERT CONDITION: 5 Fair
MAINTAINER: 1 State DOT	NUMBER OF MAIN SPANS: 1	APPROACH CONDITION: 5 Fair
FEATURE ON: US 1 A	STRUCTURE LENGTH IN FEET: 12	DATE OF INSPECTION: 11/10/2011
FEATURE UNDER: ROCKY BROOK	POSTING STATUS: 1 Open	FEDERAL SUFFICIENCY RATING: 85
ROAD INV NO: 000000001A	POSTING TYPE: 0 None needed	
ROUTE NO: 00001		
ROAD WIDTH: 0 FEET	FEDERAL BRIDGE INDICATOR: N	
CLASS: MINOR SPAN ON STATE HIGHWAY		

Structures in the Municipality of Mars Hill

CONDITION RATINGS

TOWN1: Mars Hill	TOWN2: No town 2	SUBSTRUCTURE CONDITION: N Not Applicable
BRIDGE NO.: 5269	BRIDGE REGION: Northern	SUPERSTRUCTURE CONDITION: N Not Applicable
LOCATION: 0.1 MI W OF CANADIAN BORD	YEAR BUILT: 1950	DECK CONDITION: N Not Applicable
BRDGNAME: CUSTOMS HOUSE	SPAN MATERIAL: 1 Steel	CHANNEL CONDITION: 3 Serious
OWNER: 4 Municipal	SPAN TYPE: 4 Culvert	CULVERT CONDITION: 3 Serious
MAINTAINER: 4 Municipal	NUMBER OF MAIN SPANS: 3	APPROACH CONDITION: 4 Poor
FEATURE ON: SA6/E.RIDGE OR KNO	STRUCTURE LENGTH IN FEET: 18	DATE OF INSPECTION: 10/13/2011
FEATURE UNDER: GIZOQUIT BROOK	POSTING STATUS: 1 Open	FEDERAL SUFFICIENCY RATING: 48.6
ROAD INV NO: 0000300810	POSTING TYPE: 0 None needed	
ROUTE NO: 00000		
ROAD WIDTH: 0 FEET	FEDERAL BRIDGE INDICATOR: N	
CLASS: MINOR SPAN ON STATE AID ROAD		

Structures in the Municipality of Mars Hill

CONDITION RATINGS

TOWN1: Mars Hill	TOWN2: No town 2	SUBSTRUCTURE CONDITION: N Not Applicable
BRIDGE NO.: 5268	BRIDGE REGION: Northern	SUPERSTRUCTURE CONDITION: N Not Applicable
LOCATION: .5 MI E JCT US 1	YEAR BUILT: 1950	DECK CONDITION: N Not Applicable
BRDGNAME: BOYNTON	SPAN MATERIAL: 1 Steel	CHANNEL CONDITION: 6 Satisfactory
OWNER: 1 State DOT	SPAN TYPE: 6 Arch	CULVERT CONDITION: 7 Good
MAINTAINER: 1 State DOT	NUMBER OF MAIN SPANS: 1	APPROACH CONDITION: 8 Very Good
FEATURE ON: SA 7	STRUCTURE LENGTH IN FEET: 19	DATE OF INSPECTION: 11/10/2011
FEATURE UNDER: ROCKY BROOK	POSTING STATUS: 1 Open	FEDERAL SUFFICIENCY RATING: 92.7
ROAD INV NO: 0000300820	POSTING TYPE: 0 None needed	
ROUTE NO: 00000		
ROAD WIDTH: 0 FEET	FEDERAL BRIDGE INDICATOR: N	
CLASS: MINOR SPAN ON STATE AID ROAD		

Structures in the Municipality of Mars Hill

CONDITION RATINGS

TOWN1: Mars Hill	TOWN2: No town 2	SUBSTRUCTURE CONDITION: N Not Applicable
BRIDGE NO.: 5024	BRIDGE REGION: Northern	SUPERSTRUCTURE CONDITION: N Not Applicable
LOCATION: .5 MI E JCT US 1	YEAR BUILT: 1922	DECK CONDITION: N Not Applicable
BRDGNAME: KINGS GROVE	SPAN MATERIAL: 2 Concrete	CHANNEL CONDITION: 4 Poor
OWNER: 1 State DOT	SPAN TYPE: 3 Slab	CULVERT CONDITION: 5 Fair
MAINTAINER: 1 State DOT	NUMBER OF MAIN SPANS: 1	APPROACH CONDITION: 7 Good
FEATURE ON: SA 6	STRUCTURE LENGTH IN FEET: 12	DATE OF INSPECTION: 11/10/2011
FEATURE UNDER: ROCKY BROOK	POSTING STATUS: 1 Open	FEDERAL SUFFICIENCY RATING: 89.8
ROAD INV NO: 0000300802	POSTING TYPE: 0 None needed	
ROUTE NO: 00000		
ROAD WIDTH: 0 FEET	FEDERAL BRIDGE INDICATOR: N	
CLASS: MINOR SPAN ON STATE AID ROAD		

Structures in the Municipality of Mars Hill

CONDITION RATINGS

TOWN1: Mars Hill	TOWN2: No town 2	SUBSTRUCTURE CONDITION: 4 Poor
BRIDGE NO.: 2686	BRIDGE REGION: Northern	SUPERSTRUCTURE CONDITION: 6 Satisfactory
LOCATION: 0.2 MI NE OF JCT US1	YEAR BUILT: 1955	DECK CONDITION: 6 Satisfactory
BRDGNAME: PRESTILE STREAM	SPAN MATERIAL: 2 Concrete	CHANNEL CONDITION: 6 Satisfactory
OWNER: 1 State DOT	SPAN TYPE: 1 Girder	CULVERT CONDITION: N Not Applicable
MAINTAINER: 1 State DOT	NUMBER OF MAIN SPANS: 2	APPROACH CONDITION: 7 Good
FEATURE ON: US 1A	STRUCTURE LENGTH IN FEET: 87	DATE OF INSPECTION: 10/10/2012
FEATURE UNDER: PRESTILE STREAM	POSTING STATUS: 1 Open	FEDERAL SUFFICIENCY RATING: 72.7
ROAD INV NO: 000000001A	POSTING TYPE: 0 None needed	
ROUTE NO: 00001		
ROAD WIDTH: 40 FEET	FEDERAL BRIDGE INDICATOR: Y	
CLASS: BRIDGE ON STATE HIGHWAY		