

Maine State Library

**Digital Maine**

---

Transportation Documents

Transportation

---

2-21-2008

## **Structures in the Municipality of South Berwick, 2008**

Maine Department of Transportation

Follow this and additional works at: [https://digitalmaine.com/mdot\\_docs](https://digitalmaine.com/mdot_docs)

---

## Structures in the Municipality of Eliot

### CONDITION RATINGS

<b>TOWN1:</b> Eliot	<b>TOWN2:</b> South Berwick	<b>SUBSTRUCTURE CONDITION:</b> 4 Poor
<b>BRIDGE NO.:</b> 2762	<b>BRIDGE REGION:</b> Southern	<b>SUPERSTRUCTURE CONDITION:</b> 4 Poor
<b>LOCATION:</b> .1 MI NE RTE 101	<b>YEAR BUILT:</b> 1936	<b>DECK CONDITION:</b> 7 Good
<b>BRDGNAME:</b> SHOREY	<b>SPAN MATERIAL:</b> 3 Wood	<b>CHANNEL CONDITION:</b> 5 Fair
<b>OWNER:</b> 4 Municipal	<b>SPAN TYPE:</b> 1 Girder	<b>CULVERT CONDITION:</b> N Not Applicable
<b>MAINTAINER:</b> 4 Municipal	<b>NUMBER OF MAIN SPANS:</b> 1	<b>APPROACH CONDITION:</b> 5 Fair
<b>FEATURE ON:</b> OLD FIELD RD	<b>STRUCTURE LENGTH IN FEET:</b> 14	<b>DATE OF INSPECTION:</b> 12/5/2011
<b>FEATURE UNDER:</b> SHOREY BK.	<b>POSTING STATUS:</b> 3 Posted	<b>FEDERAL SUFFICIENCY RATING:</b> 21.9
<b>ROAD INV NO:</b> 0003101593	<b>POSTING TYPE:</b> 1 Weight Limit	
<b>ROUTE NO:</b> 00000		
<b>ROAD WIDTH:</b> 21 FEET	<b>FEDERAL BRIDGE INDICATOR:</b> N	
<b>CLASS:</b> MINOR SPAN ON TOWN WAY		

## Structures in the Municipality of South Berwick

### CONDITION RATINGS

<b>TOWN1:</b> <input type="text" value="South Berwick"/>	<b>TOWN2:</b> <input type="text" value="No town 2"/>	<b>SUBSTRUCTURE CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>BRIDGE NO.:</b> <input type="text" value="1235"/>	<b>BRIDGE REGION:</b> <input type="text" value="Southern"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>LOCATION:</b> <input type="text" value="0.6 MIE OF GREAT HILL RD"/>	<b>YEAR BUILT:</b> <input type="text" value="1999"/>	<b>DECK CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>BRDGNAME:</b> <input type="text" value="RODIER"/>	<b>SPAN MATERIAL:</b> <input type="text" value="1 Steel"/>	<b>CHANNEL CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
<b>OWNER:</b> <input type="text" value="4 Municipal"/>	<b>SPAN TYPE:</b> <input type="text" value="4 Culvert"/>	<b>CULVERT CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>MAINTAINER:</b> <input type="text" value="4 Municipal"/>	<b>NUMBER OF MAIN SPANS:</b> <input type="text" value="1"/>	<b>APPROACH CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>FEATURE ON:</b> <input type="text" value="RODIER RD"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input type="text" value="15"/>	<b>DATE OF INSPECTION:</b> <input type="text" value="4/5/2011"/>
<b>FEATURE UNDER:</b> <input type="text" value="GRAY BROOK"/>	<b>POSTING STATUS:</b> <input type="text" value="1 Open"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input type="text" value="99.9"/>
<b>ROAD INV NO:</b> <input type="text" value="0003100606"/>	<b>POSTING TYPE:</b> <input type="text" value="0 None needed"/>	
<b>ROUTE NO:</b> <input type="text" value="00000"/>		
<b>ROAD WIDTH:</b> <input type="text" value="0"/> FEET	<b>FEDERAL BRIDGE INDICATOR:</b> <input type="text" value="N"/>	
<b>CLASS:</b> <input type="text" value="MINOR SPAN ON TOWN WAY"/>		

## Structures in the Municipality of South Berwick

### CONDITION RATINGS

<b>TOWN1:</b> <input type="text" value="South Berwick"/>	<b>TOWN2:</b> <input type="text" value="No town 2"/>	<b>SUBSTRUCTURE CONDITION:</b> <input type="text" value="9"/> <input type="text" value="Excellent"/>	
<b>BRIDGE NO.:</b> <input type="text" value="1236"/>	<b>BRIDGE REGION:</b> <input type="text" value="Southern"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input type="text" value="9"/> <input type="text" value="Excellent"/>	
<b>LOCATION:</b> <input type="text" value=".5 MI E HOOPER SANDS RD"/>	<b>YEAR BUILT:</b> <input type="text" value="2011"/>	<b>DECK CONDITION:</b> <input type="text" value="9"/> <input type="text" value="Excellent"/>	
<b>BRDGNAME:</b> <input type="text" value="GREAT HILL"/>	<b>SPAN MATERIAL:</b> <input type="text" value="1 Steel"/>	<b>CHANNEL CONDITION:</b> <input type="text" value="8"/> <input type="text" value="Very Good"/>	
<b>OWNER:</b> <input type="text" value="1 State DOT"/>	<b>SPAN TYPE:</b> <input type="text" value="1 Girder"/>	<b>CULVERT CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>	
<b>MAINTAINER:</b> <input type="text" value="1 State DOT"/>	<b>NUMBER OF MAIN SPANS:</b> <input type="text" value="1"/>	<b>APPROACH CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>	
<b>FEATURE ON:</b> <input type="text" value="GREAT HILL RD"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input type="text" value="74"/>	<b>DATE OF INSPECTION:</b> <input type="text" value="10/10/2012"/>	
<b>FEATURE UNDER:</b> <input type="text" value="GREAT WORKS RIVER"/>	<b>POSTING STATUS:</b> <input type="text" value="1 Open"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input type="text" value="36.3"/>	
<b>ROAD INV NO:</b> <input type="text" value="0003100606"/>	<b>POSTING TYPE:</b> <input type="text" value="0 None needed"/>		
<b>ROUTE NO:</b> <input type="text" value="00000"/>			
<b>ROAD WIDTH:</b> <input type="text" value="16"/> <b>FEET</b>	<b>FEDERAL BRIDGE INDICATOR:</b> <input type="text" value="Y"/>		
<b>CLASS:</b> <input type="text" value="BRIDGE ON TOWN WAY OR STATE AID ROAD"/>			

## Structures in the Municipality of South Berwick

### CONDITION RATINGS

<b>TOWN1:</b> <input type="text" value="South Berwick"/>	<b>TOWN2:</b> <input type="text" value="No town 2"/>	<b>SUBSTRUCTURE CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>BRIDGE NO.:</b> <input type="text" value="1237"/>	<b>BRIDGE REGION:</b> <input type="text" value="Southern"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>LOCATION:</b> <input type="text" value="2 MI E RTE 4"/>	<b>YEAR BUILT:</b> <input type="text" value="2003"/>	<b>DECK CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>BRDGNAME:</b> BENNETT	<b>SPAN MATERIAL:</b> <input type="text" value="1 Steel"/>	<b>CHANNEL CONDITION:</b> <input type="text" value="8"/> <input type="text" value="Very Good"/>
<b>OWNER:</b> <input type="text" value="4 Municipal"/>	<b>SPAN TYPE:</b> <input type="text" value="4 Culvert"/>	<b>CULVERT CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>MAINTAINER:</b> <input type="text" value="4 Municipal"/>	<b>NUMBER OF MAIN SPANS:</b> <input type="text" value="1"/>	<b>APPROACH CONDITION:</b> <input type="text" value="8"/> <input type="text" value="Very Good"/>
<b>FEATURE ON:</b> <input type="text" value="AGAMENTICUS RD"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input type="text" value="14"/>	<b>DATE OF INSPECTION:</b> <input type="text" value="4/7/2011"/>
<b>FEATURE UNDER:</b> <input type="text" value="LOVES BROOK"/>	<b>POSTING STATUS:</b> <input type="text" value="1 Open"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input type="text" value="99.8"/>
<b>ROAD INV NO:</b> <input type="text" value="0003100651"/>	<b>POSTING TYPE:</b> <input type="text" value="0 None needed"/>	
<b>ROUTE NO:</b> <input type="text" value="00000"/>		
<b>ROAD WIDTH:</b> <input type="text" value="0"/> FEET	<b>FEDERAL BRIDGE INDICATOR:</b> <input type="text" value="N"/>	
<b>CLASS:</b> <input type="text" value="MINOR SPAN ON TOWN WAY"/>		

## Structures in the Municipality of South Berwick

### CONDITION RATINGS

<b>TOWN1:</b> <input type="text" value="South Berwick"/>	<b>TOWN2:</b> <input type="text" value="No town 2"/>	<b>SUBSTRUCTURE CONDITION:</b> <input type="text" value="8"/> <input type="text" value="Very Good"/>
<b>BRIDGE NO.:</b> <input type="text" value="1240"/>	<b>BRIDGE REGION:</b> <input type="text" value="Southern"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input type="text" value="8"/> <input type="text" value="Very Good"/>
<b>LOCATION:</b> <input type="text" value=".6 MLE RTE 4"/>	<b>YEAR BUILT:</b> <input type="text" value="2002"/>	<b>DECK CONDITION:</b> <input type="text" value="8"/> <input type="text" value="Very Good"/>
<b>BRDGNAME:</b> <input type="text" value="DENET # 2"/>	<b>SPAN MATERIAL:</b> <input type="text" value="1 Steel"/>	<b>CHANNEL CONDITION:</b> <input type="text" value="8"/> <input type="text" value="Very Good"/>
<b>OWNER:</b> <input type="text" value="4 Municipal"/>	<b>SPAN TYPE:</b> <input type="text" value="1 Girder"/>	<b>CULVERT CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>MAINTAINER:</b> <input type="text" value="4 Municipal"/>	<b>NUMBER OF MAIN SPANS:</b> <input type="text" value="1"/>	<b>APPROACH CONDITION:</b> <input type="text" value="5"/> <input type="text" value="Fair"/>
<b>FEATURE ON:</b> <input type="text" value="OLD N BERWICK RD"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input type="text" value="61"/>	<b>DATE OF INSPECTION:</b> <input type="text" value="4/5/2011"/>
<b>FEATURE UNDER:</b> <input type="text" value="GREAT WORKS RIVER"/>	<b>POSTING STATUS:</b> <input type="text" value="1 Open"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input type="text" value="81.4"/>
<b>ROAD INV NO:</b> <input type="text" value="0003100461"/>	<b>POSTING TYPE:</b> <input type="text" value="0 None needed"/>	
<b>ROUTE NO:</b> <input type="text" value="00000"/>		
<b>ROAD WIDTH:</b> <input type="text" value="22"/> <b>FEET</b>	<b>FEDERAL BRIDGE INDICATOR:</b> <input type="text" value="Y"/>	
<b>CLASS:</b> <input type="text" value="LOW USE/REDUNDANT BRIDGE"/>		

## Structures in the Municipality of South Berwick

### CONDITION RATINGS

<b>TOWN1:</b> <input type="text" value="South Berwick"/>	<b>TOWN2:</b> <input type="text" value="No town 2"/>	<b>SUBSTRUCTURE CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>BRIDGE NO.:</b> <input type="text" value="1243"/>	<b>BRIDGE REGION:</b> <input type="text" value="Southern"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>LOCATION:</b> <input type="text" value="150' N OF EMERYS BR RD"/>	<b>YEAR BUILT:</b> <input type="text" value="1983"/>	<b>DECK CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>BRDGNAME:</b> EMERYS	<b>SPAN MATERIAL:</b> <input type="text" value="1 Steel"/>	<b>CHANNEL CONDITION:</b> <input type="text" value="4"/> <input type="text" value="Poor"/>
<b>OWNER:</b> <input type="text" value="1 State DOT"/>	<b>SPAN TYPE:</b> <input type="text" value="1 Girder"/>	<b>CULVERT CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>MAINTAINER:</b> <input type="text" value="1 State DOT"/>	<b>NUMBER OF MAIN SPANS:</b> <input type="text" value="1"/>	<b>APPROACH CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
<b>FEATURE ON:</b> <input type="text" value="HOOPER SANDS ROAD"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input type="text" value="84"/>	<b>DATE OF INSPECTION:</b> <input type="text" value="10/10/2012"/>
<b>FEATURE UNDER:</b> <input type="text" value="GREAT WORKS RIVER"/>	<b>POSTING STATUS:</b> <input type="text" value="1 Open"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input type="text" value="95.9"/>
<b>ROAD INV NO:</b> <input type="text" value="0003100649"/>	<b>POSTING TYPE:</b> <input type="text" value="0 None needed"/>	
<b>ROUTE NO:</b> <input type="text" value="00000"/>		
<b>ROAD WIDTH:</b> <input type="text" value="27"/> FEET	<b>FEDERAL BRIDGE INDICATOR:</b> <input type="text" value="Y"/>	
<b>CLASS:</b> <input type="text" value="BRIDGE ON TOWN WAY OR STATE AID ROAD"/>		

## Structures in the Municipality of South Berwick

### CONDITION RATINGS

<b>TOWN1:</b> <input type="text" value="South Berwick"/>	<b>TOWN2:</b> <input type="text" value="No town 2"/>	<b>SUBSTRUCTURE CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>BRIDGE NO.:</b> <input type="text" value="1245"/>	<b>BRIDGE REGION:</b> <input type="text" value="Southern"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>LOCATION:</b> <input type="text" value="1.1 MI SW EMERY'S BR RD"/>	<b>YEAR BUILT:</b> <input type="text" value="2003"/>	<b>DECK CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
<b>BRDGNAME:</b> HOOPER MILL	<b>SPAN MATERIAL:</b> <input type="text" value="1 Steel"/>	<b>CHANNEL CONDITION:</b> <input type="text" value="8"/> <input type="text" value="Very Good"/>
<b>OWNER:</b> <input type="text" value="4 Municipal"/>	<b>SPAN TYPE:</b> <input type="text" value="1 Girder"/>	<b>CULVERT CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>MAINTAINER:</b> <input type="text" value="4 Municipal"/>	<b>NUMBER OF MAIN SPANS:</b> <input type="text" value="1"/>	<b>APPROACH CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>FEATURE ON:</b> <input type="text" value="BELL MARSH ROAD"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input type="text" value="24"/>	<b>DATE OF INSPECTION:</b> <input type="text" value="4/7/2011"/>
<b>FEATURE UNDER:</b> <input type="text" value="HOOPER BROOK"/>	<b>POSTING STATUS:</b> <input type="text" value="3 Posted"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input type="text" value="70.9"/>
<b>ROAD INV NO:</b> <input type="text" value="0003100655"/>	<b>POSTING TYPE:</b> <input type="text" value="1 Weight Limit"/>	
<b>ROUTE NO:</b> <input type="text" value="00000"/>		
<b>ROAD WIDTH:</b> <input type="text" value="20"/> FEET	<b>FEDERAL BRIDGE INDICATOR:</b> <input type="text" value="Y"/>	
<b>CLASS:</b> <input type="text" value="MINOR SPAN ON TOWN WAY"/>		



## Structures in the Municipality of South Berwick

### CONDITION RATINGS

<b>TOWN1:</b> <input style="width: 150px;" type="text" value="South Berwick"/>	<b>TOWN2:</b> <input style="width: 100px;" type="text" value="No town 2"/>	<b>SUBSTRUCTURE CONDITION:</b> <input style="width: 20px;" type="text" value="N"/> <input style="width: 80px;" type="text" value="Not Applicable"/>
<b>BRIDGE NO.:</b> <input style="width: 50px;" type="text" value="0221"/>	<b>BRIDGE REGION:</b> <input style="width: 80px;" type="text" value="Southern"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input style="width: 20px;" type="text" value="N"/> <input style="width: 80px;" type="text" value="Not Applicable"/>
<b>LOCATION:</b> <input style="width: 130px;" type="text" value="3.5 MI. N. RTE. 91"/>	<b>YEAR BUILT:</b> <input style="width: 50px;" type="text" value="1980"/>	<b>DECK CONDITION:</b> <input style="width: 20px;" type="text" value="N"/> <input style="width: 80px;" type="text" value="Not Applicable"/>
<b>BRDGNAME:</b> <input style="width: 100px;" type="text" value="HOOPER BROOK"/>	<b>SPAN MATERIAL:</b> <input style="width: 100px;" type="text" value="1 Steel"/>	<b>CHANNEL CONDITION:</b> <input style="width: 20px;" type="text" value="6"/> <input style="width: 80px;" type="text" value="Satisfactory"/>
<b>OWNER:</b> <input style="width: 80px;" type="text" value="4 Municipal"/>	<b>SPAN TYPE:</b> <input style="width: 100px;" type="text" value="4 Culvert"/>	<b>CULVERT CONDITION:</b> <input style="width: 20px;" type="text" value="5"/> <input style="width: 80px;" type="text" value="Fair"/>
<b>MAINTAINER:</b> <input style="width: 100px;" type="text" value="4 Municipal"/>	<b>NUMBER OF MAIN SPANS:</b> <input style="width: 40px;" type="text" value="1"/>	<b>APPROACH CONDITION:</b> <input style="width: 20px;" type="text" value="5"/> <input style="width: 80px;" type="text" value="Fair"/>
<b>FEATURE ON:</b> <input style="width: 100px;" type="text" value="EMERYS BRIDGE ROAD"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input style="width: 40px;" type="text" value="10"/>	<b>DATE OF INSPECTION:</b> <input style="width: 60px;" type="text" value="4/7/2011"/>
<b>FEATURE UNDER:</b> <input style="width: 100px;" type="text" value="HOOPERS BROOK"/>	<b>POSTING STATUS:</b> <input style="width: 80px;" type="text" value="1 Open"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input style="width: 50px;" type="text" value="75.1"/>
<b>ROAD INV NO:</b> <input style="width: 60px;" type="text" value="0003100646"/>	<b>POSTING TYPE:</b> <input style="width: 90px;" type="text" value="0 None needed"/>	
<b>ROUTE NO:</b> <input style="width: 60px;" type="text" value="00000"/>		
<b>ROAD WIDTH:</b> <input style="width: 40px;" type="text" value="0"/> <b>FEET</b>	<b>FEDERAL BRIDGE INDICATOR:</b> <input style="width: 30px;" type="text" value="N"/>	
<b>CLASS:</b> <input style="width: 100px;" type="text" value="MINOR SPAN ON TOWN WAY"/>		

## Structures in the Municipality of South Berwick

### CONDITION RATINGS

<b>TOWN1:</b> <input type="text" value="South Berwick"/>	<b>TOWN2:</b> <input type="text" value="No town 2"/>	<b>SUBSTRUCTURE CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>BRIDGE NO.:</b> <input type="text" value="3027"/>	<b>BRIDGE REGION:</b> <input type="text" value="Southern"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
<b>LOCATION:</b> <input type="text" value=".3 MI S OF S JCT RTE 236"/>	<b>YEAR BUILT:</b> <input type="text" value="1971"/>	<b>DECK CONDITION:</b> <input type="text" value="8"/> <input type="text" value="Very Good"/>
<b>BRDGNAME:</b> <input type="text" value="LANDING"/>	<b>SPAN MATERIAL:</b> <input type="text" value="1 Steel"/>	<b>CHANNEL CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>OWNER:</b> <input type="text" value="1 State DOT"/>	<b>SPAN TYPE:</b> <input type="text" value="1 Girder"/>	<b>CULVERT CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>MAINTAINER:</b> <input type="text" value="1 State DOT"/>	<b>NUMBER OF MAIN SPANS:</b> <input type="text" value="2"/>	<b>APPROACH CONDITION:</b> <input type="text" value="8"/> <input type="text" value="Very Good"/>
<b>FEATURE ON:</b> <input type="text" value="ROUTE 4"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input type="text" value="165"/>	<b>DATE OF INSPECTION:</b> <input type="text" value="5/21/2012"/>
<b>FEATURE UNDER:</b> <input type="text" value="SALMON FALLS RIVER"/>	<b>POSTING STATUS:</b> <input type="text" value="1 Open"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input type="text" value="97.2"/>
<b>ROAD INV NO:</b> <input type="text" value="000000004X"/>	<b>POSTING TYPE:</b> <input type="text" value="0 None needed"/>	
<b>ROUTE NO:</b> <input type="text" value="00004"/>		
<b>ROAD WIDTH:</b> <input type="text" value="44"/> FEET	<b>FEDERAL BRIDGE INDICATOR:</b> <input type="text" value="Y"/>	
<b>CLASS:</b> <input type="text" value="BRIDGE ON STATE HIGHWAY"/>		

## Structures in the Municipality of South Berwick

### CONDITION RATINGS

<b>TOWN1:</b> <input type="text" value="South Berwick"/>	<b>TOWN2:</b> <input type="text" value="No town 2"/>	<b>SUBSTRUCTURE CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>BRIDGE NO.:</b> <input type="text" value="6415"/>	<b>BRIDGE REGION:</b> <input type="text" value="Southern"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>LOCATION:</b> <input type="text" value=".1 SOUTH BERWICK T.L."/>	<b>YEAR BUILT:</b> <input type="text" value="2000"/>	<b>DECK CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>BRDGNAME:</b> <input type="text" value="OUTLET GOLF XING"/>	<b>SPAN MATERIAL:</b> <input type="text" value="2 Concrete"/>	<b>CHANNEL CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>OWNER:</b> <input type="text" value="7 Private"/>	<b>SPAN TYPE:</b> <input type="text" value="4 Culvert"/>	<b>CULVERT CONDITION:</b> <input type="text" value="9"/> <input type="text" value="Excellent"/>
<b>MAINTAINER:</b> <input type="text" value="7 Private"/>	<b>NUMBER OF MAIN SPANS:</b> <input type="text" value="1"/>	<b>APPROACH CONDITION:</b> <input type="text" value="8"/> <input type="text" value="Very Good"/>
<b>FEATURE ON:</b> <input type="text" value="ROUTE 4"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input type="text" value="12"/>	<b>DATE OF INSPECTION:</b> <input type="text" value="4/6/2001"/>
<b>FEATURE UNDER:</b> <input type="text" value="GOLF COURSE UNDERPA"/>	<b>POSTING STATUS:</b> <input type="text" value="1 Open"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input type="text" value="99"/>
<b>ROAD INV NO:</b> <input type="text" value="000000004X"/>	<b>POSTING TYPE:</b> <input type="text" value="0 None needed"/>	
<b>ROUTE NO:</b> <input type="text" value="00004"/>		
<b>ROAD WIDTH:</b> <input type="text" value="0"/> <b>FEET</b>	<b>FEDERAL BRIDGE INDICATOR:</b> <input type="text" value="N"/>	
<b>CLASS:</b> <input type="text" value="MINOR SPAN ON STATE HIGHWAY"/>		

## Structures in the Municipality of South Berwick

### CONDITION RATINGS

<b>TOWN1:</b> <input style="width: 150px;" type="text" value="South Berwick"/>	<b>TOWN2:</b> <input style="width: 100px;" type="text" value="No town 2"/>	<b>SUBSTRUCTURE CONDITION:</b> <input style="width: 20px;" type="text" value="N"/> <input style="width: 80px;" type="text" value="Not Applicable"/>
<b>BRIDGE NO.:</b> <input style="width: 50px;" type="text" value="3311"/>	<b>BRIDGE REGION:</b> <input style="width: 80px;" type="text" value="Southern"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input style="width: 20px;" type="text" value="N"/> <input style="width: 80px;" type="text" value="Not Applicable"/>
<b>LOCATION:</b> <input style="width: 130px;" type="text" value="3.0 MI S RT 236"/>	<b>YEAR BUILT:</b> <input style="width: 50px;" type="text" value="1989"/>	<b>DECK CONDITION:</b> <input style="width: 20px;" type="text" value="N"/> <input style="width: 80px;" type="text" value="Not Applicable"/>
<b>BRDGNAME:</b> <input style="width: 100px;" type="text" value="NEALS BRIDGE"/>	<b>SPAN MATERIAL:</b> <input style="width: 100px;" type="text" value="1 Steel"/>	<b>CHANNEL CONDITION:</b> <input style="width: 20px;" type="text" value="6"/> <input style="width: 80px;" type="text" value="Satisfactory"/>
<b>OWNER:</b> <input style="width: 80px;" type="text" value="4 Municipal"/>	<b>SPAN TYPE:</b> <input style="width: 100px;" type="text" value="4 Culvert"/>	<b>CULVERT CONDITION:</b> <input style="width: 20px;" type="text" value="6"/> <input style="width: 80px;" type="text" value="Satisfactory"/>
<b>MAINTAINER:</b> <input style="width: 100px;" type="text" value="4 Municipal"/>	<b>NUMBER OF MAIN SPANS:</b> <input style="width: 40px;" type="text" value="1"/>	<b>APPROACH CONDITION:</b> <input style="width: 20px;" type="text" value="7"/> <input style="width: 80px;" type="text" value="Good"/>
<b>FEATURE ON:</b> <input style="width: 100px;" type="text" value="OLD FIELD ROAD"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input style="width: 40px;" type="text" value="10"/>	<b>DATE OF INSPECTION:</b> <input style="width: 60px;" type="text" value="4/7/2011"/>
<b>FEATURE UNDER:</b> <input style="width: 100px;" type="text" value="QUAMPHEGAN BRK"/>	<b>POSTING STATUS:</b> <input style="width: 80px;" type="text" value="1 Open"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input style="width: 40px;" type="text" value="99"/>
<b>ROAD INV NO:</b> <input style="width: 60px;" type="text" value="0003101593"/>	<b>POSTING TYPE:</b> <input style="width: 100px;" type="text" value="0 None needed"/>	
<b>ROUTE NO:</b> <input style="width: 60px;" type="text" value="00000"/>		
<b>ROAD WIDTH:</b> <input style="width: 40px;" type="text" value="0"/> <b>FEET</b>	<b>FEDERAL BRIDGE INDICATOR:</b> <input style="width: 30px;" type="text" value="N"/>	
<b>CLASS:</b> <input style="width: 100px;" type="text" value="MINOR SPAN ON TOWN WAY"/>		

## Structures in the Municipality of South Berwick

### CONDITION RATINGS

<b>TOWN1:</b> <input type="text" value="South Berwick"/>	<b>TOWN2:</b> <input type="text" value="No town 2"/>	<b>SUBSTRUCTURE CONDITION:</b> <input type="text" value="1"/> <input type="text" value="Imminent Failure"/>
<b>BRIDGE NO.:</b> <input type="text" value="3312"/>	<b>BRIDGE REGION:</b> <input type="text" value="Southern"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input type="text" value="5"/> <input type="text" value="Fair"/>
<b>LOCATION:</b> <input type="text" value="0.7 MI S JCT 236"/>	<b>YEAR BUILT:</b> <input type="text" value="1955"/>	<b>DECK CONDITION:</b> <input type="text" value="5"/> <input type="text" value="Fair"/>
<b>BRDGNAME:</b> <input type="text" value="VARNEYS"/>	<b>SPAN MATERIAL:</b> <input type="text" value="1 Steel"/>	<b>CHANNEL CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
<b>OWNER:</b> <input type="text" value="1 State DOT"/>	<b>SPAN TYPE:</b> <input type="text" value="1 Girder"/>	<b>CULVERT CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>MAINTAINER:</b> <input type="text" value="1 State DOT"/>	<b>NUMBER OF MAIN SPANS:</b> <input type="text" value="6"/>	<b>APPROACH CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>FEATURE ON:</b> <input type="text" value="VINE STREET"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input type="text" value="240"/>	<b>DATE OF INSPECTION:</b> <input type="text" value="5/21/2012"/>
<b>FEATURE UNDER:</b> <input type="text" value="GREAT WORKS RIVER"/>	<b>POSTING STATUS:</b> <input type="text" value="2 Closed"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input type="text" value="22.8"/>
<b>ROAD INV NO:</b> <input type="text" value="0003100629"/>	<b>POSTING TYPE:</b> <input type="text" value="0 None needed"/>	
<b>ROUTE NO:</b> <input type="text" value="00000"/>		
<b>ROAD WIDTH:</b> <input type="text" value="20"/> FEET	<b>FEDERAL BRIDGE INDICATOR:</b> <input type="text" value="Y"/>	
<b>CLASS:</b> <input type="text" value="BRIDGE ON TOWN WAY OR STATE AID ROAD"/>		

## Structures in the Municipality of South Berwick

### CONDITION RATINGS

<b>TOWN1:</b> <input type="text" value="South Berwick"/>	<b>TOWN2:</b> <input type="text" value="No town 2"/>	<b>SUBSTRUCTURE CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>BRIDGE NO.:</b> <input type="text" value="5343"/>	<b>BRIDGE REGION:</b> <input type="text" value="Southern"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input type="text" value="5"/> <input type="text" value="Fair"/>
<b>LOCATION:</b> <input type="text" value=".1 MI W JCT 236"/>	<b>YEAR BUILT:</b> <input type="text" value="1961"/>	<b>DECK CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
<b>BRDGNAME:</b> <input type="text" value="GREAT WORKS"/>	<b>SPAN MATERIAL:</b> <input type="text" value="1 Steel"/>	<b>CHANNEL CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>OWNER:</b> <input type="text" value="1 State DOT"/>	<b>SPAN TYPE:</b> <input type="text" value="1 Girder"/>	<b>CULVERT CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>MAINTAINER:</b> <input type="text" value="1 State DOT"/>	<b>NUMBER OF MAIN SPANS:</b> <input type="text" value="2"/>	<b>APPROACH CONDITION:</b> <input type="text" value="5"/> <input type="text" value="Fair"/>
<b>FEATURE ON:</b> <input type="text" value="BRATTLE ST"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input type="text" value="143"/>	<b>DATE OF INSPECTION:</b> <input type="text" value="5/29/2012"/>
<b>FEATURE UNDER:</b> <input type="text" value="GREAT WORKS RIVER"/>	<b>POSTING STATUS:</b> <input type="text" value="1 Open"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input type="text" value="62.5"/>
<b>ROAD INV NO:</b> <input type="text" value="0003101593"/>	<b>POSTING TYPE:</b> <input type="text" value="0 None needed"/>	
<b>ROUTE NO:</b> <input type="text" value="00000"/>		
<b>ROAD WIDTH:</b> <input type="text" value="26"/> <b>FEET</b>	<b>FEDERAL BRIDGE INDICATOR:</b> <input type="text" value="Y"/>	
<b>CLASS:</b> <input type="text" value="BRIDGE ON TOWN WAY OR STATE AID ROAD"/>		

## Structures in the Municipality of South Berwick

### CONDITION RATINGS

<b>TOWN1:</b> <input style="width: 150px;" type="text" value="South Berwick"/>	<b>TOWN2:</b> <input style="width: 100px;" type="text" value="No town 2"/>	<b>SUBSTRUCTURE CONDITION:</b> <input style="width: 20px;" type="text" value="9"/> <input style="width: 80px;" type="text" value="Excellent"/>
<b>BRIDGE NO.:</b> <input style="width: 50px;" type="text" value="5610"/>	<b>BRIDGE REGION:</b> <input style="width: 80px;" type="text" value="Southern"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input style="width: 20px;" type="text" value="9"/> <input style="width: 80px;" type="text" value="Excellent"/>
<b>LOCATION:</b> <input style="width: 130px;" type="text" value="2.5 MI NO TOWNLINE"/>	<b>YEAR BUILT:</b> <input style="width: 50px;" type="text" value="2010"/>	<b>DECK CONDITION:</b> <input style="width: 20px;" type="text" value="9"/> <input style="width: 80px;" type="text" value="Excellent"/>
<b>BRDGNAME:</b> <b>GREAT WORKS RIVER</b>	<b>SPAN MATERIAL:</b> <input style="width: 100px;" type="text" value="1 Steel"/>	<b>CHANNEL CONDITION:</b> <input style="width: 20px;" type="text" value="8"/> <input style="width: 80px;" type="text" value="Very Good"/>
<b>OWNER:</b> <input style="width: 80px;" type="text" value="1 State DOT"/>	<b>SPAN TYPE:</b> <input style="width: 100px;" type="text" value="1 Girder"/>	<b>CULVERT CONDITION:</b> <input style="width: 20px;" type="text" value="N"/> <input style="width: 80px;" type="text" value="Not Applicable"/>
<b>MAINTAINER:</b> <input style="width: 80px;" type="text" value="1 State DOT"/>	<b>NUMBER OF MAIN SPANS:</b> <input style="width: 40px;" type="text" value="1"/>	<b>APPROACH CONDITION:</b> <input style="width: 20px;" type="text" value="7"/> <input style="width: 80px;" type="text" value="Good"/>
<b>FEATURE ON:</b> <input style="width: 100px;" type="text" value="236"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input style="width: 40px;" type="text" value="100"/>	<b>DATE OF INSPECTION:</b> <input style="width: 80px;" type="text" value="5/29/2012"/>
<b>FEATURE UNDER:</b> <input style="width: 100px;" type="text" value="GREAT WORKS RIVER"/>	<b>POSTING STATUS:</b> <input style="width: 80px;" type="text" value="1 Open"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input style="width: 50px;" type="text" value="97.8"/>
<b>ROAD INV NO:</b> <input style="width: 60px;" type="text" value="000000236X"/>	<b>POSTING TYPE:</b> <input style="width: 100px;" type="text" value="0 None needed"/>	
<b>ROUTE NO:</b> <input style="width: 60px;" type="text" value="00236"/>		
<b>ROAD WIDTH:</b> <input style="width: 40px;" type="text" value="37"/> <b>FEET</b>	<b>FEDERAL BRIDGE INDICATOR:</b> <input style="width: 30px;" type="text" value="Y"/>	
<b>CLASS:</b> <input style="width: 100px;" type="text" value="BRIDGE ON STATE HIGHWAY"/>		

## Structures in the Municipality of South Berwick

### CONDITION RATINGS

<b>TOWN1:</b> <input type="text" value="South Berwick"/>	<b>TOWN2:</b> <input type="text" value="No town 2"/>	<b>SUBSTRUCTURE CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
<b>BRIDGE NO.:</b> <input type="text" value="5700"/>	<b>BRIDGE REGION:</b> <input type="text" value="Southern"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>LOCATION:</b> <input type="text" value="TOWNLINE"/>	<b>YEAR BUILT:</b> <input type="text" value="1959"/>	<b>DECK CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
<b>BRDGNAME:</b> <input type="text" value="SALMON FALLS"/>	<b>SPAN MATERIAL:</b> <input type="text" value="1 Steel"/>	<b>CHANNEL CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>OWNER:</b> <input type="text" value="1 State DOT"/>	<b>SPAN TYPE:</b> <input type="text" value="1 Girder"/>	<b>CULVERT CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>MAINTAINER:</b> <input type="text" value="1 State DOT"/>	<b>NUMBER OF MAIN SPANS:</b> <input type="text" value="2"/>	<b>APPROACH CONDITION:</b> <input type="text" value="8"/> <input type="text" value="Very Good"/>
<b>FEATURE ON:</b> <input type="text" value="SA 18"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input type="text" value="150"/>	<b>DATE OF INSPECTION:</b> <input type="text" value="10/5/2011"/>
<b>FEATURE UNDER:</b> <input type="text" value="SALMON FALLS RIVER"/>	<b>POSTING STATUS:</b> <input type="text" value="1 Open"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input type="text" value="79.2"/>
<b>ROAD INV NO:</b> <input type="text" value="00031S7181"/>	<b>POSTING TYPE:</b> <input type="text" value="0 None needed"/>	
<b>ROUTE NO:</b> <input type="text" value="00000"/>		
<b>ROAD WIDTH:</b> <input type="text" value="26"/> <b>FEET</b>	<b>FEDERAL BRIDGE INDICATOR:</b> <input type="text" value="Y"/>	
<b>CLASS:</b> <input type="text" value="BRIDGE ON TOWN WAY OR STATE AID ROAD"/>		



## Structures in the Municipality of South Berwick

### CONDITION RATINGS

<b>TOWN1:</b> <input style="width: 150px;" type="text" value="South Berwick"/>	<b>TOWN2:</b> <input style="width: 100px;" type="text" value="No town 2"/>	<b>SUBSTRUCTURE CONDITION:</b> <input style="width: 30px;" type="text" value="6"/> <input style="width: 100px;" type="text" value="Satisfactory"/>
<b>BRIDGE NO.:</b> <input style="width: 60px;" type="text" value="5944"/>	<b>BRIDGE REGION:</b> <input style="width: 80px;" type="text" value="Southern"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input style="width: 30px;" type="text" value="7"/> <input style="width: 80px;" type="text" value="Good"/>
<b>LOCATION:</b> <input style="width: 130px;" type="text" value="0.2 MI E AGAMENTICUS RD"/>	<b>YEAR BUILT:</b> <input style="width: 50px;" type="text" value="1891"/>	<b>DECK CONDITION:</b> <input style="width: 30px;" type="text" value="6"/> <input style="width: 80px;" type="text" value="Satisfactory"/>
<b>BRDGNAME:</b> <input style="width: 100px;" type="text" value="JUNCTION"/>	<b>SPAN MATERIAL:</b> <input style="width: 100px;" type="text" value="1 Steel"/>	<b>CHANNEL CONDITION:</b> <input style="width: 30px;" type="text" value="6"/> <input style="width: 80px;" type="text" value="Satisfactory"/>
<b>OWNER:</b> <input style="width: 90px;" type="text" value="1 State DOT"/>	<b>SPAN TYPE:</b> <input style="width: 100px;" type="text" value="1 Girder"/>	<b>CULVERT CONDITION:</b> <input style="width: 30px;" type="text" value="N"/> <input style="width: 80px;" type="text" value="Not Applicable"/>
<b>MAINTAINER:</b> <input style="width: 90px;" type="text" value="1 State DOT"/>	<b>NUMBER OF MAIN SPANS:</b> <input style="width: 40px;" type="text" value="1"/>	<b>APPROACH CONDITION:</b> <input style="width: 30px;" type="text" value="5"/> <input style="width: 60px;" type="text" value="Fair"/>
<b>FEATURE ON:</b> <input style="width: 110px;" type="text" value="EMERYS BRIDGE ROAD"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input style="width: 40px;" type="text" value="71"/>	<b>DATE OF INSPECTION:</b> <input style="width: 60px;" type="text" value="6/27/2012"/>
<b>FEATURE UNDER:</b> <input style="width: 110px;" type="text" value="GREAT WORKS RIVER"/>	<b>POSTING STATUS:</b> <input style="width: 80px;" type="text" value="1 Open"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input style="width: 50px;" type="text" value="73.2"/>
<b>ROAD INV NO:</b> <input style="width: 60px;" type="text" value="0003100646"/>	<b>POSTING TYPE:</b> <input style="width: 90px;" type="text" value="0 None needed"/>	
<b>ROUTE NO:</b> <input style="width: 60px;" type="text" value="00000"/>		
<b>ROAD WIDTH:</b> <input style="width: 50px;" type="text" value="26"/> <b>FEET</b>	<b>FEDERAL BRIDGE INDICATOR:</b> <input style="width: 30px;" type="text" value="Y"/>	
<b>CLASS:</b> <input style="width: 100px;" type="text" value="BRIDGE ON TOWN WAY OR STATE AID ROAD"/>		

## Structures in the Municipality of South Berwick

### CONDITION RATINGS

<b>TOWN1:</b> <input type="text" value="South Berwick"/>	<b>TOWN2:</b> <input type="text" value="No town 2"/>	<b>SUBSTRUCTURE CONDITION:</b> <input type="text" value="5"/> <input type="text" value="Fair"/>
<b>BRIDGE NO.:</b> <input type="text" value="3017"/>	<b>BRIDGE REGION:</b> <input type="text" value="Southern"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>LOCATION:</b> <input type="text" value="0.8 MI NW OF ELIOT TL"/>	<b>YEAR BUILT:</b> <input type="text" value="1969"/>	<b>DECK CONDITION:</b> <input type="text" value="5"/> <input type="text" value="Fair"/>
<b>BRDGNAME:</b> TOLL	<b>SPAN MATERIAL:</b> <input type="text" value="1 Steel"/>	<b>CHANNEL CONDITION:</b> <input type="text" value="5"/> <input type="text" value="Fair"/>
<b>OWNER:</b> <input type="text" value="1 State DOT"/>	<b>SPAN TYPE:</b> <input type="text" value="1 Girder"/>	<b>CULVERT CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>MAINTAINER:</b> <input type="text" value="1 State DOT"/>	<b>NUMBER OF MAIN SPANS:</b> <input type="text" value="4"/>	<b>APPROACH CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>FEATURE ON:</b> <input type="text" value="ROUTE 101"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input type="text" value="492"/>	<b>DATE OF INSPECTION:</b> <input type="text" value="1/30/2012"/>
<b>FEATURE UNDER:</b> <input type="text" value="SALMON FALLS RIVER"/>	<b>POSTING STATUS:</b> <input type="text" value="1 Open"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input type="text" value="68.3"/>
<b>ROAD INV NO:</b> <input type="text" value="000000101X"/>	<b>POSTING TYPE:</b> <input type="text" value="0 None needed"/>	
<b>ROUTE NO:</b> <input type="text" value="00101"/>		
<b>ROAD WIDTH:</b> <input type="text" value="29"/> FEET	<b>FEDERAL BRIDGE INDICATOR:</b> <input type="text" value="Y"/>	
<b>CLASS:</b> <input type="text" value="BRIDGE ON TOWN WAY OR STATE AID ROAD"/>		