

Maine State Library

Digital Maine

Transportation Documents

Transportation

2-21-2008

Structures in the Municipality of Starks, 2008

Maine Department of Transportation

Follow this and additional works at: https://digitalmaine.com/mdot_docs

Structures in the Municipality of Starks

CONDITION RATINGS

TOWN1: <input style="width: 150px;" type="text" value="Starks"/>	TOWN2: <input style="width: 100px;" type="text" value="No town 2"/>	SUBSTRUCTURE CONDITION: <input style="width: 30px;" type="text" value="6"/> <input style="width: 100px;" type="text" value="Satisfactory"/>
BRIDGE NO.: <input style="width: 60px;" type="text" value="5842"/>	BRIDGE REGION: <input style="width: 80px;" type="text" value="Western"/>	SUPERSTRUCTURE CONDITION: <input style="width: 30px;" type="text" value="7"/> <input style="width: 80px;" type="text" value="Good"/>
LOCATION: <input style="width: 140px;" type="text" value="1.5 MI E JCT 134"/>	YEAR BUILT: <input style="width: 50px;" type="text" value="1962"/>	DECK CONDITION: <input style="width: 30px;" type="text" value="7"/> <input style="width: 80px;" type="text" value="Good"/>
BRDGNAME: <input style="width: 100px;" type="text" value="WILLIAMSON"/>	SPAN MATERIAL: <input style="width: 100px;" type="text" value="1 Steel"/>	CHANNEL CONDITION: <input style="width: 30px;" type="text" value="4"/> <input style="width: 80px;" type="text" value="Poor"/>
OWNER: <input style="width: 100px;" type="text" value="4 Municipal"/>	SPAN TYPE: <input style="width: 100px;" type="text" value="1 Girder"/>	CULVERT CONDITION: <input style="width: 30px;" type="text" value="N"/> <input style="width: 100px;" type="text" value="Not Applicable"/>
MAINTAINER: <input style="width: 100px;" type="text" value="4 Municipal"/>	NUMBER OF MAIN SPANS: <input style="width: 50px;" type="text" value="1"/>	APPROACH CONDITION: <input style="width: 30px;" type="text" value="7"/> <input style="width: 80px;" type="text" value="Good"/>
FEATURE ON: <input style="width: 120px;" type="text" value="RIVER RD"/>	STRUCTURE LENGTH IN FEET: <input style="width: 50px;" type="text" value="75"/>	DATE OF INSPECTION: <input style="width: 60px;" type="text" value="7/13/2011"/>
FEATURE UNDER: <input style="width: 120px;" type="text" value="LEMON STR"/>	POSTING STATUS: <input style="width: 80px;" type="text" value="1 Open"/>	FEDERAL SUFFICIENCY RATING: <input style="width: 60px;" type="text" value="90.8"/>
ROAD INV NO: <input style="width: 60px;" type="text" value="0002500650"/>	POSTING TYPE: <input style="width: 100px;" type="text" value="0 None needed"/>	
ROUTE NO: <input style="width: 60px;" type="text" value="00000"/>		
ROAD WIDTH: <input style="width: 60px;" type="text" value="24"/> FEET	FEDERAL BRIDGE INDICATOR: <input style="width: 40px;" type="text" value="Y"/>	
CLASS: <input style="width: 100px; height: 40px;" type="text" value="LOW USE/REDUNDANT BRIDGE"/>		

Structures in the Municipality of Starks

CONDITION RATINGS

TOWN1: <input style="width: 150px;" type="text" value="Starks"/>	TOWN2: <input style="width: 100px;" type="text" value="No town 2"/>	SUBSTRUCTURE CONDITION: <input style="width: 30px;" type="text" value="6"/> <input style="width: 100px;" type="text" value="Satisfactory"/>
BRIDGE NO.: <input style="width: 60px;" type="text" value="3758"/>	BRIDGE REGION: <input style="width: 80px;" type="text" value="Western"/>	SUPERSTRUCTURE CONDITION: <input style="width: 30px;" type="text" value="7"/> <input style="width: 80px;" type="text" value="Good"/>
LOCATION: <input style="width: 140px;" type="text" value="0.6 MI N JCT RTE 134"/>	YEAR BUILT: <input style="width: 50px;" type="text" value="1941"/>	DECK CONDITION: <input style="width: 30px;" type="text" value="5"/> <input style="width: 80px;" type="text" value="Fair"/>
BRDGNAME: <input style="width: 100px;" type="text" value="VILLAGE"/>	SPAN MATERIAL: <input style="width: 100px;" type="text" value="1 Steel"/>	CHANNEL CONDITION: <input style="width: 30px;" type="text" value="6"/> <input style="width: 80px;" type="text" value="Satisfactory"/>
OWNER: <input style="width: 90px;" type="text" value="1 State DOT"/>	SPAN TYPE: <input style="width: 100px;" type="text" value="1 Girder"/>	CULVERT CONDITION: <input style="width: 30px;" type="text" value="N"/> <input style="width: 80px;" type="text" value="Not Applicable"/>
MAINTAINER: <input style="width: 100px;" type="text" value="1 State DOT"/>	NUMBER OF MAIN SPANS: <input style="width: 50px;" type="text" value="1"/>	APPROACH CONDITION: <input style="width: 30px;" type="text" value="5"/> <input style="width: 80px;" type="text" value="Fair"/>
FEATURE ON: <input style="width: 110px;" type="text" value="ROUTE 43"/>	STRUCTURE LENGTH IN FEET: <input style="width: 50px;" type="text" value="77"/>	DATE OF INSPECTION: <input style="width: 100px;" type="text" value="10/25/2012"/>
FEATURE UNDER: <input style="width: 110px;" type="text" value="LEMON STREAM"/>	POSTING STATUS: <input style="width: 80px;" type="text" value="1 Open"/>	FEDERAL SUFFICIENCY RATING: <input style="width: 50px;" type="text" value="71.8"/>
ROAD INV NO: <input style="width: 60px;" type="text" value="000000043X"/>	POSTING TYPE: <input style="width: 90px;" type="text" value="0 None needed"/>	
ROUTE NO: <input style="width: 60px;" type="text" value="00043"/>		
ROAD WIDTH: <input style="width: 60px;" type="text" value="24"/> FEET	FEDERAL BRIDGE INDICATOR: <input style="width: 30px;" type="text" value="Y"/>	
CLASS: <input style="width: 100px;" type="text" value="BRIDGE ON TOWN WAY OR STATE AID ROAD"/>		

Structures in the Municipality of Starks

CONDITION RATINGS

TOWN1: <input style="width: 150px;" type="text" value="Starks"/>	TOWN2: <input style="width: 100px;" type="text" value="No town 2"/>	SUBSTRUCTURE CONDITION: <input style="width: 20px;" type="text" value="N"/> <input style="width: 80px;" type="text" value="Not Applicable"/>
BRIDGE NO.: <input style="width: 50px;" type="text" value="3688"/>	BRIDGE REGION: <input style="width: 80px;" type="text" value="Western"/>	SUPERSTRUCTURE CONDITION: <input style="width: 20px;" type="text" value="N"/> <input style="width: 80px;" type="text" value="Not Applicable"/>
LOCATION: <input style="width: 130px;" type="text" value="1.3 MI S TOWNLIN"/>	YEAR BUILT: <input style="width: 50px;" type="text" value="1964"/>	DECK CONDITION: <input style="width: 20px;" type="text" value="N"/> <input style="width: 80px;" type="text" value="Not Applicable"/>
BRDGNAME: <input style="width: 100px;" type="text" value="HILTON BROOK"/>	SPAN MATERIAL: <input style="width: 100px;" type="text" value="2 Concrete"/>	CHANNEL CONDITION: <input style="width: 20px;" type="text" value="7"/> <input style="width: 80px;" type="text" value="Good"/>
OWNER: <input style="width: 80px;" type="text" value="1 State DOT"/>	SPAN TYPE: <input style="width: 100px;" type="text" value="7 Rigid Frame"/>	CULVERT CONDITION: <input style="width: 20px;" type="text" value="7"/> <input style="width: 80px;" type="text" value="Good"/>
MAINTAINER: <input style="width: 100px;" type="text" value="1 State DOT"/>	NUMBER OF MAIN SPANS: <input style="width: 40px;" type="text" value="1"/>	APPROACH CONDITION: <input style="width: 20px;" type="text" value="4"/> <input style="width: 80px;" type="text" value="Poor"/>
FEATURE ON: <input style="width: 100px;" type="text" value="ROUTE 43"/>	STRUCTURE LENGTH IN FEET: <input style="width: 50px;" type="text" value="23"/>	DATE OF INSPECTION: <input style="width: 100px;" type="text" value="7/10/2012"/>
FEATURE UNDER: <input style="width: 100px;" type="text" value="HILTON BROOK"/>	POSTING STATUS: <input style="width: 80px;" type="text" value="1 Open"/>	FEDERAL SUFFICIENCY RATING: <input style="width: 50px;" type="text" value="99"/>
ROAD INV NO: <input style="width: 60px;" type="text" value="000000043X"/>	POSTING TYPE: <input style="width: 100px;" type="text" value="0 None needed"/>	
ROUTE NO: <input style="width: 60px;" type="text" value="00043"/>		
ROAD WIDTH: <input style="width: 50px;" type="text" value="0"/> FEET	FEDERAL BRIDGE INDICATOR: <input style="width: 30px;" type="text" value="Y"/>	
CLASS: <input style="width: 100px;" type="text" value="BRIDGE ON TOWN WAY OR STATE AID ROAD"/>		

Structures in the Municipality of Starks

CONDITION RATINGS

TOWN1: <input style="width: 150px;" type="text" value="Starks"/>	TOWN2: <input style="width: 100px;" type="text" value="No town 2"/>	SUBSTRUCTURE CONDITION: <input style="width: 20px;" type="text" value="7"/> <input style="width: 60px;" type="text" value="Good"/>
BRIDGE NO.: <input style="width: 50px;" type="text" value="3571"/>	BRIDGE REGION: <input style="width: 80px;" type="text" value="Western"/>	SUPERSTRUCTURE CONDITION: <input style="width: 20px;" type="text" value="6"/> <input style="width: 60px;" type="text" value="Satisfactory"/>
LOCATION: <input style="width: 130px;" type="text" value=".5 MI E TOWNLINE"/>	YEAR BUILT: <input style="width: 50px;" type="text" value="1938"/>	DECK CONDITION: <input style="width: 20px;" type="text" value="6"/> <input style="width: 60px;" type="text" value="Satisfactory"/>
BRDGNAME: <input style="width: 100px;" type="text" value="CURTIS"/>	SPAN MATERIAL: <input style="width: 100px;" type="text" value="2 Concrete"/>	CHANNEL CONDITION: <input style="width: 20px;" type="text" value="5"/> <input style="width: 60px;" type="text" value="Fair"/>
OWNER: <input style="width: 80px;" type="text" value="1 State DOT"/>	SPAN TYPE: <input style="width: 100px;" type="text" value="3 Slab"/>	CULVERT CONDITION: <input style="width: 20px;" type="text" value="N"/> <input style="width: 60px;" type="text" value="Not Applicable"/>
MAINTAINER: <input style="width: 100px;" type="text" value="1 State DOT"/>	NUMBER OF MAIN SPANS: <input style="width: 40px;" type="text" value="1"/>	APPROACH CONDITION: <input style="width: 20px;" type="text" value="6"/> <input style="width: 60px;" type="text" value="Satisfactory"/>
FEATURE ON: <input style="width: 100px;" type="text" value="#43"/>	STRUCTURE LENGTH IN FEET: <input style="width: 40px;" type="text" value="21"/>	DATE OF INSPECTION: <input style="width: 50px;" type="text" value="1/11/2013"/>
FEATURE UNDER: <input style="width: 100px;" type="text" value="CURTIS BRK"/>	POSTING STATUS: <input style="width: 80px;" type="text" value="1 Open"/>	FEDERAL SUFFICIENCY RATING: <input style="width: 50px;" type="text" value="89.3"/>
ROAD INV NO: <input style="width: 60px;" type="text" value="000000043X"/>	POSTING TYPE: <input style="width: 90px;" type="text" value="0 None needed"/>	
ROUTE NO: <input style="width: 60px;" type="text" value="00043"/>		
ROAD WIDTH: <input style="width: 40px;" type="text" value="27"/> FEET	FEDERAL BRIDGE INDICATOR: <input style="width: 30px;" type="text" value="N"/>	
CLASS: <input style="width: 100px;" type="text" value="MINOR SPAN ON STATE AID ROAD"/>		

Structures in the Municipality of Starks

CONDITION RATINGS

TOWN1: <input style="width: 150px;" type="text" value="Starks"/>	TOWN2: <input style="width: 100px;" type="text" value="No town 2"/>	SUBSTRUCTURE CONDITION: <input style="width: 30px;" type="text" value="7"/> <input style="width: 60px;" type="text" value="Good"/>
BRIDGE NO.: <input style="width: 50px;" type="text" value="3054"/>	BRIDGE REGION: <input style="width: 80px;" type="text" value="Western"/>	SUPERSTRUCTURE CONDITION: <input style="width: 30px;" type="text" value="6"/> <input style="width: 60px;" type="text" value="Satisfactory"/>
LOCATION: <input style="width: 130px;" type="text" value="1.3 MI NO TOWNLINE"/>	YEAR BUILT: <input style="width: 50px;" type="text" value="1934"/>	DECK CONDITION: <input style="width: 30px;" type="text" value="6"/> <input style="width: 60px;" type="text" value="Satisfactory"/>
BRDGNAME: <input style="width: 100px;" type="text" value="JOSHUA BROOK"/>	SPAN MATERIAL: <input style="width: 100px;" type="text" value="2 Concrete"/>	CHANNEL CONDITION: <input style="width: 30px;" type="text" value="5"/> <input style="width: 60px;" type="text" value="Fair"/>
OWNER: <input style="width: 80px;" type="text" value="1 State DOT"/>	SPAN TYPE: <input style="width: 100px;" type="text" value="3 Slab"/>	CULVERT CONDITION: <input style="width: 30px;" type="text" value="N"/> <input style="width: 60px;" type="text" value="Not Applicable"/>
MAINTAINER: <input style="width: 100px;" type="text" value="1 State DOT"/>	NUMBER OF MAIN SPANS: <input style="width: 40px;" type="text" value="1"/>	APPROACH CONDITION: <input style="width: 30px;" type="text" value="6"/> <input style="width: 60px;" type="text" value="Satisfactory"/>
FEATURE ON: <input style="width: 100px;" type="text" value="#134"/>	STRUCTURE LENGTH IN FEET: <input style="width: 40px;" type="text" value="21"/>	DATE OF INSPECTION: <input style="width: 50px;" type="text" value="1/14/2013"/>
FEATURE UNDER: <input style="width: 100px;" type="text" value="JOSHUA BRK"/>	POSTING STATUS: <input style="width: 80px;" type="text" value="1 Open"/>	FEDERAL SUFFICIENCY RATING: <input style="width: 50px;" type="text" value="84.3"/>
ROAD INV NO: <input style="width: 60px;" type="text" value="000000134X"/>	POSTING TYPE: <input style="width: 90px;" type="text" value="0 None needed"/>	
ROUTE NO: <input style="width: 60px;" type="text" value="00134"/>		
ROAD WIDTH: <input style="width: 50px;" type="text" value="22"/> FEET	FEDERAL BRIDGE INDICATOR: <input style="width: 30px;" type="text" value="N"/>	
CLASS: <input style="width: 100px;" type="text" value="MINOR SPAN ON STATE AID ROAD"/>		

Structures in the Municipality of Starks

CONDITION RATINGS

TOWN1: <input style="width: 150px;" type="text" value="Starks"/>	TOWN2: <input style="width: 100px;" type="text" value="No town 2"/>	SUBSTRUCTURE CONDITION: <input style="width: 20px;" type="text" value="5"/> <input style="width: 80px;" type="text" value="Fair"/>
BRIDGE NO.: <input style="width: 60px;" type="text" value="1054"/>	BRIDGE REGION: <input style="width: 80px;" type="text" value="Western"/>	SUPERSTRUCTURE CONDITION: <input style="width: 20px;" type="text" value="5"/> <input style="width: 80px;" type="text" value="Fair"/>
LOCATION: <input style="width: 140px;" type="text" value="1.4 MI S RT 43"/>	YEAR BUILT: <input style="width: 50px;" type="text" value="1920"/>	DECK CONDITION: <input style="width: 20px;" type="text" value="5"/> <input style="width: 80px;" type="text" value="Fair"/>
BRDGNAME: LEEMAN	SPAN MATERIAL: <input style="width: 100px;" type="text" value="1 Steel"/>	CHANNEL CONDITION: <input style="width: 20px;" type="text" value="6"/> <input style="width: 80px;" type="text" value="Satisfactory"/>
OWNER: <input style="width: 100px;" type="text" value="4 Municipal"/>	SPAN TYPE: <input style="width: 100px;" type="text" value="1 Girder"/>	CULVERT CONDITION: <input style="width: 20px;" type="text" value="N"/> <input style="width: 80px;" type="text" value="Not Applicable"/>
MAINTAINER: <input style="width: 100px;" type="text" value="4 Municipal"/>	NUMBER OF MAIN SPANS: <input style="width: 40px;" type="text" value="1"/>	APPROACH CONDITION: <input style="width: 20px;" type="text" value="5"/> <input style="width: 80px;" type="text" value="Fair"/>
FEATURE ON: <input style="width: 120px;" type="text" value="BRANN MILL RD"/>	STRUCTURE LENGTH IN FEET: <input style="width: 40px;" type="text" value="22"/>	DATE OF INSPECTION: <input style="width: 60px;" type="text" value="7/13/2011"/>
FEATURE UNDER: <input style="width: 120px;" type="text" value="CURTIS BRK"/>	POSTING STATUS: <input style="width: 80px;" type="text" value="3 Posted"/>	FEDERAL SUFFICIENCY RATING: <input style="width: 50px;" type="text" value="32.5"/>
ROAD INV NO: <input style="width: 60px;" type="text" value="0002500652"/>	POSTING TYPE: <input style="width: 100px;" type="text" value="1 Weight Limit"/>	
ROUTE NO: <input style="width: 60px;" type="text" value="00000"/>		
ROAD WIDTH: <input style="width: 40px;" type="text" value="17"/> FEET	FEDERAL BRIDGE INDICATOR: <input style="width: 30px;" type="text" value="N"/>	
CLASS: <input style="width: 100px;" type="text" value="MINOR SPAN ON TOWN WAY"/>		

Structures in the Municipality of Starks

CONDITION RATINGS

TOWN1: <input style="width: 150px;" type="text" value="Starks"/>	TOWN2: <input style="width: 100px;" type="text" value="No town 2"/>	SUBSTRUCTURE CONDITION: <input style="width: 30px;" type="text" value="N"/> <input style="width: 100px;" type="text" value="Not Applicable"/>
BRIDGE NO.: <input style="width: 50px;" type="text" value="1053"/>	BRIDGE REGION: <input style="width: 80px;" type="text" value="Western"/>	SUPERSTRUCTURE CONDITION: <input style="width: 30px;" type="text" value="N"/> <input style="width: 100px;" type="text" value="Not Applicable"/>
LOCATION: <input style="width: 130px;" type="text" value=".5 MI WEST RT 134"/>	YEAR BUILT: <input style="width: 50px;" type="text" value="1988"/>	DECK CONDITION: <input style="width: 30px;" type="text" value="N"/> <input style="width: 100px;" type="text" value="Not Applicable"/>
BRDGNAME: <input style="width: 100px;" type="text" value="BRANN"/>	SPAN MATERIAL: <input style="width: 100px;" type="text" value="1 Steel"/>	CHANNEL CONDITION: <input style="width: 30px;" type="text" value="7"/> <input style="width: 100px;" type="text" value="Good"/>
OWNER: <input style="width: 80px;" type="text" value="4 Municipal"/>	SPAN TYPE: <input style="width: 100px;" type="text" value="4 Culvert"/>	CULVERT CONDITION: <input style="width: 30px;" type="text" value="6"/> <input style="width: 100px;" type="text" value="Satisfactory"/>
MAINTAINER: <input style="width: 100px;" type="text" value="4 Municipal"/>	NUMBER OF MAIN SPANS: <input style="width: 40px;" type="text" value="1"/>	APPROACH CONDITION: <input style="width: 30px;" type="text" value="5"/> <input style="width: 100px;" type="text" value="Fair"/>
FEATURE ON: <input style="width: 100px;" type="text" value="BRANN MILLS ROAD"/>	STRUCTURE LENGTH IN FEET: <input style="width: 50px;" type="text" value="16"/>	DATE OF INSPECTION: <input style="width: 100px;" type="text" value="7/13/2011"/>
FEATURE UNDER: <input style="width: 100px;" type="text" value="JOSHUA BROOK"/>	POSTING STATUS: <input style="width: 80px;" type="text" value="1 Open"/>	FEDERAL SUFFICIENCY RATING: <input style="width: 50px;" type="text" value="100"/>
ROAD INV NO: <input style="width: 60px;" type="text" value="0002500652"/>	POSTING TYPE: <input style="width: 100px;" type="text" value="0 None needed"/>	
ROUTE NO: <input style="width: 60px;" type="text" value="00000"/>		
ROAD WIDTH: <input style="width: 50px;" type="text" value="0"/> FEET	FEDERAL BRIDGE INDICATOR: <input style="width: 30px;" type="text" value="N"/>	
CLASS: <input style="width: 100px;" type="text" value="MINOR SPAN ON TOWN WAY"/>		

Structures in the Municipality of Starks

CONDITION RATINGS

TOWN1: <input type="text" value="Starks"/>	TOWN2: <input type="text" value="No town 2"/>	SUBSTRUCTURE CONDITION: <input type="text" value="3"/> <input type="text" value="Serious"/>
BRIDGE NO.: <input type="text" value="1052"/>	BRIDGE REGION: <input type="text" value="Western"/>	SUPERSTRUCTURE CONDITION: <input type="text" value="4"/> <input type="text" value="Poor"/>
LOCATION: <input type="text" value=".3 MI E RT 148"/>	YEAR BUILT: <input type="text" value="1989"/>	DECK CONDITION: <input type="text" value="4"/> <input type="text" value="Poor"/>
BRDGNAME: <input type="text" value="LEMON STREAM"/>	SPAN MATERIAL: <input type="text" value="1 Steel"/>	CHANNEL CONDITION: <input type="text" value="2"/> <input type="text" value="Critical"/>
OWNER: <input type="text" value="4 Municipal"/>	SPAN TYPE: <input type="text" value="1 Girder"/>	CULVERT CONDITION: <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
MAINTAINER: <input type="text" value="4 Municipal"/>	NUMBER OF MAIN SPANS: <input type="text" value="1"/>	APPROACH CONDITION: <input type="text" value="4"/> <input type="text" value="Poor"/>
FEATURE ON: <input type="text" value="WEST MILLS RD"/>	STRUCTURE LENGTH IN FEET: <input type="text" value="21"/>	DATE OF INSPECTION: <input type="text" value="7/12/2011"/>
FEATURE UNDER: <input type="text" value="LEMON STREAM"/>	POSTING STATUS: <input type="text" value="3 Posted"/>	FEDERAL SUFFICIENCY RATING: <input type="text" value="26.6"/>
ROAD INV NO: <input type="text" value="0002500665"/>	POSTING TYPE: <input type="text" value="1 Weight Limit"/>	
ROUTE NO: <input type="text" value="00000"/>		
ROAD WIDTH: <input type="text" value="15"/> FEET	FEDERAL BRIDGE INDICATOR: <input type="text" value="N"/>	
CLASS: <input type="text" value="MINOR SPAN ON TOWN WAY"/>		

Structures in the Municipality of Starks

CONDITION RATINGS

TOWN1: <input style="width: 150px;" type="text" value="Starks"/>	TOWN2: <input style="width: 100px;" type="text" value="No town 2"/>	SUBSTRUCTURE CONDITION: <input style="width: 30px;" type="text" value="3"/> <input style="width: 80px;" type="text" value="Serious"/>
BRIDGE NO.: <input style="width: 60px;" type="text" value="1051"/>	BRIDGE REGION: <input style="width: 80px;" type="text" value="Western"/>	SUPERSTRUCTURE CONDITION: <input style="width: 30px;" type="text" value="4"/> <input style="width: 80px;" type="text" value="Poor"/>
LOCATION: <input style="width: 140px;" type="text" value="1 MI S RT 148"/>	YEAR BUILT: <input style="width: 50px;" type="text" value="1907"/>	DECK CONDITION: <input style="width: 30px;" type="text" value="5"/> <input style="width: 80px;" type="text" value="Fair"/>
BRDGNAME: <input style="width: 100px;" type="text" value="PELTON BROOK"/>	SPAN MATERIAL: <input style="width: 100px;" type="text" value="1 Steel"/>	CHANNEL CONDITION: <input style="width: 30px;" type="text" value="4"/> <input style="width: 80px;" type="text" value="Poor"/>
OWNER: <input style="width: 100px;" type="text" value="4 Municipal"/>	SPAN TYPE: <input style="width: 100px;" type="text" value="1 Girder"/>	CULVERT CONDITION: <input style="width: 30px;" type="text" value="N"/> <input style="width: 80px;" type="text" value="Not Applicable"/>
MAINTAINER: <input style="width: 100px;" type="text" value="4 Municipal"/>	NUMBER OF MAIN SPANS: <input style="width: 50px;" type="text" value="1"/>	APPROACH CONDITION: <input style="width: 30px;" type="text" value="5"/> <input style="width: 80px;" type="text" value="Fair"/>
FEATURE ON: <input style="width: 120px;" type="text" value="TW (MAYEW RD ?)"/>	STRUCTURE LENGTH IN FEET: <input style="width: 50px;" type="text" value="24"/>	DATE OF INSPECTION: <input style="width: 60px;" type="text" value="7/12/2011"/>
FEATURE UNDER: <input style="width: 120px;" type="text" value="PELTON BROOK"/>	POSTING STATUS: <input style="width: 80px;" type="text" value="3 Posted"/>	FEDERAL SUFFICIENCY RATING: <input style="width: 60px;" type="text" value="26.3"/>
ROAD INV NO: <input style="width: 60px;" type="text" value="0002500642"/>	POSTING TYPE: <input style="width: 100px;" type="text" value="1 Weight Limit"/>	
ROUTE NO: <input style="width: 60px;" type="text" value="00000"/>		
ROAD WIDTH: <input style="width: 60px;" type="text" value="17"/> FEET	FEDERAL BRIDGE INDICATOR: <input style="width: 40px;" type="text" value="N"/>	
CLASS: <input style="width: 100px;" type="text" value="MINOR SPAN ON TOWN WAY"/>		