

Maine State Library

**Digital Maine**

---

Transportation Documents

Transportation

---

2-21-2008

## **Structures in the Municipality of Sullivan, 2008**

Maine Department of Transportation

Follow this and additional works at: [https://digitalmaine.com/mdot\\_docs](https://digitalmaine.com/mdot_docs)

---

## Structures in the Municipality of Hancock

### CONDITION RATINGS

<b>TOWN1:</b> <input type="text" value="Hancock"/>	<b>TOWN2:</b> <input type="text" value="Sullivan"/>	<b>SUBSTRUCTURE CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>BRIDGE NO.:</b> <input type="text" value="2973"/>	<b>BRIDGE REGION:</b> <input type="text" value="Eastern"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>LOCATION:</b> <input type="text" value="4.5 MI E JCT 182 ON 1"/>	<b>YEAR BUILT:</b> <input type="text" value="1999"/>	<b>DECK CONDITION:</b> <input type="text" value="8"/> <input type="text" value="Very Good"/>
<b>BRDGNAME:</b> HANCOCK SULLIVAN	<b>SPAN MATERIAL:</b> <input type="text" value="7 Precast Concrete"/>	<b>CHANNEL CONDITION:</b> <input type="text" value="8"/> <input type="text" value="Very Good"/>
<b>OWNER:</b> <input type="text" value="1 State DOT"/>	<b>SPAN TYPE:</b> <input type="text" value="1 Girder"/>	<b>CULVERT CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>MAINTAINER:</b> <input type="text" value="1 State DOT"/>	<b>NUMBER OF MAIN SPANS:</b> <input type="text" value="8"/>	<b>APPROACH CONDITION:</b> <input type="text" value="8"/> <input type="text" value="Very Good"/>
<b>FEATURE ON:</b> <input type="text" value="US 1"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input type="text" value="1023"/>	<b>DATE OF INSPECTION:</b> <input type="text" value="10/31/2012"/>
<b>FEATURE UNDER:</b> <input type="text" value="TAUNTON RIVER"/>	<b>POSTING STATUS:</b> <input type="text" value="1 Open"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input type="text" value="95.7"/>
<b>ROAD INV NO:</b> <input type="text" value="000000001X"/>	<b>POSTING TYPE:</b> <input type="text" value="0 None needed"/>	
<b>ROUTE NO:</b> <input type="text" value="00001"/>		
<b>ROAD WIDTH:</b> <input type="text" value="34"/> FEET	<b>FEDERAL BRIDGE INDICATOR:</b> <input type="text" value="Y"/>	
<b>CLASS:</b> <input type="text" value="BRIDGE ON STATE HIGHWAY"/>		

## Structures in the Municipality of Sullivan

### CONDITION RATINGS

<b>TOWN1:</b> <input type="text" value="Sullivan"/>	<b>TOWN2:</b> <input type="text" value="No town 2"/>	<b>SUBSTRUCTURE CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>BRIDGE NO.:</b> <input type="text" value="5896"/>	<b>BRIDGE REGION:</b> <input type="text" value="Eastern"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>LOCATION:</b> <input type="text" value="1.5 MI W RT 200"/>	<b>YEAR BUILT:</b> <input type="text" value="1950"/>	<b>DECK CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>BRDGNAME:</b> <input type="text" value="VILLAGE"/>	<b>SPAN MATERIAL:</b> <input type="text" value="2 Concrete"/>	<b>CHANNEL CONDITION:</b> <input type="text" value="6"/> <input type="text" value="Satisfactory"/>
<b>OWNER:</b> <input type="text" value="1 State DOT"/>	<b>SPAN TYPE:</b> <input type="text" value="4 Culvert"/>	<b>CULVERT CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>MAINTAINER:</b> <input type="text" value="1 State DOT"/>	<b>NUMBER OF MAIN SPANS:</b> <input type="text" value="1"/>	<b>APPROACH CONDITION:</b> <input type="text" value="9"/> <input type="text" value="Excellent"/>
<b>FEATURE ON:</b> <input type="text" value="US 1"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input type="text" value="16"/>	<b>DATE OF INSPECTION:</b> <input type="text" value="6/13/2011"/>
<b>FEATURE UNDER:</b> <input type="text" value="HIGGINS STREAM"/>	<b>POSTING STATUS:</b> <input type="text" value="1 Open"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input type="text" value="66.1"/>
<b>ROAD INV NO:</b> <input type="text" value="000000001X"/>	<b>POSTING TYPE:</b> <input type="text" value="0 None needed"/>	
<b>ROUTE NO:</b> <input type="text" value="00001"/>		
<b>ROAD WIDTH:</b> <input type="text" value="0"/> FEET	<b>FEDERAL BRIDGE INDICATOR:</b> <input type="text" value="N"/>	
<b>CLASS:</b> <input type="text" value="MINOR SPAN ON STATE HIGHWAY"/>		

## Structures in the Municipality of Sullivan

### CONDITION RATINGS

<b>TOWN1:</b> Sullivan	<b>TOWN2:</b> No town 2	<b>SUBSTRUCTURE CONDITION:</b> N Not Applicable
<b>BRIDGE NO.:</b> 5668	<b>BRIDGE REGION:</b> Eastern	<b>SUPERSTRUCTURE CONDITION:</b> N Not Applicable
<b>LOCATION:</b> .3 MI W TOWNLIN	<b>YEAR BUILT:</b> 1955	<b>DECK CONDITION:</b> N Not Applicable
<b>BRDGNAME:</b> MORANCY PD OUTLET	<b>SPAN MATERIAL:</b> 1 Steel	<b>CHANNEL CONDITION:</b> 8 Very Good
<b>OWNER:</b> 1 State DOT	<b>SPAN TYPE:</b> 6 Arch	<b>CULVERT CONDITION:</b> 7 Good
<b>MAINTAINER:</b> 1 State DOT	<b>NUMBER OF MAIN SPANS:</b> 1	<b>APPROACH CONDITION:</b> 6 Satisfactory
<b>FEATURE ON:</b> US 1	<b>STRUCTURE LENGTH IN FEET:</b> 14	<b>DATE OF INSPECTION:</b> 6/10/2011
<b>FEATURE UNDER:</b> MORANCY PD OUTLET	<b>POSTING STATUS:</b> 1 Open	<b>FEDERAL SUFFICIENCY RATING:</b> 84.8
<b>ROAD INV NO:</b> 000000001X	<b>POSTING TYPE:</b> 0 None needed	
<b>ROUTE NO:</b> 00001		
<b>ROAD WIDTH:</b> 0 FEET	<b>FEDERAL BRIDGE INDICATOR:</b> N	
<b>CLASS:</b> MINOR SPAN ON STATE HIGHWAY		

## Structures in the Municipality of Sullivan

### CONDITION RATINGS

<b>TOWN1:</b> <input type="text" value="Sullivan"/>	<b>TOWN2:</b> <input type="text" value="No town 2"/>	<b>SUBSTRUCTURE CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>BRIDGE NO.:</b> <input type="text" value="5184"/>	<b>BRIDGE REGION:</b> <input type="text" value="Eastern"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>LOCATION:</b> <input type="text" value="4 MI N JCT US 1"/>	<b>YEAR BUILT:</b> <input type="text" value="2012"/>	<b>DECK CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>BRDGNAME:</b> <input type="text" value="BEAN"/>	<b>SPAN MATERIAL:</b> <input type="text" value="5 Aluminum"/>	<b>CHANNEL CONDITION:</b> <input type="text" value="9"/> <input type="text" value="Excellent"/>
<b>OWNER:</b> <input type="text" value="4 Municipal"/>	<b>SPAN TYPE:</b> <input type="text" value="4 Culvert"/>	<b>CULVERT CONDITION:</b> <input type="text" value="9"/> <input type="text" value="Excellent"/>
<b>MAINTAINER:</b> <input type="text" value="4 Municipal"/>	<b>NUMBER OF MAIN SPANS:</b> <input type="text" value="1"/>	<b>APPROACH CONDITION:</b> <input type="text" value="9"/> <input type="text" value="Excellent"/>
<b>FEATURE ON:</b> <input type="text" value="THORNE RD"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input type="text" value="0"/>	<b>DATE OF INSPECTION:</b> <input type="text" value="10/19/2012"/>
<b>FEATURE UNDER:</b> <input type="text" value="FLANDERS STREAM"/>	<b>POSTING STATUS:</b> <input type="text" value="1 Open"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input type="text" value="33.6"/>
<b>ROAD INV NO:</b> <input type="text" value="0000900511"/>	<b>POSTING TYPE:</b> <input type="text" value="0 None needed"/>	
<b>ROUTE NO:</b> <input type="text" value="00000"/>		
<b>ROAD WIDTH:</b> <input type="text" value="0"/> FEET	<b>FEDERAL BRIDGE INDICATOR:</b> <input type="text" value="N"/>	
<b>CLASS:</b> <input type="text" value="MINOR SPAN ON TOWN WAY"/>		

## Structures in the Municipality of Sullivan

### CONDITION RATINGS

<b>TOWN1:</b> Sullivan	<b>TOWN2:</b> No town 2	<b>SUBSTRUCTURE CONDITION:</b> N Not Applicable
<b>BRIDGE NO.:</b> 2984	<b>BRIDGE REGION:</b> Eastern	<b>SUPERSTRUCTURE CONDITION:</b> N Not Applicable
<b>LOCATION:</b> .2 MI NE RTE 1	<b>YEAR BUILT:</b> 1935	<b>DECK CONDITION:</b> N Not Applicable
<b>BRDGNAME:</b> SMITH MILL	<b>SPAN MATERIAL:</b> 2 Concrete	<b>CHANNEL CONDITION:</b> 4 Poor
<b>OWNER:</b> 4 Municipal	<b>SPAN TYPE:</b> 3 Slab	<b>CULVERT CONDITION:</b> 6 Satisfactory
<b>MAINTAINER:</b> 4 Municipal	<b>NUMBER OF MAIN SPANS:</b> 1	<b>APPROACH CONDITION:</b> 6 Satisfactory
<b>FEATURE ON:</b> OLD RTE 1(TO ASHVI	<b>STRUCTURE LENGTH IN FEET:</b> 14	<b>DATE OF INSPECTION:</b> 10/19/2012
<b>FEATURE UNDER:</b> MORANCEY STR.	<b>POSTING STATUS:</b> 1 Open	<b>FEDERAL SUFFICIENCY RATING:</b> 92.8
<b>ROAD INV NO:</b> 0000901819	<b>POSTING TYPE:</b> 0 None needed	
<b>ROUTE NO:</b> 00000		
<b>ROAD WIDTH:</b> 0 FEET	<b>FEDERAL BRIDGE INDICATOR:</b> N	
<b>CLASS:</b> MINOR SPAN ON TOWN WAY		

## Structures in the Municipality of Sullivan

### CONDITION RATINGS

<b>TOWN1:</b> <input style="width: 150px;" type="text" value="Sullivan"/>	<b>TOWN2:</b> <input style="width: 100px;" type="text" value="No town 2"/>	<b>SUBSTRUCTURE CONDITION:</b> <input style="width: 30px;" type="text" value="N"/> <input style="width: 100px;" type="text" value="Not Applicable"/>
<b>BRIDGE NO.:</b> <input style="width: 60px;" type="text" value="2285"/>	<b>BRIDGE REGION:</b> <input style="width: 80px;" type="text" value="Eastern"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input style="width: 30px;" type="text" value="N"/> <input style="width: 100px;" type="text" value="Not Applicable"/>
<b>LOCATION:</b> <input style="width: 130px;" type="text" value="0.2 MI W JCT RTE 183"/>	<b>YEAR BUILT:</b> <input style="width: 50px;" type="text" value="1927"/>	<b>DECK CONDITION:</b> <input style="width: 30px;" type="text" value="N"/> <input style="width: 100px;" type="text" value="Not Applicable"/>
<b>BRDGNAME:</b> <input style="width: 100px;" type="text" value="FLANDERS STREAM"/>	<b>SPAN MATERIAL:</b> <input style="width: 100px;" type="text" value="2 Concrete"/>	<b>CHANNEL CONDITION:</b> <input style="width: 30px;" type="text" value="8"/> <input style="width: 100px;" type="text" value="Very Good"/>
<b>OWNER:</b> <input style="width: 80px;" type="text" value="1 State DOT"/>	<b>SPAN TYPE:</b> <input style="width: 100px;" type="text" value="1 Girder"/>	<b>CULVERT CONDITION:</b> <input style="width: 30px;" type="text" value="7"/> <input style="width: 100px;" type="text" value="Good"/>
<b>MAINTAINER:</b> <input style="width: 100px;" type="text" value="1 State DOT"/>	<b>NUMBER OF MAIN SPANS:</b> <input style="width: 50px;" type="text" value="1"/>	<b>APPROACH CONDITION:</b> <input style="width: 30px;" type="text" value="8"/> <input style="width: 100px;" type="text" value="Very Good"/>
<b>FEATURE ON:</b> <input style="width: 100px;" type="text" value="ROUTE US 1"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input style="width: 50px;" type="text" value="23"/>	<b>DATE OF INSPECTION:</b> <input style="width: 100px;" type="text" value="4/7/2011"/>
<b>FEATURE UNDER:</b> <input style="width: 100px;" type="text" value="FLANDERS STREAM"/>	<b>POSTING STATUS:</b> <input style="width: 80px;" type="text" value="1 Open"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input style="width: 50px;" type="text" value="83.8"/>
<b>ROAD INV NO:</b> <input style="width: 60px;" type="text" value="000000001X"/>	<b>POSTING TYPE:</b> <input style="width: 100px;" type="text" value="0 None needed"/>	
<b>ROUTE NO:</b> <input style="width: 60px;" type="text" value="00001"/>		
<b>ROAD WIDTH:</b> <input style="width: 60px;" type="text" value="0"/> <b>FEET</b>	<b>FEDERAL BRIDGE INDICATOR:</b> <input style="width: 30px;" type="text" value="Y"/>	
<b>CLASS:</b> <input style="width: 100px;" type="text" value="BRIDGE ON STATE HIGHWAY"/>		